	State of New Me	XICO	Form C-103
Office District I	Energy, Minerals and Natu	ral Resources	Revised March 25, 1999 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		ŀ	30-025-29789
1301 W. Grand Avenue, Artesia, NM 88210	OIL CONSERVATION	1	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra	í	STATE 🗹 FEE 🗆
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87	303	6. State Oil & Gas Lease No. B-3011
SUNDRY NOTIC	ES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	LS TO DRILL OR TO DEEPEN OR PLU	JG BACK TO A	New Mexico "Z" State NCT-5
1. Type of Well: Oil Well Gas Well	Other		
2. Name of Operator Chevron USA Inc		8. Well No.	
3. Address of Operator 15 Smith Rd, Midland, TX 79705		9. Pool name or Wildcat Airstrip, Wolfcamp/B. Springs	
4. Well Location		······································	
Unit Letter J: 1850 feet from the South line and 2310 feet from the East line			
Section 14	Township 18-S Ra	inge 34-E	_{NMPM} Lea _{County} 1
	10. Elevation (Show whether D.	R, RKB, RT, GR, etc.,	
-	propriate Box to Indicate Na		•
NOTICE OF INT PERFORM REMEDIAL WORK	ENTION TO: PLUG AND ABANDON 🔽	SUBS REMEDIAL WORK	EQUENT REPORT OF: ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILI	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND	ABANDONMENT C
OTHER:		OTHER:	
~ · · · — · · ·	L		
12. Describe proposed or complet	ed operations. (Clearly state all p SEE RULE 1103. For Multiple C	pertinent details, and Completions: Attach	give pertinent dates, including estimated dat wellbore diagram of proposed completion
12. Describe proposed or complet of starting any proposed work). or recompilation. 1. Notify OCD 24 hrs prior to 2. RIH Tag 5 1/2 CIBP @ + 3. Displace hole w/MLF, 9.4. Spot 25sx plug 7300-710. 5. Spot 25sx plug 4500-430. 6. Spot 25sx plug 3450-325. 7. Spot 25sx plug 1950-175. 8. Spot 50sx plug 450-Surf. 9. Install dry hole marker.	SEE RULE 1103. For Multiple Cooking of MI & RU. - 93:75 spot 25sx plug 93:759 5# brine w/25# gel P/BBL. 10 (DV-Tool). 10 (Queen). 10 (8 5/8 shoe) WOC Tag. 10 (T-Salt) WOC Tag. 11 3/4 shoe, Surf) WOC Tag.	Completions: Attach	WOC Tag. 3A56789707
 Describe proposed or complet of starting any proposed work). or recompilation. Notify OCD 24 hrs prior to 2. RIH Tag 5 1/2 CIBP @ + 3. Displace hole w/MLF, y 9.5 4. Spot 25sx plug 7300-710 5. Spot 25sx plug 4500-430 6. Spot 25sx plug 3450-325 7. Spot 25sx plug 1950-175 8. Spot 50sx plug 450-Surf 	SEE RULE 1103. For Multiple Cooking of MI & RU. - 93:75 spot 25sx plug 93:759 5# brine w/25# gel P/BBL. 10 (DV-Tool). 10 (Queen). 10 (8 5/8 shoe) WOC Tag. 10 (T-Salt) WOC Tag. 11 3/4 shoe, Surf) WOC Tag.	Completions: Attach	WOC Tag. 3A56789707
12. Describe proposed or complet of starting any proposed work). or recompilation. 1. Notify OCD 24 hrs prior to 2. RIH Tag 5 1/2 CIBP @ + 3. Displace hole w/MLF, 9.4. Spot 25sx plug 7300-710. 5. Spot 25sx plug 4500-430. 6. Spot 25sx plug 3450-325. 7. Spot 25sx plug 1950-175. 8. Spot 50sx plug 450-Surf. 9. Install dry hole marker.	SEE RULE 1103. For Multiple Cooking of MI & RU. - 93:75 spot 25sx plug 93:759 5# brine w/25# gel P/BBL. 10 (DV-Tool). 10 (Queen). 10 (8 5/8 shoe) WOC Tag. 10 (T-Salt) WOC Tag. 11 3/4 shoe, Surf) WOC Tag.	Completions: Attach	WOC Tag 3 A 5 6 7 8 9 70 70 8 FP 2008 CONTROL OF THOMAS OF THOMAS OF THE PROPERTY OF THE PROPE
12. Describe proposed or complet of starting any proposed work). or recompilation. 1. Notify OCD 24 hrs prior to 2. RIH Tag 5 1/2 CIBP @ + 3. Displace hole w/MLF, 9.5. 4. Spot 25sx plug 7300-710. 5. Spot 25sx plug 4500-430. 6. Spot 25sx plug 3450-325. 7. Spot 25sx plug 1950-175. 8. Spot 50sx plug 450-Surf. 9. Install dry hole marker.	SEE RULE 1103. For Multiple Cook of MI & RU. - 93.75 spot 25sx plug 93.759 fb brine w/25# gel P/BBL. - 90 (DV-Tool). - 90 (Queen). - 90 (8 5/8 shoe) WOC Tag. - 90 (T-Salt) WOC Tag. - (11 3/4 shoe, Surf) WOC Tag.	Completions: Attach	WOC Tag 3 A 5 6 7 8 9 70 70 8 FP 200 8
12. Describe proposed or complet of starting any proposed work). or recompilation. 1. Notify OCD 24 hrs prior to 2. RIH Tag 5 1/2 CIBP @ + 3. Displace hole w/MLF, 9.9.4. Spot 25sx plug 7300-710. 5. Spot 25sx plug 4500-430. 6. Spot 25sx plug 3450-325. 7. Spot 25sx plug 1950-175. 8. Spot 50sx plug 450-Surf. 9. Install dry hole marker. I hereby certify that the information a SIGNATURE	SEE RULE 1103. For Multiple Cook MI & RU. - 93.7 5 spot 25sx plug 93.7 59 5# brine w/25# gel P/BBL. 10 (DV-Tool). 10 (Queen). 10 (8 5/8 shoe) WOC Tag. 10 (T-Salt) WOC Tag. (11 3/4 shoe, Surf) WOC Tag.	Completions: Attach	WOC Tag 3 A 5 6 7 8 9 70 70 8 FP 200 8
12. Describe proposed or complet of starting any proposed work). or recompilation. 1. Notify OCD 24 hrs prior to 2. RIH Tag 5 1/2 CIBP @ + 3. Displace hole w/MLF, 9.9.4. Spot 25sx plug 7300-710. 5. Spot 25sx plug 4500-430. 6. Spot 25sx plug 3450-325. 7. Spot 25sx plug 1950-175. 8. Spot 50sx plug 450-Surf. 9. Install dry hole marker. I hereby certify that the information a SIGNATURE	SEE RULE 1103. For Multiple Cook MI & RU. - 93.75 spot 25sx plug 93.759 strong w/25# gel P/BBL. - 90 (DV-Tool). - 90 (Queen). - 90 (See Signal of the strong with the stro	Dest of my knowledge HES Specialis	WOC Tag 3 A 5 6 7 8 9 70 70 8 FP 200 8

PLUGGING OPERATIONS FOR THE C-1035 TO BE APPROVED.

OPERATOR CHEVEN USA INC. STATE (NCT-5) LEASENAME NEW MEXICO WELL 18-5 RNG 34-E TWN SECT ŒW L N(S)L FROM 1850 2510 FORMATION @ TD TD: 10, 155 FORMATION @ PBTD Boue Speings PBTD: 9375 SIZE TOC SET @ TOC DETERMINED BY SURFACE 113/4 113/4 400 Ciec. SURF INTMED 1 85/8 @ 400 3400 SURF Ciec TOC SURE INTMED 2 MLF **PROD** د/'5 10.155 ciec SURF SIZE TOP BOT TOC DETERMINED BY LINER 1 LINER 2 MLF CUT & PULL @ TOP - BOTTOM INTMED 1 - 95ao PERFS 9472 INTMED 2 OPENHOLE TOC PROD * REOUIRED PLUGS DISTRICT I MLF PLUG TYPE SACKS DEPTH RUSTLER (ANHYD) PLIG **CMNT** YATES QUEEN EXAMPLES OH 25 SXS 9850 PLUG#1 GRAYBURG PLUG#2 SHOE 50 SXS 8700'-8800' SAN ANDRES MLF CIBP/35' PLUG #3 5300' CIBP 25 SXS 5300 PLUG#3 CAPITAN REEF 4600'-4700' PLUG#4 **STUB** 50 SXS RETNR SOZ 200 SXS 400 PLUG#6 DELAWARE MLF 0-10 **SURF** 10 SXS PLU0#7 BELL CANYON 9375 B. Speirs 25 CHERRY CANYON PLUG#1 7300 PLUG#2 DN TOOL 25 BRUSHY CANYON BONE SPRING PLUG#3 **QUEEN** 25 4500 25/2 S PLING#4 25 2450 1950 PLUG#5 T-SALT 25 GLORIETA TOC SURF 11345 450 BLINEBRY PLUG#6 50 PLUG#7 плвв PLUG#8 DRINKARD PLIMA PLUG# 10 PLUG# wc PLUG# PENN STRAWN ATOKA MORROW TD 10 155 DEVONIAN

(3 STRING CSNG)

PLUGGING & ABANDONMENT WORKSHEET