State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	TION DIVISION		
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240	1220 South St Santa Fe, N		WELL API NO. 30-025-124	96
DISTRICT II	, -		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
	ICES AND REPORTS ON WELI		7. Lease Name or Unit Agreem	ent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "AP	PLICATION FOR PERMIT" (Form G101		North Hobbs (G/SA) Unit Section 28	
1. Type of Well:			8. Well No. 141	
Oil Well X	Gas Well Other			
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.			40.75	
3. Address of Operator	- 0000		10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323			
4. Well Location				
Unit Letter M : 330	Feet From The South	Feet	From The West	Line
Section 28	Township 18-S	Range 38-E	NMPM	Lea County
	11. Elevation (Show whether DF, RKB, 3639' GL	, RT GR, etc.)	444	Maria de la companya
			Harittanian ilaania sirrataan	
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground	Water Distance from nea	arest fresh water well	Distance from nearest su	rface water
Pit Liner Thickness mil	Below-Grade Tank: Volume			
12. Check	Appropriate Box to Indicate Natu	re of Notice Penart or O	ther Data	
NOTICE OF INTE			EQUENT REPORT OF	·:
PERFORM REMEDIAL WORK		REMEDIAL WORK	ALTERING	
TENTONIA NEWEBIAE WORK	TEOGRAPH	KEWIEDIAE WORK	ALIENINO	CA31143
TEMPODADILY ADAMBON	CHANCE DIANC	SOMMENOE DON LINO ODN	~ [5,1,0,0,4,7	TANDONIATNIT -
TEMPORARILY ABANDON		COMMENCE DRILLING OPN	S. PLUG & AF	BANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING		COMMENCE DRILLING OPN CASING TEST AND CEMENT		BANDONMENT
	Multiple Completion			BANDONMENT
PULL OR ALTER CASING OTHER: Clean out/acid treat	Multiple Completion X	CASING TEST AND CEMENT OTHER:	I JOB	
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope	Multiple Completion X C	CASING TEST AND CEMENT OTHER: ails, and give pertinent dates	, including estimated date of	starting any
PULL OR ALTER CASING OTHER: Clean out/acid treat	Multiple Completion X C	CASING TEST AND CEMENT OTHER: ails, and give pertinent dates	, including estimated date of	starting any
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole	Multiple Completion X Crations (Clearly state all pertinent deteor Multiple Completions: Attach well with ESP equipment.	CASING TEST AND CEMENT OTHER: ails, and give pertinent dates	, including estimated date of	starting any
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C	Multiple Completion X rations (Clearly state all pertinent deteor Multiple Completions: Attach well with ESP equipment. irculate clean.	CASING TEST AND CEMENT OTHER:ails, and give pertinent dates Ilbore dagram of proposed co	, including estimated date of completion or recompletion.	starting any
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15%	Multiple Completion X rations (Clearly state all pertinent deteor Multiple Completions: Attach well with ESP equipment. irculate clean.	CASING TEST AND CEMENT OTHER:ails, and give pertinent dates Ilbore dagram of proposed co	, including estimated date of completion or recompletion.	starting any
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze.	Multiple Completion X rations (Clearly state all pertinent deteor Multiple Completions: Attach well with ESP equipment. irculate clean. 6 PAD acid with gelled rock salt blo	CASING TEST AND CEMENT OTHER:ails, and give pertinent dates Ilbore dagram of proposed co	, including estimated date of completion or recompletion.	starting any
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment	Multiple Completion X rations (Clearly state all pertinent deteor Multiple Completions: Attach well with ESP equipment. irculate clean. 6 PAD acid with gelled rock salt blo	CASING TEST AND CEMENT OTHER:ails, and give pertinent dates Ilbore dagram of proposed co	, including estimated date of completion or recompletion.	starting any
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze.	Multiple Completion X rations (Clearly state all pertinent deteor Multiple Completions: Attach well with ESP equipment. irculate clean. 6 PAD acid with gelled rock salt blo	CASING TEST AND CEMENT OTHER:ails, and give pertinent dates Ilbore dagram of proposed co	, including estimated date of completion or recompletion.	starting any 62726 7 900 800 123
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment	Multiple Completion X rations (Clearly state all pertinent deteor Multiple Completions: Attach well with ESP equipment. irculate clean. 6 PAD acid with gelled rock salt blo	CASING TEST AND CEMENT OTHER:ails, and give pertinent dates Ilbore dagram of proposed co	, including estimated date of completion or recompletion.	starting any
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment	Multiple Completion X rations (Clearly state all pertinent deteor Multiple Completions: Attach well with ESP equipment. irculate clean. 6 PAD acid with gelled rock salt blo	CASING TEST AND CEMENT OTHER:ails, and give pertinent dates Ilbore dagram of proposed co	, including estimated date of completion or recompletion.	starting any 62726 7 900 800 123
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment	Multiple Completion X rations (Clearly state all pertinent deteor Multiple Completions: Attach well with ESP equipment. irculate clean. 6 PAD acid with gelled rock salt blo	CASING TEST AND CEMENT OTHER:ails, and give pertinent dates Ilbore dagram of proposed co	, including estimated date of completion or recompletion.	starting any 62726 7 900 800 123
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment	Multiple Completion X rations (Clearly state all pertinent deteor Multiple Completions: Attach well with ESP equipment. irculate clean. 6 PAD acid with gelled rock salt blo	CASING TEST AND CEMENT OTHER:ails, and give pertinent dates Ilbore dagram of proposed co	, including estimated date of completion or recompletion.	starting any 62726 7 900 800 123
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production.	Multiple Completion X	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates Ilbore dagram of proposed co	n, including estimated date of completion or recompletion.	starting any 627263 000 8627263
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production. I hereby certify that the information above is treonstructed or	Multiple Completion X	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates Ilbore dagram of proposed co	n, including estimated date of completion or recompletion.	starting any 627263 000 8627263
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production.	Multiple Completion X	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates libore dagram of proposed co ock. Flush with 50 bbl fresh dge and belief. Further certify the	n, including estimated date of completion or recompletion. a water.	starting any 627263 000 8627263
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production. I hereby certify that the information above is treonstructed or	Multiple Completion X	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates libore dagram of proposed co ock. Flush with 50 bbl fresh	n, including estimated date of completion or recompletion. a water.	starting any 627263 000 8627263
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production. I hereby certify that the information above is treonstructed or	Multiple Completion X	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates libore diagram of proposed co ock. Flush with 50 bbl fresh dge and belief. Further certify the or an (attached) alternative plan)	nat any pit or below-grade tank ha	starting any 6627263 900 800 800 800 800 800 800 80
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production. I hereby certify that the information above is tree constructed or closed according to NMOCD guidelines SIGNATURE SIGNATURE	Multiple Completion Tations (Clearly state all pertinent detror Multiple Completions: Attach well with ESP equipment. irculate clean. APAD acid with gelled rock salt bloomt. The period of the best of my knowled the complete to the best of my knowled the complete to the best of my knowled.	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates albore diagram of proposed cook. Flush with 50 bbl fresh alge and belief. Further certify the or an (attached) alternative plan. TITLE Administrative A	nat any pit or below-grade tank has OCD-approved Associate DATE	starting any starting any solution solution
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production. I hereby certify that the information above is tree constructed or closed according to NMOCD guidelines SIGNATURE SIGNATURE	Multiple Completion Tations (Clearly state all pertinent detror Multiple Completions: Attach well with ESP equipment. irculate clean. APAD acid with gelled rock salt bloomt. The period of the best of my knowled the complete to the best of my knowled the complete to the best of my knowled.	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates libore diagram of proposed co ock. Flush with 50 bbl fresh dge and belief. Further certify the or an (attached) alternative plan)	nat any pit or below-grade tank ha	starting any 6627263 900 800 800 800 800 800 800 80
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production. I hereby certify that the information above is trends to constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. John For State Use Only	Multiple Completion Tations (Clearly state all pertinent detror Multiple Completions: Attach well with ESP equipment. irculate clean. APAD acid with gelled rock salt bloomt. The period of the best of my knowled the complete to the best of my knowled the complete to the best of my knowled.	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates albore diagram of proposed contacts. Flush with 50 bbl fresh dige and belief. Further certify the or an (attached) alternative plan alternative Administrative Amendy johnson@oxy.com	nat any pit or below-grade tank has OCD-approved Associate DATE TELEPHONE NO.	starting any 26272833 2929 3939 3949 3959 3969
OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production. I hereby certify that the information above is tree constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. John For State Use Only APPROVED BY Haryway Language 1. Clean out/acid treat Approved By Haryway Language 1. Clean out/acid treat Approved By Haryway Language 1. Clean out/acid treat Table 1. Clean out/acid treat Approved By Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only Approved By Haryway Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only Approved By Haryway Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only Approved By Haryway Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only	Multiple Completion TX Tations (Clearly state all pertinent detector Multiple Completions: Attach well with ESP equipment. irculate clean. A PAD acid with gelled rock salt bloomt. The property of the best of my knowled the pertinent detector Multiple Completions: Attach well with ESP equipment. The property of the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates libore diagram of proposed cook. Flush with 50 bbl fresh or an (attached) alternative plan TITLE Administrative Amendy johnson@oxy.com	nat any pit or below-grade tank hat OCD-approved Associate DATE TELEPHONE NO.	starting any 26272833 2929 3939 3949 3959 3969
PULL OR ALTER CASING OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production. I hereby certify that the information above is trends to constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. John For State Use Only	Multiple Completion TX Tations (Clearly state all pertinent detector Multiple Completions: Attach well with ESP equipment. irculate clean. A PAD acid with gelled rock salt bloomt. The property of the best of my knowled the pertinent detector Multiple Completions: Attach well with ESP equipment. The property of the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates libore diagram of proposed cook. Flush with 50 bbl fresh or an (attached) alternative plan TITLE Administrative Amendy johnson@oxy.com	nat any pit or below-grade tank hat OCD-approved Associate DATE TELEPHONE NO.	starting any 62726 9092 100
OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production. I hereby certify that the information above is tree constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. John For State Use Only APPROVED BY Haryway Language 1. Clean out/acid treat Approved By Haryway Language 1. Clean out/acid treat Approved By Haryway Language 1. Clean out/acid treat Table 1. Clean out/acid treat Approved By Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only Approved By Haryway Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only Approved By Haryway Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only Approved By Haryway Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only	Multiple Completion TX Tations (Clearly state all pertinent detector Multiple Completions: Attach well with ESP equipment. irculate clean. A PAD acid with gelled rock salt bloomt. The property of the best of my knowled the pertinent detector Multiple Completions: Attach well with ESP equipment. The property of the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates libore diagram of proposed cook. Flush with 50 bbl fresh or an (attached) alternative plan TITLE Administrative Amendy johnson@oxy.com	nat any pit or below-grade tank hat OCD-approved Associate DATE TELEPHONE NO.	starting any 62726 9092 100
OTHER: Clean out/acid treat 13. Describe Proposed or Completed Ope proposed work) SEE RULE 1103. F 1. Kill well. NU BOP. Pull out of hole 2. Clean out well to PBTD @4228'. C 3. Acid treat well with 2000 gal of 15% 4. Perform scale squeeze. 5. Run back in hole with ESP equipment 6. Return well to production. I hereby certify that the information above is tree constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. John For State Use Only APPROVED BY Haryway Language 1. Clean out/acid treat Approved By Haryway Language 1. Clean out/acid treat Approved By Haryway Language 1. Clean out/acid treat Table 1. Clean out/acid treat Approved By Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only Approved By Haryway Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only Approved By Haryway Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only Approved By Haryway Language 1. Clean out/acid treat Type OR PRINT NAME Mendy A. John For State Use Only	Multiple Completion TX Tations (Clearly state all pertinent detector Multiple Completions: Attach well with ESP equipment. irculate clean. A PAD acid with gelled rock salt bloomt. The property of the best of my knowled the pertinent detector Multiple Completions: Attach well with ESP equipment. The property of the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowled the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete to the best of my knowledge the pertinent detector Multiple Complete	CASING TEST AND CEMENT DTHER: ails, and give pertinent dates albore diagram of proposed contacts. Flush with 50 bbl fresh dige and belief. Further certify the or an (attached) alternative plan alternative Administrative Amendy johnson@oxy.com	nat any pit or below-grade tank hat OCD-approved Associate DATE TELEPHONE NO.	starting any 62726 9092 100