Submit 3 Copies To Appropriate District	State of New		Form C-103
Office District I	Energy, Minerals and Na	itural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.
District II	OIL CONSERVATI	ON DIVISION	30-025-04525
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. 1		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM		STATE X FEE
District IV	Salita Fe, Niv	1 0 / 3 0 3	
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.
SUNDRY NOTICE	S AND REPORTS ON W	'ELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSITION OF THE PROPOSALS.)	SALS TO DRILL OR TO DEEPE	N OR PLUG BACK TO A	Eunice Monument South Unit
1. Type of Well: Oil Well X Gas Well	Other	A	8. Well Number 249
2. Name of Operator	o uner		9. OGRID Number
-		My sat	005380
XTO Energy, Inc.		Received	
3. Address of Operator	W: 13 TV 70701	Hobbs	10. Pool name or Wildcat
200 N. Loraine, Ste. 800	Midland, IX /9/01		Eunice Monument: Grayburg-San Andres
4. Well Location			
Unit Letter!:	1980 feet from the	South line and	660 feet from the West line
Section 9-6	Township 21S	Range 36E	NMPM County Lea
Beetron			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application	or Closure		
Pit type Depth to Groundwater _		resh water well Dis	stance from nearest surface water
Pit Liner Thickness: mil			on Material
THE PHICKIESS.	Delow-Grade Talik. Volu	neobis, Constructi	on viaceriax
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	NG OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB	
OTHER: Clean Out, Acid Stim &	Scale Sqz. Well 🔀	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
MI and rack 2-7/8" workstring. POOH w/rods. ND WH. NU BOP. MIRU Scanalog. RIH w/4-3/4" bit on workstring to 3,838'. RIH w/Sonic Hammer on 2-7/8" workstring. RIH w/5-1/2" packer on workstring. Set packer at 3,715'. RU pumping company on backside & pressure test TCA to 500#. Treat the isolated interval w/5,000 gals of 20% NEFE 90/10 in 5 stages dropping rock salt.			
Sqz perfs & open hole w/scale inhibitor. RIH w/production tbg, rods, & pump. ND BOP. NU WH. Put well in test and RWTP.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan			
SIGNATURE & rists W	asd		ry Analyst DATE 01/17/07
Type or print name Kristy Ward		E-mail address: kr	isty_ward@xtoenergy.com isty_ward@xtoenergy.com isty_ward@xtoenergy.com isty_ward@xtoenergy.com
,	·	- wetar	Sophone 10. 432-020-0740
For State Use Only	ما المالياليا	CALL STANFORM	in control
APPROVED BY Conditions of Approval, if any.	with of	MILE	DATE