Office		exico	Form C-103		
District I	Energy, Minerals and Natu	ral Resources	May 27, 2004		
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONCEDUATION	DIVICION	WELL API NO. 30-025-10715		
District III  District III  OIL CONSERVATION DIVISION  1220 South St. Francis Dr.		5. Indicate Type of Lease			
1000 Dio Prozos Pd. Astes NM 97410		STATE 🛛 FEE 🗌			
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	/505	6. State Oil & Gas Lease No.		
87505					
	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSED DIFFERENT RESERVOIR. USE "APPLICE "APPLICE"			State A A/C 1		
PROPOSALS.)			8. Well Number 78		
Type of Well: Oil Well     Name of Operator	Gas Well 🛛 Other		9. OGRID Number		
Petrohawk Operating			9. OGRID Number		
3. Address of Operator			10. Pool name or Wildcat		
1000 Louisiana, Suite 5600 Houston TX 77002			Jalmat, Tansill, Yates, 7Rivers (gas)		
4. Well Location					
Unit LetterG:	1980feet from theFNL	line and	1980feet from theFELline		
Section 14	Township 23S	Range 36E			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
Bit or Poloni guada Tank Amplication .	3400 GR	· · · · · · · · · · · · · · · · · · ·			
Pit or Below-grade Tank Application or Closure  Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN	TENTION TO:	SUBS	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WORK			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRII			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB		
OTHER:		OTHER:			
	(011	pertinent details, and	give pertinent dates, including estimated date		
		of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
of starting any proposed wo		le Completions: Att	ach wellbore diagram of proposed completion		
of starting any proposed wo or recompletion.	rk). SEE RULE 1103. For Multip	le Completions: Att	ach wellbore diagram of proposed completion		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze	rk). SEE RULE 1103. For Multipoerfs: 3055'-3070' w/45 sks cmt.	le Completions: Att	ach wellbore diagram of proposed completion		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p 2. DO squeeze & CO to 3450'	rk). SEE RULE 1103. For Multip perfs: 3055'-3070' w/ 45 sks cmt. . Set CIBP on tbg @ 3425'.	-			
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p 2. DO squeeze & CO to 3450'	rk). SEE RULE 1103. For Multip perfs: 3055'-3070' w/ 45 sks cmt. . Set CIBP on tbg @ 3425'. casing liner @ 3425'. Cmt w/ 250	-			
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p 2. DO squeeze & CO to 3450' 3. Run 82 jts 4 ½' 11.60# J-55 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each	ork). SEE RULE 1103. For Multipoerfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'.  casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'.  perf w/ PPI tool.	-			
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p 2. DO squeeze & CO to 3450' 3. Run 82 jts 4 ½" 11.60# J-55 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendati	ork). SEE RULE 1103. For Multipoerfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'.  casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'.  perf w/ PPI tool. on.	-	5 sks to pit.		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p 2. DO squeeze & CO to 3450' 3. Run 82 jts 4 ½" 11.60# J-55 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendati 7. Flow & test well. Put well of	ork). SEE RULE 1103. For Multipoerfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'.  casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'.  perf w/ PPI tool.  on.  n pump. Put well to sales.	-	5 sks to pit.		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p 2. DO squeeze & CO to 3450' 3. Run 82 jts 4 ½" 11.60# J-55 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendati	ork). SEE RULE 1103. For Multipoerfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'.  casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'.  perf w/ PPI tool.  on.  n pump. Put well to sales.	-	5 sks to pit.		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p 2. DO squeeze & CO to 3450' 3. Run 82 jts 4 ½" 11.60# J-55 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendati 7. Flow & test well. Put well of	ork). SEE RULE 1103. For Multipoerfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'.  casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'.  perf w/ PPI tool.  on.  n pump. Put well to sales.	-	5 sks to pit.		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p 2. DO squeeze & CO to 3450' 3. Run 82 jts 4 ½" 11.60# J-55 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendati 7. Flow & test well. Put well of	ork). SEE RULE 1103. For Multipoerfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'.  casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'.  perf w/ PPI tool.  on.  n pump. Put well to sales.	-	5 sks to pit.		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p 2. DO squeeze & CO to 3450' 3. Run 82 jts 4 ½" 11.60# J-55 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendati 7. Flow & test well. Put well of	ork). SEE RULE 1103. For Multipoerfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'.  casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'.  perf w/ PPI tool.  on.  n pump. Put well to sales.	-	5 sks to pit.		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p 2. DO squeeze & CO to 3450' 3. Run 82 jts 4 ½" 11.60# J-55 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendati 7. Flow & test well. Put well of	ork). SEE RULE 1103. For Multipoerfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'.  casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'.  perf w/ PPI tool.  on.  n pump. Put well to sales.	-	5 sks to pit.  5 sks to pit.  15 08 67 8 9 10 77 73 13 14 15 16 17 78 16 17 78 16 17 78 16 16 17 78 16 16 17 78 16 16 17 78 16 16 16 16 16 16 16 16 16 16 16 16 16		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p. 2. DO squeeze & CO to 3450'  3. Run 82 jts 4 ½' 11.60# J-55  4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendati 7. Flow & test well. Put well c. 8. See attached wellbore diagr	perfs: 3055'-3070' w/ 45 sks cmt. Set CIBP on tbg @ 3425'. casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'. perf w/ PPI tool. on. n pump. Put well to sales. am.	sks cmt, circulate 2.	5 sks to pit.  Eog 6789 1077 23 13 16 17 78 17 78 17 17 17 17 17 17 17 17 17 17 17 17 17		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p. 2. DO squeeze & CO to 3450'. 3. Run 82 jts 4 ½'. 11.60# J-55. 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendat. 7. Flow & test well. Put well c. 8. See attached wellbore diagr.	perfs: 3055'-3070' w/ 45 sks cmt. Set CIBP on tbg @ 3425'. casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'. perf w/ PPI tool. on. n pump. Put well to sales. am.	sks cmt, circulate 2.	5 sks to pit.		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p. 2. DO squeeze & CO to 3450.  3. Run 82 jts 4 ½. 11.60# J-55.  4. RU E line. Perf: Tansill, Ya. 5. Break down & acidize each. 6. Frac well per recommendat. 7. Flow & test well. Put well of 8. See attached wellbore diagramments. See attached wellbore diagramments. See attached wellbore diagramments.	perfs: 3055'-3070' w/ 45 sks cmt. Set CIBP on tbg @ 3425'. casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'. perf w/ PPI tool. on. n pump. Put well to sales. am.	est of my knowledge	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p. 2. DO squeeze & CO to 3450. 3. Run 82 jts 4 ½. 11.60# J-55. 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendat. 7. Flow & test well. Put well of 8. See attached wellbore diagrate tank has been/will be constructed or SIGNATURE.	perfs: 3055'-3070' w/ 45 sks cmt. Set CIBP on tbg @ 3425'. casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'. perf w/ PPI tool. on. n pump. Put well to sales. am.	sks cmt, circulate 2.	s and belief. I further certify that any pit or below-		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p. 2. DO squeeze & CO to 3450°. 3. Run 82 jts 4 ½" 11.60# J-55. 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendate 7. Flow & test well. Put well constructed or 8. See attached wellbore diagrate tank has been/will be constructed or SIGNATURE J.	perfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'. casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'. perf w/ PPI tool. on. n pump. Put well to sales. am.  Above is true and complete to the beclosed according to NMOCD guidelines [	est of my knowledge  a general permit   coduction Foreman  cess: jsisk@petroha	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan   DATE 2-12-07  wk.com Telephone No. 505-394-2574		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p. 2. DO squeeze & CO to 3450. 3. Run 82 jts 4 ½. 11.60# J-55. 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendat. 7. Flow & test well. Put well of 8. See attached wellbore diagrate tank has been/will be constructed or SIGNATURE.	perfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'. casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'. perf w/ PPI tool. on. n pump. Put well to sales. am.  Above is true and complete to the beclosed according to NMOCD guidelines [	est of my knowledge  a general permit   coduction Foreman  cess: jsisk@petroha	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan   DATE 2-12-07  wk.com Telephone No. 505-394-2574		
of starting any proposed wo or recompletion.  1. MIRU. NU-BOP. Squeeze p. 2. DO squeeze & CO to 3450°. 3. Run 82 jts 4 ½" 11.60# J-55. 4. RU E line. Perf: Tansill, Ya 5. Break down & acidize each 6. Frac well per recommendate 7. Flow & test well. Put well constructed or 8. See attached wellbore diagrate tank has been/will be constructed or SIGNATURE J.	perfs: 3055'-3070' w/ 45 sks cmt.  Set CIBP on tbg @ 3425'. casing liner @ 3425'. Cmt w/ 250 tes, 7 Rivers 2938'-3375'. perf w/ PPI tool. on. n pump. Put well to sales. am.  Above is true and complete to the beclosed according to NMOCD guidelines [	est of my knowledge  a general permit   coduction Foreman  cess: jsisk@petroha	and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE 2-12-07		

