

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.	30-025-03188
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	E-7277
7. Lease Name or Unit Agreement Name:	East Pearl Queen Unit
8. Well No.	17
9. Pool name or Wildcat	Pearl Queen

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☐ Injection	
2. Name of Operator Xeric Oil & Gas Corporation	
3. Address of Operator P. O. Box 352 Midland, TX 79702	
4. Well Location Unit Letter <u>P</u> : <u>660</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>22</u> Township <u>19S</u> Range <u>35E</u> NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3743' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 1) MIRU Pulling Unit.
- 2) Circulate hole w/+/- 60 bbls mud.
- 3) Tag top of cement retainer @ 3775'.
- 4) Perforate @ 1700' & squeeze 25 sx cement 50' in & out & tag.
- 5) Perforate @ 350' & squeeze 50' out and circulate to surface.
- 6) Spot 10 sx plug @ 60'.
- 7) RD. Install dry hole marker & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 9/4/03
Type or print name Angie Crawford Telephone No. 432-683-3171

(This space for State use)

APPROVED BY GARY W WINK OC FIELD REPRESENTATIVE II/STAFF MANAGER
Conditions of approval, if any: GARY W WINK DATE SEP 08 2003
OC FIELD REPRESENTATIVE II/STAFF MANAGER

XERIC OIL & GAS CORP.
WELLBORE DIAGRAM

WELL: East Pearl Queen #17

COUNTY: Lea

STATE: NM

