Submit 3 Copes To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	•	WELL API NO.
District II	OIL CONSERVATION DIVISION	30-025-26580
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE S FEE
District IV	Santa Fe, NWI 87303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		E-7585
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		East Vacuum GB/SA Unit Tract #2980
PROPOSALS.)		8. Well Number 002
	Gas Well Other	
2. Name of Operator		9. OGRID Number
ConocoPhillips Company ATTN: Celeste Dale		217817 10. Pool name or Wildcat
3. Address of Operator		
3303 N. St	reet, Bldg. 6 #247, Midland, Texas 79705-5406	Vacuum Grayburg/San Andres
4. Well Location		
Unit Letter F :	1,330 feet from the North line and	1,330 feet from the West line
Section 29	Township 17-S Range 35-E	
South 25	11. Elevation (Show whether DR, RKB, RT, GR, of	
	3,973' GR	
Pit or Below-grade Tank Application O		
		Distance from nearest surface water N/A
" = :		
Pit Liner Thickness: STEEL mi	Below-Grade Tank: Volume 180 bbls;	Construction Material STEEL
12. Check A	appropriate Box to Indicate Nature of Notice	ce, Report or Other Data
	• •	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE I	DRILLING OPNS.□ P AND A 🛛
 -		ENT ION
PULL OR ALTER CASING	MULTIPLE COMPL II CASING/CEM	ENIJOB⊚∢⊜ ∋∂1⊠
PULL OR ALTER CASING OTHER:	MULTIPLE COMPL CASING/CEM OTHER:	ENT JOB 19 20 2723
OTHER:	☐ OTHER:	1 €2/
OTHER: 13. Describe proposed or compl	eted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date Attach wellbore diagrams of proposed completion
OTHER: 13. Describe proposed or comple of starting any proposed wo	☐ OTHER:	and give pertinent dates, including estimated date Attach wellbore diagrams of proposed completion
OTHER: 13. Describe proposed or compl	eted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date Attach wellbore diagrams of proposed completion
OTHER: 13. Describe proposed or compl of starting any proposed wo or recompletion.	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagrams of proposed completion
OTHER: 13. Describe proposed or complor of starting any proposed wo or recompletion. See attached plugged wellbore	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a plugging equipment. SD WO rig anchors.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a plugging equipment. SD WO rig anchors.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a plugging equipment. SD WO rig anchors.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a plugging equipment. SD WO rig anchors.
OTHER: 13. Describe proposed or complor of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. Help of the safety meeting. P SDFN.	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26 OOH laying down rods & pump. NU BOP. POINT POI	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'.
OTHER: 13. Describe proposed or complos of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'.
OTHER: 13. Describe proposed or complor of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26 OOH laying down rods & pump. NU BOP. PO IH w/ HM tubing-set CIBP on workstring to 4,4 led 25 sx C cmt 4,476 – 4,228'. Pumped 25 sx gged cmt @ 1,515'. Pumped 25 sx C cmt 412	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'.
OTHER: 13. Describe proposed or complos of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26 OOH laying down rods & pump. NU BOP. PO IH w/ HM tubing-set CIBP on workstring to 4,4 led 25 sx C cmt 4,476 – 4,228'. Pumped 25 sx gged cmt @ 1,515'. Pumped 25 sx C cmt 412	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, is	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26 OOH laying down rods & pump. NU BOP. PO IH w/ HM tubing-set CIBP on workstring to 4,4 led 25 sx C cmt 4,476 – 4,228'. Pumped 25 sx gged cmt @ 1,515'. Pumped 25 sx C cmt 412 RD.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, is	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26 OOH laying down rods & pump. NU BOP. PO IH w/ HM tubing-set CIBP on workstring to 4,4 led 25 sx C cmt 4,476 – 4,228'. Pumped 25 sx led dry hole marker. Backfilled cellar. Ap	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. C C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bors.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, is	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26 OOH laying down rods & pump. NU BOP. PO IH w/ HM tubing-set CIBP on workstring to 4,4 led 25 sx C cmt 4,476 – 4,228'. Pumped 25 sx logged cmt @ 1,515'. Pumped 25 sx C cmt 412 RD. Ap Lia Ap Lia Ap Lia Ap Lia Ap Lia Lia Ap Lia Lia Ap Lia Li	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. C C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bore. bility under bond is retained until
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, is	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26 OOH laying down rods & pump. NU BOP. PO IH w/ HM tubing-set CIBP on workstring to 4,4 led 25 sx C cmt 4,476 – 4,228'. Pumped 25 sx logged cmt @ 1,515'. Pumped 25 sx C cmt 412 RD. Ap Lia Ap Lia Ap Lia Ap Lia Ap Lia Lia Ap Lia Lia Ap Lia Li	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. C C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bors.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, is Cut off wellhead & anchors, instal	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26 OOH laying down rods & pump. NU BOP. PO IH w/ HM tubing-set CIBP on workstring to 4,4 led 25 sx C cmt 4,476 – 4,228'. Pumped 25 sx logged cmt @ 1,515'. Pumped 25 sx C cmt 412 RD. led dry hole marker. Backfilled cellar. Ap Lia sur	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bore bility under bond is retained until face restoration is completed.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, if Cut off wellhead & anchors, install I hereby certify that the information a	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26 OOH laying down rods & pump. NU BOP. PO IH w/ HM tubing-set CIBP on workstring to 4,4 led 25 sx C cmt 4,476 – 4,228'. Pumped 25 sx logged cmt @ 1,515'. Pumped 25 sx C cmt 412 RD. led dry hole marker. Backfilled cellar. Ap Lia sur	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bore bility under bond is retained until face restoration is completed.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, if Cut off wellhead & anchors, install I hereby certify that the information a	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram eld tailgate safety meeting. MI Triple N rig #26 OOH laying down rods & pump. NU BOP. PO IH w/ HM tubing-set CIBP on workstring to 4,4 led 25 sx C cmt 4,476 – 4,228'. Pumped 25 sx logged cmt @ 1,515'. Pumped 25 sx C cmt 412 RD. led dry hole marker. Backfilled cellar. Ap Lia sur	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bore bility under bond is retained until face restoration is completed.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, I Cut off wellhead & anchors, instal	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bors. bility under bond is retained until face restoration is completed. edge and belief. I further certify that any pit or belowing or an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, if Cut off wellhead & anchors, install I hereby certify that the information a	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bore bility under bond is retained until face restoration is completed.
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, R Cut off wellhead & anchors, instal	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bore. In proved as to plugging of the Well Bore. Edge and belief. I further certify that any pit or belowed or an (attached) alternative OCD-approved plan . In P.E. (Triple N Services) DATE 02/16/07
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, I Cut off wellhead & anchors, instal I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Type or print name	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bors. bility under bond is retained until face restoration is completed. edge and belief. I further certify that any pit or belowing or an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, R Cut off wellhead & anchors, instal	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bore. In proved as to plugging of the Well Bore. Edge and belief. I further certify that any pit or belowed or an (attached) alternative OCD-approved plan . In P.E. (Triple N Services) DATE 02/16/07
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, if Cut off wellhead & anchors, instal I hereby certify that the information a grade tank has been/will be constructed or start of the st	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bore bility under bond is retained until face restoration is completed. edge and belief. I further certify that any pit or belowing or an (attached) alternative OCD-approved plan . n. P.E. (Triple N Services) DATE 02/16/07 iplenservices.com Telephone No. 432-687-1994
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, if Cut off wellhead & anchors, instal I hereby certify that the information a grade tank has been/will be constructed or state Use Only APPROVED BY:	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bore. bility under bond is retained until face restoration is completed. edge and belief. I further certify that any pit or belowed or an (attached) alternative OCD-approved plan . n. P.E. (Triple N Services) DATE 02/16/07 iplenservices.com Telephone No. 432-687-1994
OTHER: 13. Describe proposed or complete of starting any proposed wo or recompletion. See attached plugged wellbore 02/13/07 Set steel working pit. He 02/14/07 Held safety meeting. P SDFN. 02/15/07 Held safety meeting. R Circulated hole w/ mud and pump w/ CaCl ₂ @ 1,751'. WOC and tag 96' to surface. POOH w/ tubing, if Cut off wellhead & anchors, instal I hereby certify that the information a grade tank has been/will be constructed or start of the st	OTHER: leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: diagram	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion plugging equipment. SD WO rig anchors. OOH laving down production tubing. SI well, 76'. RU cementer and set CIBP @ 4,476'. (C cmt 2,762 – 2,514'. Pumped 25 sx C cmt – 165'. ND BOP and circulated 25 sx C cmt proved as to plugging of the Well Bore bility under bond is retained until face restoration is completed. edge and belief. I further certify that any pit or belowing or an (attached) alternative OCD-approved plan . n. P.E. (Triple N Services) DATE 02/16/07 iplenservices.com Telephone No. 432-687-1994

PLUGGED WELLBORE SKETCH

ConocoPhillips Company -- Mid-Continent Unit / Odessa

RKB@ 3984.7 DF@ 3973' GL@

Subarea: Buckeye

Lease & Well No.: East Vacuum GB/SA Unit, Tract 2980, Well No. 002

Legal Description : 1330' FNL & 1330' FWL, Sec. 29, T-17-S, R-35-E County: Lea State: New Mexico

Field: Vacuum (Grayburg-San Andres)

Date Spudded : Dec. 29, 1979 Rig Released: Jan. 11, 1980 30-025-26580

API Number : Status: PLUGGED 02/15/07

State Lease No. E-7585

Date: February 16, 2007

25 sx C cmt 96' to surface

11" Hole

8-5/8" 24# K-55 ST&C @ 353' Cmt'd w/350 sx, circ 80 sx 25 sx C cmt 412 - 165'

Stimulation History:

Max Max Lbs. Press ISIP Rate <u>Interval</u> <u>Date</u> <u>Type</u> <u>Gals</u> <u>Sand</u> 10/14/80 Perforate 4523-4638 (select fire) 4523-4638 10/15/80 15% NE HCI 6,000 4400 3850 YF-40 PSD 44,000 62,000 3380 3800 9/12/95 Perforate 4700-4750 (select fire)

4700-4750 9/14/95 15% HCI 2.500

Test 47 BOPD, 22 BWPD, 0.3 MCFPD

25 sx C cmt 1,751 -1,403' TAGGED Top of Salt @ 1670'



PLUGS SET 02/13/07 thru 02/15/07

1) set CIBP @ 4,476'

2) 25 sx C cmt 4,476 - 4,228'

3) 25 sx C cmt 2,762 - 2,514'

4) 25 sx C cmt 1,751 -1,403' TAGGED

5) 25 sx C cmt 412 - 165'

6) 25 sx C cmt 96' to surface

Base Salt @ 2670'

25 sx C cmt 2,762 - 2,514'

Capacities 4-1/2" 9.5# csg: 10.960 ft/ft3 0.0912 ft3/ft 7.661 ft/ft3 5-1/2" 17# csg: 0.1305 ft3/ft 7" 20# csg: 4.399 ft/ft3 0.2273 ft3/ft 7" 24# csg: 4.567 ft/ft3 0.2189 ft3/ft 3.775 ft/ft3 0.2648 ft3/ft 7-5/8" 26.4# csg: 8-5/8" 28# csg: 2.853 ft/ft3 0.3505 ft3/ft 9-5/8" 36# csg: 2.304 ft/ft3 0.4340 ft3/ft 13-3/8" 48# csg: 0.8817 ft3/ft 1.134 ft/ft3 7-7/8" openhole: 2.957 ft/ft3 0.3382 ft3/ft 8-3/4" openhole: 2.395 ft/ft3 0.4176 ft3/ft 11" openhole: 1.515 ft/ft3 0.66 ft3/ft

25 sx C cmt 4,476 - 4,228' set CIBP @ 4,476'

4523-4538 4562-4577 4600-4615 4623-4638 4700-4710 4715-4719 4730-4750

7-7/8" Hole

==

PBTD:

TD:

==

4850

5-1/2" 17# N-80 LT&C @ 4900" Cmt'd w/1065 sx, circ 55 sx

TOC @ Surface 4908

Formation Tops:

Rustler	1640'
Salado	
Yates	2940'
Queen	3808'
Grayburg	4202'
San Andres	4482'