Submit 3 Copies To Appropriate District Office State of New Mexico Energy Minerals and Natural Resources	Form C-103
District I	WELL API NO.
1625 N. French Dr., Hobbs, NM 87240 District II OIL CONSERVATION DIVISION	30-025-04542
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7 1 N
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Eunice Monument South Unit
1. Type of Well:	8. Well Number
Oil Well X Gas Well Other 2. Name of Operator	9. OGRID Number
XTO Energy, Inc.	9. OGRID Number 005380
3. Address of Operator	10. Pool name or Wildcat
200 N. Loraine, Ste. 800 Midland, TX 79701	Eunice Monument: Grayburg-San Andres
4. Well Location	
Unit Letter G: 1980 feet from the North line and	1980 feet from the East line
Section 7 Township 21S Range 36E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR,	etc.)
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well I	vistance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construc	tion Material
12. Check Appropriate Box to Indicate Nature of Notice	e, Report, or Other Data
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK TO PLUG AND ABANDON IXT REMEDIAL WORK	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL	BSEQUENT REPORT OF: ALTERING CASING LING OPNS. 61 18 19 20 27 AND PLUC AN
PERFORM REMEDIAL WORK TO PLUG AND ABANDON IXT REMEDIAL WORK	BSEQUENT REPORT OF: ALTERING CASING LING OPNS. 61 18 19 20 27 AND PLUC AN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE CASING TEST AN	ALTERING CASING DIAMETER PLUS AND ABANDON MET
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE CASING TEST AN CEMENT JOB OTHER: OTHER:	ALTERING CASING ABANDON ABANDO
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: OTHER: OTHER: The proposed or completed operations. (Clearly state all pertinent details, and go of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attached the proposed work of the proposed work.	ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ABANDO
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: OTHER: The proposed or completed operations. (Clearly state all pertinent details, and go of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompletion.	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONNATION ABANDONN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE CASING TEST AN CEMENT JOB OTHER: OTHER: OTHER: OTHER: MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP	ALTERING CASING ALTERING CASING ALTERING CASING ABANDONING ABANDON
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE CASING TEST AN CEMENT JOB OTHER: OTHER: OTHER: OTHER: MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP 2. Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 sho	ALTERING CASING ALTERING CASING ALTERING CASING ABANDON MATERIAL PLUC AND ABANDON MATERING CASING ABANDON MATERING CASING ABANDON MATERIAL PLUC ABANDON MA
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: OTHER: OTHER: MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 sho cement. Top of salt section is @ 1326' & bottom of salt section 3. PUH to 2,600'. Spot 30 sx cement. PUH to 2,275'. Tag TOC at 2	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ABANDONMEN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPLETION CHANGE PLANS OTHER: OTHER: OTHER: OTHER: MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 sho cement. Top of salt section is @ 1326' & bottom of salt section REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB CHANGE PLANS CHANGE PLANS CASING TEST AN CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and go of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. 1. MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP 2. Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 sho cement. Top of salt section is @ 1326' & bottom of salt section 3. PUH to 2,600'. Spot 30 sx cement. PUH to 2,275'. Tag TOC at 2 4. RIH w/wireline to 800' and perforate squeeze holes in 6 5/8" case	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ABANDONMEN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: OTHER: OTHER: I MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP 2. Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 shc cement. Top of salt section is @ 1326' & bottom of salt section 3. PUH to 2,600'. Spot 30 sx cement. PUH to 2,275'. Tag TOC at 2 4. RIH w/wireline to 800' and perforate squeeze holes in 6 5/8" cas 5. Pump cement down casing and through squeeze holes. Should take in	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ABANDONMEN
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: OTHER: OTHER: OTHER: MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP 2. Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 sho cement. Top of salt section is @ 1326' & bottom of salt section 3. PUH to 2,600'. Spot 30 sx cement. PUH to 2,275'. Tag TOC at 2. 4. RIH w/wireline to 800' and perforate squeeze holes in 6 5/8" cas 5. Pump cement down casing and through squeeze holes. Should take in Total of 200 sx for the surface plug.	ALTERING CASING ALTERING CASIN
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRIL PULL OR ALTER CASING MULTIPLE CASING TEST AN CEMENT JOB OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP 2. Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 shc cement. Top of salt section is @ 1326' & bottom of salt section 3. PUH to 2,600'. Spot 30 sx cement. PUH to 2,275'. Tag TOC at 2. A RIH w/wireline to 800' and perforate squeeze holes in 6 5/8" cas 5. Pump cement down casing and through squeeze holes. Should take in Total of 200 sx for the surface plug. 6. RDMO plugging company. Cut off wellhead and anchors, install dry	ALTERING CASING ALTERING CASIN
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AN CEMENT JOB OTHER: OTHER: OTHER: OTHER: MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP 2. Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 sho cement. Top of salt section is @ 1326' & bottom of salt section 3. PUH to 2,600'. Spot 30 sx cement. PUH to 2,275'. Tag TOC at 2. 4. RIH w/wireline to 800' and perforate squeeze holes in 6 5/8" cas 5. Pump cement down casing and through squeeze holes. Should take in Total of 200 sx for the surface plug.	ALTERING CASING ALTERING CASIN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE CASING TEST AN CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompletion. 1. MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP 2. Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 sho cement. Top of salt section is @ 1326' & bottom of salt section 3. PUH to 2,600'. Spot 30 sx cement. PUH to 2,275'. Tag TOC at 2. 4. RIH w/wireline to 800' and perforate squeeze holes in 6 5/8" cas 5. Pump cement down casing and through squeeze holes. Should take in Total of 200 sx for the surface plug. 6. RDMO plugging company. Cut off wellhead and anchors, install dry I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE Regulater.	ALTERING CASING ALTERING CASIN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE CASING TEST AN CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompletion. 1. MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP 2. Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 sho cement. Top of salt section is @ 1326' & bottom of salt section 3. PUH to 2,600'. Spot 30 sx cement. PUH to 2,275'. Tag TOC at 2. 4. RIH w/wireline to 800' and perforate squeeze holes in 6 5/8" cas 5. Pump cement down casing and through squeeze holes. Should take in Total of 200 sx for the surface plug. 6. RDMO plugging company. Cut off wellhead and anchors, install dry I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE Regulater.	ALTERING CASING ALTERING CASING ABANDONNIA A
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE CASING TEST AN CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompletion. 1. MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP 2. Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 sho cement. Top of salt section is @ 1326' & bottom of salt section 3. PUH to 2,600'. Spot 30 sx cement. PUH to 2,275'. Tag TOC at 2. 4. RIH w/wireline to 800' and perforate squeeze holes in 6 5/8" cas 5. Pump cement down casing and through squeeze holes. Should take in Total of 200 sx for the surface plug. 6. RDMO plugging company. Cut off wellhead and anchors, install dry I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permits SIGNATURE TITLE Regulate E-mail address: Type or print name Kristy Ward	ALTERING CASING ALTERING CASING ABANDONNIA A
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE CASING TEST AN CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and gi of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attacor recompletion. 1. MIRU PU. ND WH. NU BOP. TIH With 2 7/8" workstring and tag CIBP 2. Spot 60 sx cement. PUH to 3,070'. Tag TOC (3,172'), 8 5/8 she cement. Top of salt section is @ 1326' & bottom of salt section 3. PUH to 2,600'. Spot 30 sx cement. PUH to 2,275'. Tag TOC at 2. 4. RIH w/wireline to 800' and perforate squeeze holes in 6 5/8" cas 5. Pump cement down casing and through squeeze holes. Should take in Total of 200 sx for the surface plug. 6. RDMO plugging company. Cut off wellhead and anchors, install dry I hereby certify that the information above is true and complete to the best of my knowledgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Regulate E-mail address:	ALTERING CASING ABANDON ABANDO

Chevron

WELL DATA SHEET

