Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103	
	rgy, Minerals and Natural Resources	May 27, 2004	
District I 1625 N. French Dr., Hobbs, NM 88240	igy, willionals and water research	WELL API NO.	
	L CONSERVATION DIVISION	30-025-03463	
1301 W. Grand Ave., Artesia, NM 88210		5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.	STATE 🛛 FEE 🗌	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			
87505	DEPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		State W E E	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		State III 2	
PROPOSALS.)		8. Well Number 001	
1. Type of Well: Oil Well Gas Well	Other		
2. Name of Operator		9. OGRID Number	
Finley Resources, Inc.		180387 10. Pool name or Wildcat	
3. Address of Operator		Eumont: Yates-7 Rivers-Queen	
1308 Lake Street, Ste. 200, Fort Worth, Texas 76102		Eulliont. Fates-7 Kivers-Queen	
4. Well Location			
Unit Letter K : 2310'	feet from theSouth line and2:	310'feet from theWestline	
Section 13	Township 21S Range 35E	NMPM County Lea	
Section 13	vation (Show whether DR, RKB, RT, GR, etc.	c.)	
3,589° GL			
Pit or Below-grade Tank Application or Closure			
Donth to Croundwater	Distance from nearest fresh water wellD	istance from nearest surface water	
		Construction Material	
The Billet Timetimess.			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION	•••		
1 2 1 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	AND ABANDON 🔀 REMEDIAL WO	- · · · · · · · · · · · · · · · · · · ·	
TEINI OTO WILL THE TOTAL CONTROL OF THE TOTAL CONTROL OT THE TOTAL CONTROL OF THE TOTAL CONTR	— —		
PULL OR ALTER CASING	PLE COMPL CASING/CEME	NT JOB \square	
	CTUED:	П	
OTHER:	OTHER:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
13. Describe proposed or completed ope	rations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated date	
of starting any proposed work). SEF	rations. (Clearly state all pertinent details, a ERULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion	
 Describe proposed or completed ope of starting any proposed work). SEE or recompletion. 	rations. (Clearly state all pertinent details, a ERULE 1103. For Multiple Completions:	Attach wellbore diagram of proposed completion	
of starting any proposed work). SEE or recompletion.	E RULE 1103. For Multiple Completions: A	Attach wellbore diagram of proposed completion	
of starting any proposed work). SEE or recompletion.	erify. Circulate hole with 9.5#/gal. salt gel i	nud. Determined free point on 5 ½" casing. Cut	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to very a real real 5 1/2 energy within 100' of free point.	erify. Circulate hole with 9.5#/gal. salt gel i	nud. Determined free point on 5 ½" casing. Cut	
of starting any proposed work). SEE or recompletion.	erify. Circulate hole with 9.5#/gal. salt gel i	nud. Determined free point on 5 ½" casing. Cut	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to very a real real 5 1/2 energy within 100' of free point.	erify. Circulate hole with 9.5#/gal. salt gel i	nud. Determined free point on 5 ½" casing. Cut	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to very a real real 5 1/2 energy within 100' of free point.	erify. Circulate hole with 9.5#/gal. salt gel i	nud. Determined free point on 5 ½" casing. Cut	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to very a real real 5 1/2 energy within 100' of free point.	erify. Circulate hole with 9.5#/gal. salt gel i	nud. Determined free point on 5 ½" casing. Cut	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to very a real real 5 1/2 energy within 100' of free point.	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5	mud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to ve and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify.	erify. Circulate hole with 9.5#/gal. salt gel n or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5	mud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to ve and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify.	erify. Circulate hole with 9.5#/gal. salt gel n or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5	mud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to ve and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify.	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5	nud. Determined free point on 5 ½" casing. Cut	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to ve and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify.	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5	mud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to ve and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify.	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5	nud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to ve and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify.	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5	mud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to very and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify. THE OIL CONSERVATION OF PLUGGING OF BEGINNING OF PLUGGING OF PLUG	erify. Circulate hole with 9.5#/gal. salt gel n or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5 THE PERATIONS.	nud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to verify and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify. THE OIL CONSERVATION OF PLUGGING OF BEGINNING OF PLUGGING OF PL	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5 THE PERATIONS.	nud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to ve and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify. THE OIL CONSERYA BE NOTIFIED 24 1. BEGINNING OF PLUGGING OF BEGINNING OF PLUGGING OF PLUG	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5 THE PERATIONS.	nud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to ve and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify. THE OIL CONSERYA BE NOTIFIED 24 1. BEGINNING OF PLUGGING OF BEGINNING OF PLUGGING OF PLUG	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5 THE PERATIONS. true and complete to the best of my knowledge for the NMOCD guidelines , a general permit	mud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to ve and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify. THE OIL CONSERYA BE NOTIFIED 24 1. BEGINNING OF PLUGGING OF BEGINNING OF PLUGGING OF PLUG	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5 THE PERATIONS.	mud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker.	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to verify and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify BE NOTIFIED 24 is BEGINNING OF PLUGGING O	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5 THE PERATIONS. True and complete to the best of my knowle cording to NMOCD guidelines , a general permit	mud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker. 13141516	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to verify and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify BE NOTIFIED 24 is BEGINNING OF PLUGGING O	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5 THE PERATIONS. true and complete to the best of my knowledge for the NMOCD guidelines , a general permit	mud. Determined free point on 5 ½" casing. Cut low cut to 50' above cut. Tag to verify. Spot /8" casing and weld dry hole marker. 13141516	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to verify and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify BE NOTIFIED 24 is BEGINNING OF PLUGGING O	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5 THE PERATIONS. True and complete to the best of my knowle cording to NMOCD guidelines \(\square\), a general permit TITLE: Production & Oper	dge and belief. I further certify that any pit or belowarions EngineerDATE	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to wand pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify. THE OIL CONSERVATION BE NOTIFIED 24 1. BEGINNING OF PLUGGING OF BEGINNING OF PLUGGING OF BEGINNING OF PLUGGING OF BEGINNING OF PLUGGING OF STATE AND STATE AN	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5 THE PERATIONS. True and complete to the best of my knowle cording to NMOCD guidelines \(\square\), a general permit TITLE: Production & Oper	dge and belief. I further certify that any pit or belowarions EngineerDATE	
of starting any proposed work). SEE or recompletion. Set CIBP @ 3525'. Spot 25 sx cmt. Tag to verify and pull 5 ½" casing within 100' of freepoint 100' cement from 358' to 258'. Tag to verify BE NOTIFIED 24 is BEGINNING OF PLUGGING O	erify. Circulate hole with 9.5#/gal. salt gel is or +- 2000'. Spot 100' cement from 50' be. Spot 60' surface plug. Cut off excess 9 5 THE PERATIONS. True and complete to the best of my knowle cording to NMOCD guidelines , a general permit	dge and belief. I further certify that any pit or belowarions EngineerDATE	

State WE E #1

2310' FSL, 2310' FWL, Sec 13K T21S, R35E Lea Co., NM

Eumont Field completion Date: 5/1/54

KB 3589' API # 30 025 03463 NM ID 1149453 E-395

