State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVA	ATION DIVISION
1606 N. F I D. II. II. N. 00040	St. Francis Dr. WELL API NO. NM 87505 30-025-26973
<u>DISTRICT II</u>	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	STATE X FEE
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WEL	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O	OR PLUG BACK TO A North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form G10	
Type of Well: Oil Well Gas Well Other Inje	8. Well No. 323
2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	30,750
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location	
Unit Letter G : 1370 Feet From The NORTH	1400 Feet From The EAST Line
Section 32 Township 18-S	Range 38-E NMPM LEA County
11. Elevation (Show whether DF, RKI 3637' GR	B, RT GR, etc.)
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from ne	earest fresh water well Distance from nearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume	
THE EMICE THICKNESS IIII Delow-Glade Falix. Volume	oois, construction
12. Check Appropriate Box to Indicate Nati NOTICE OF INTENTION TO:	ure of Notice, Report, or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
	<u> </u>
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat X 13. Describe Proposed or Completed Operations (Clearly state all pertinent decompleted operations)	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat X 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach we	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat X 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach words. Test tubing/casing annulus to 1000 PSI.	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach work. 1. Test tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment.	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach works tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs.	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach works tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292').	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach works tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs.	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach works tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface.	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach works to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well.	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach works tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well. 9. Acid treat perfs with 1680 gal of 15% HCL acid.	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach we 1. Test tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well. 9. Acid treat perfs with 1680 gal of 15% HCL acid. 10. Run in hole with injection equipment.	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: etails, and give pertinent dates, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach works tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well. 9. Acid treat perfs with 1680 gal of 15% HCL acid.	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach we 1. Test tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well. 9. Acid treat perfs with 1680 gal of 15% HCL acid. 10. Run in hole with injection equipment.	CASING TEST AND CEMENT JOB OTHER: etails, and give pertinent dates, including estimated date of starting any ellbore diagram of proposed completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach we 1. Test tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well . 9. Acid treat perfs with 1680 gal of 15% HCL acid. 10. Run in hole with injection equipment. 11. Test casing and chart for the NMOCD.	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: Etails, and give pertinent dates, including estimated date of starting any ellbore diagram of proposed completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach we 1. Test tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well . 9. Acid treat perfs with 1680 gal of 15% HCL acid. 10. Run in hole with injection equipment. 11. Test casing and chart for the NMOCD.	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: Etails, and give pertinent dates, including estimated date of starting any ellbore diagram of proposed completion or recompletion. edge and belief. Ifurther certify that any pit of below-grade tank has been/will be or an (attached) alternative OCD-approved
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach we lead to be proposed work of the proposed wor	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: etails, and give pertinent dates, including estimated date of starting any ellbore diagram of proposed completion or recompletion. edge and belief. Ifurther certify that any pit of below-grade tank has been/will be or an (attached) alternative OCD-approved plan
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach we 1. Test tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well . 9. Acid treat perfs with 1680 gal of 15% HCL acid. 10. Run in hole with injection equipment. 11. Test casing and chart for the NMOCD.	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: Etails, and give pertinent dates, including estimated date of starting any ellbore diagram of proposed completion or recompletion. edge and belief. Ifurther certify that any pit of below-grade tank has been/will be or an (attached) alternative OCD-approved
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach we 1. Test tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well . 9. Acid treat perfs with 1680 gal of 15% HCL acid. 10. Run in hole with injection equipment. 11. Test casing and chart for the NMOCD. I hereby certify that the information above is true and complete to the best of my knowleast constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address:	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: ctails, and give pertinent dates, including estimated date of starting any ellbore diagram of proposed completion or recompletion. edge and belief. Ifurther certify that any pit of below-grade tank has been/will be or an (attached) alternative OCD-approved plan TITLE Administrative Associate DATE 03/23/2007 mendy johnson@oxy.com TELEPHONE NO. 505/397-8206
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach we 1. Test tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well. 9. Acid treat perfs with 1680 gal of 15% HCL acid. 10. Run in hole with injection equipment. 11. Test casing and chart for the NMOCD. I hereby certify that the information above is true and complete to the best of my knowledness according to NMOCD guidelines agency. A general permit SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address: For State Use Only	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: etails, and give pertinent dates, including estimated date of starting any ellbore diagram of poposed completion or recompletion. edge and belief. Ifurther certify that any pit of below-grade tank has been/will be or an (attached) alternative OCD-approved plan or TITLE Administrative Associate DATE 03/23/2007 mendy johnson@oxy.com TELEPHONE NO. 505/397-8206
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER: Run liner/perforate/acid treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent de proposed work) SEE RULE 1103. For Multiple Completions: Attach we 1. Test tubing/casing annulus to 1000 PSI. 2. Kill well. Pull injection equipment. 3. Set CICR @±3900'. Squeeze open perfs. 4. Drill out squeeze & clean out to PBTD (4292'). 5. Run 4-1/2" liner. Cement in place. 6. Clean out line & test to 1000 PSI. 7. Run CBL/CCL/GR from PBTD to surface. 8. Peforate well . 9. Acid treat perfs with 1680 gal of 15% HCL acid. 10. Run in hole with injection equipment. 11. Test casing and chart for the NMOCD. I hereby certify that the information above is true and complete to the best of my knowleast constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address:	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: ctails, and give pertinent dates, including estimated date of starting any ellbore diagram of proposed completion or recompletion. edge and belief. Ifurther certify that any pit of below-grade tank has been/will be or an (attached) alternative OCD-approved plan TITLE Administrative Associate DATE 03/23/2007 mendy johnson@oxy.com TELEPHONE NO. 505/397-8206