Submit 3 Copies To Appropriate District		State of New Mexico			Form C-103		
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240				Revised June 10, 2003 WELL API NO.			
District II I301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-00359 5. Indicate Type of Lease				
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1000 Rio Brazos Rd., Aztec, NM 87410				STATE FEE			
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil &	Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or Unit Agreement Name North Anderson Ranch Unit 33			
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other				8. Well Number 3			
2. Name of Operator				9. OGRID Number 6137			
Devon Energy Production Company, LP 3. Address of Operator				10. Pool name or Wildcat			
20 North Broadway, Suite 1500, Oklahoma City, Oklahoma 73102				North Anderson Ranch Wolfcamp			
4. Well Location							
Unit Letter K : 1980' feet from the South line and 1980' feet from the West line							
Section 33 Township 15S Range 32E					ea County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4305' GL							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
					REPORT OF:	_	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORI	K L	ALTERING CASING		
TEMPORARILY ABANDON] CHANGE PLANS		COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT] PLUG AND ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB				
OTHER:			OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.							
1. MIRU. POOH w/2-7/8" tubing. Spot 35' cement on top of existing CIBP at 9822'. Circulate hole w/ 9.5 ppg sat 212 and							
 Spot 25 Sx cement at 6960'. Spot 25 Sx cement at 4202'. Tag TOC. Covers 9-5/8" casing shoe at 4152' WOCH TAGE 4102. Cut 5-1/2" casing at +/-3000'. POOH w/ casing. Spot 30 Sx cement for stub plug at 3050'. Tag TOC. 							
4. Cut 5-1/2" casing at +/-3000'. POOH w/ casing. Spot 30 Sx cement for stub plug at 3050'. Tag TOC.							
 2. Spot 25 Sx cement at 6960'. 3. Spot 25 Sx cement at 4202'. Tag TOC. Covers 9-5/8" casing shoe at 4152' WICH TAGE 4/02, 73, 97, 102, 102, 103, 102, 102, 102, 103, 103, 103, 103, 103, 103, 103, 103							
7. Spot 35 Sx cement at $1380 - 1480$. (Top of sait at 1480) 7. Spot 35 Sx cement at 655'. Tag TOC. Covers 13-3/8" casing shoe at 605'. We TAG @ 55							
 8. Spot 20 Sx cement for 60' surface plug 9. Cut casings off 3' below ground level. Set P&A marker. Clean location. 							
	d level. Bet i dell'i market.				1016810CHE1	/	
I hereby certify that the information	above is true and comple	ete to the be	est of my knowledge	e and belief.			
SIGNATURE Konnie D.	SlackTIT	LE: Engir	neering Technician	D	ATE_4/17/07		
Type or print name Ronnie G. Sla	ck E-mail addres	ss: Ronnie.	Slack@dvn.com	Teleph	one No. 405-552-4615		
(This space for State use)	1.1.1						
APPPROVED BY Lange OCHEED REPRESENTATIVE II/STAFF MANAGES APR 2 2007							
Conditions of approval, if any:							
			1				
THE OIL CONSERVATION DIVICION OF BE NOTIFIED 24 HOURS PRIOR TO THE							
BEGINNING OF PLUGGING OPERATIONS.							



