Form 3160-5 (April 2004)

## DEPARTMENT OF THE INTERIOR OCD-HORBS BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

for proposels to drill or to re-enter an

GWW

(Instructions on page 2)

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

5.	Lease Serial	No.
	NIM_23	an

6.	Ħ	Indian,	Allottee	or Trit	e Name
----	---	---------	----------	---------	--------

abandoned well. Use Form 3160-3 (	APD) for such pro	posais.				
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Gas Well Other  2. Name of Operator Mar Oil and Gas Corp				8. Well Name and No. TP Federal # 1 9. API Well No.		
3a. Address 3b. Phone 3ct 3b. Phone 3ct		le area code)	30-025-24278  10. Field and Pool, or Exploratory Area  West Sawyer, SA  11. County or Parish, State			
Section 22, T9S, R37E	29 20 20 20 20 20 20 20 20 20 20 20 20 20	[3]	Lea/Ni			
12. CHECK APPROPRIATE BOX(ES) TYPE OF SUPPRISSION	INDIGAÇE MATUI	RE OF NOTICE, RE	PORT, OR	OTHER DATA		
TYPE OF SUBMISSION  Acidize  Acidize  Alter Casing  Casing Repair  Change Plans  Final Abandonment Notice  Convert to Injection	Deepen Fracture Treat Siew Construction Plug and Abandon Plug Back	Production (Star Reclamation Recomplete Temporarily Aba Water Disposal		Water Shut-Off Well Integrity Other		
13. Describe Proposed or Completed Operation (clearly state all per If the proposal is to deepen directionally or recomplete horizonta Attach the Bond under which the work will be performed or pro following completion of the involved operations. If the operation testing has been completed. Final Abandonment Notices shall be determined that the site is ready for final inspection.)  No pits will constructed during plugging operation 8 5/8" 20# Casing set at 431ft X Cmt w/ 375sx cmt 4 ½",10.5# Casing set at 5100ft X Cmt w/ 250sx cmt Perfs 4978-5018ft X TS 2315ft X BS 2790ft MISU X NU BOP Run and set CIBP at 4925ft X Displace well with ge Spot 25sx cmt plug Pull tbg X perf casing at 2840ft Run packer X Set packer at 2100ft X Squeeze perfs Tag plug X Pull tbg X Perf casing at 2365ft Run packer X Set packer at 2000ft X Squeeze perfs Tag plug X Pull tbg X Perf casing at 481ft	alty, give subsurface location de the Bond No. on file in results in a multiple come filed only after all requires X Notify BLM when X Cmt circulated at the lelled brine water is with 50 sx cmt X Work with 50 sx cmt X Wo	with BLM/BIA. Require upletion or recompletion in ements, including reclamant plugging operation.	d subsequent r a new interva ation, have bee	eports shall be filed within 30 days al, a Form 3160-4 shall be filed once on completed, and the operator has		
Circulate cement to surface Estimated at 100sx cr Cut off well head and install PA marker RD MOSU X Cut off SU anchors X Clean and level			PERSON	and the second of the second o		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Billy E. Prichard	Title	Foreman				
Signature Billy E. Trubu	Date	4/12/0	7			
THIS SPACE FOR	R FEDERAL OR	STATE OFFICE	USE			
Approved by  Conditions of approval, if any, are attached. Approval of this not certify that the applicant holds legal or equitable title to those righ which would entitle the applicant to conduct operations thereon.	ts in the subject lease	Office		Date		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make States any false, fictitious or fraudulent statements or representation	it a crime for any person ons as to any matter within	knowingly and willfully its jurisdiction.	to make to a	ny ocpariment or agency of the Officea		