0.00	State	of New Me	exico		Form C-103
Office District I	Energy, Miner	rals and Natu	ral Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	
District II	OIL CONGI	DVATION	DIVISION	30-02	25-37628
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type of	Lease
District III	1220 South St. Francis Dr.		STATE 🔯	FEE 🗌	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Sant	a Fe, NM 87	7505	6. State Oil & Gas I	Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		112	15 14 10 10		
87505		10,			
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLIPROPOSALS.) 1. Type of Well: Oil Well	ICES AND REPORT	S OXYWELLS	ু 🗗 🗽	7. Lease Name or U	Init Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO	DEEREN OR PL	GBACK TO A		
DIFFERENT RESERVOIR. USE "APPLI	CATION FOR PERMIT" (FORM C-101	R'SUCHI 12		BIG State
1. Type of Well: Oil Well	Gos Well Cother	. Tite. A	Ceiver R	8. Well Number	
1. Type of Wen. On Wen	Gas Well Oulci	The state of the s	lopps of		1
2. Name of Operator		187		9. OGRID Number	
Yates Petroleum Corporat	ion		.db/	ì	25575
3. Address of Operator	1011	1608	6207179	10. Pool name or W	
105 S. 4 th Street, Artesia,	NM 88210	-	90800	ł.	e; Abo
	14141 00210			Dan	
4. Well Location					
Unit Letter L:	1980 feet from the	e South	n line and	660 feet from th	ne <u>West</u> line
Section 1	Township	10S Rai	nge 33E	NMPM Lea	County
Section			, RKB, RT, GR, etc.)		county
	11. Elevation (Sno	<i>w whether DR</i> , 4238'	•		
Pit or Below-grade Tank Application	or Closure	4236	GK		
Pit type Depth to Groundwat	er Distance fron	n nearest fresh w	ater well Dis	tance from nearest surfac	e water
Pit Liner Thickness: mil	Below-Grade Tank	: Volume	bbls; Co	nstruction Material	
10 01 1	D	7 1' 4 N	CNT 4	D 4 OdD	
12. Check	Appropriate Box to	o indicate N	ature of Notice,	Report or Other D	ata
NOTICE OF I	ITENITION TO		i cun	OFOLIENT DED	ODT OF:
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK			REMEDIAL WOR		LTERING CASING 🔲
TEMPORARILY ABANDON 🗌	CHANGE PLANS		COMMENCE DRI	LLING OPNS.□ P	AND A
PULL OR ALTER CASING	MULTIPLE COMPI	L 🔲	CASING/CEMENT	ΓJOB □	
PULL OR ALTER CASING					
PULL OR ALTER CASING					
OTHER:			OTHER:		
OTHER: 13. Describe proposed or com	pleted operations. (Cl		pertinent details, and		
OTHER:	pleted operations. (Cl		pertinent details, and		
OTHER: 13. Describe proposed or compost of starting any proposed w	pleted operations. (Cl		pertinent details, and le Completions: At	tach wellbore diagram	of proposed completion
OTHER: 13. Describe proposed or com	pleted operations. (Cl		pertinent details, and le Completions: At App	tach wellbore diagram proved as to pluggin	of proposed completion g of the Well Bore.
OTHER: 13. Describe proposed or compost of starting any proposed w	pleted operations. (Cl		pertinent details, and le Completions: At App Liak	tach wellbore diagram proved as to pluggin pility under bond is	of proposed completion g of the Well Bore. retained until
OTHER: 13. Describe proposed or composed was of starting any proposed was or recompletion.	pleted operations. (Clork). SEE RULE 110	3. For Multip	pertinent details, and le Completions: At App Liak	tach wellbore diagram proved as to pluggin	of proposed completion g of the Well Bore. retained until
OTHER: 13. Describe proposed or composed or starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V	pleted operations. (Clork). SEE RULE 110	3. For Multip H w/tubing.	pertinent details, and le Completions: At App Liak	tach wellbore diagram proved as to pluggin pility under bond is	of proposed completion g of the Well Bore. retained until
OTHER: 13. Describe proposed or composed or composed was or recompletion. 5-4-07 MIRU all equipment. ND V. 5-7-07 Set CIBP @ 8800'. Dump	pleted operations. (Clork). SEE RULE 110 WH. NU BOP. POOI 35' of cement on plug	3. For Multip H w/tubing.	pertinent details, and le Completions: At App Liak surf	tach wellbore diagram proved as to plugging pility under bond is face restoration is co	of proposed completion g of the Well Bore. retained until ompleted.
OTHER: 13. Describe proposed or composed or composed was or recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated	pleted operations. (Clork). SEE RULE 110 WH. NU BOP. POOl 35' of cement on plug	H w/tubing. Spot 25 sx (pertinent details, and le Completions: At App Lial surf	tach wellbore diagram proved as to plugging pility under bond is ace restoration is \$\pi\$ 253' and spot 25 sx. (1)	of proposed completion g of the Well Bore. retained until ompleted. Circulated plugging mud.
OTHER: 13. Describe proposed or composed was or recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'.	pleted operations. (Clork). SEE RULE 110 WH. NU BOP. POOl 35' of cement on plug	H w/tubing. Spot 25 sx (pertinent details, and le Completions: At App Lial surf	tach wellbore diagram proved as to plugging pility under bond is ace restoration is \$\pi\$ 253' and spot 25 sx. (1)	of proposed completion g of the Well Bore. retained until ompleted. Circulated plugging mud.
OTHER: 13. Describe proposed or compost of starting any proposed was or recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC.	wh. NU BOP. POOl 15° of cement on plug 16° hole w/plugging much 26° Perforate squeeze holes.	H w/tubing. Spot 25 sx (les @ 2098'. I	pertinent details, and le Completions: At App Liak surf	tach wellbore diagram proved as to plugging pility under bond is face restoration is \$20.053' and spot 25 sx. \$1.1000#. POOH. RIH	of proposed completion g of the Well Bore. retained until ompleted. Circulated plugging mud. open-ended and spot 25
OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'.	wh. NU BOP. POOI hole w/plugging much Perforate squeeze hole POOH. RIH and spo	H w/tubing. Spot 25 sx (les @ 2098'. I	pertinent details, and le Completions: At App Liak surf	tach wellbore diagram proved as to plugging pility under bond is face restoration is \$20.053' and spot 25 sx. \$1.1000#. POOH. RIH	of proposed completion g of the Well Bore. retained until ompleted. Circulated plugging mud. open-ended and spot 25
OTHER: 13. Describe proposed or compost of starting any proposed was or recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC.	wh. NU BOP. POOI hole w/plugging much Perforate squeeze hole POOH. RIH and spo	H w/tubing. Spot 25 sx (les @ 2098'. I	pertinent details, and le Completions: At App Lial surf	tach wellbore diagram proved as to plugging pility under bond is face restoration is \$20.053' and spot 25 sx. \$1.1000#. POOH. RIH	of proposed completion g of the Well Bore. retained until ompleted. Circulated plugging mud. open-ended and spot 25
OTHER: 13. Describe proposed or compost of starting any proposed we or recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'.	wh. NU BOP. POOI hole w/plugging much Perforate squeeze hole POOH. RIH and spo	H w/tubing. Spot 25 sx (les @ 2098'. I	pertinent details, and le Completions: At App Lial surf	tach wellbore diagram proved as to plugging pility under bond is face restoration is \$20.053' and spot 25 sx. \$1.1000#. POOH. RIH	of proposed completion g of the Well Bore. retained until ompleted. Circulated plugging mud. open-ended and spot 25
OTHER: 13. Describe proposed or composed of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and	wh. NU BOP. POOl hole w/plugging much Perforate squeeze hole POOH. RIH and spot cleaned location.	H w/tubing. I. Spot 25 sx (des @ 2098'. It	pertinent details, and le Completions: At App Liak surf	tach wellbore diagram proved as to plugging pility under bond is face restoration is co 053' and spot 25 sx. Of 1 1000#. POOH. RIH 10' and circulated 15 st	of proposed completion g of the Well Bore. retained until ompleted. Circulated plugging mud. open-ended and spot 25
OTHER: 13. Describe proposed or composed of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and	wh. NU BOP. POOI hole w/plugging much Perforate squeeze hole POOH. RIH and spo	H w/tubing. I. Spot 25 sx (des @ 2098'. It	pertinent details, and le Completions: At App Liak surf	tach wellbore diagram proved as to plugging pility under bond is face restoration is co 053' and spot 25 sx. Of 1 1000#. POOH. RIH 10' and circulated 15 st	of proposed completion g of the Well Bore. retained until ompleted. Circulated plugging mud. open-ended and spot 25
OTHER: 13. Describe proposed or composed of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and	wh. NU BOP. POOl hole w/plugging much Perforate squeeze hole POOH. RIH and spot cleaned location.	H w/tubing. I. Spot 25 sx (des @ 2098'. It	pertinent details, and le Completions: At App Liak surf	tach wellbore diagram proved as to plugging pility under bond is face restoration is co 053' and spot 25 sx. Of 1 1000#. POOH. RIH 10' and circulated 15 st	of proposed completion g of the Well Bore. retained until ompleted. Circulated plugging mud. open-ended and spot 25
OTHER: 13. Describe proposed or composed of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and	wh. NU BOP. POOl of the property of the proper	H w/tubing. I. Spot 25 sx (des @ 2098'. It 25 sx @ 452	pertinent details, and le Completions: At App Liak surf @ 6814'. PUH to 40 RIH w/packer. Held'. POOH. RIH to 60 NDONED. FINAL	tach wellbore diagram proved as to plugging polity under bond is cace restoration is can be also be a second of the case of th	of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. copen-ended and spot 25 x to surface. Cut off
OTHER: 13. Describe proposed or composed was of starting any proposed was or recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and I hereby certify that the information	WH. NU BOP. POOl hole w/plugging much perforate squeeze hole pool. RIH and spot cleaned location.	H w/tubing. I. Spot 25 sx (des @ 2098'. It 25 sx @ 452 D AND ABAM	pertinent details, and le Completions: At App Liak surf @ 6814'. PUH to 40 RIH w/packer. Held'. POOH. RIH to 60 NDONED. FINAL est of my knowledge	tach wellbore diagram proved as to plugging polity under bond is cace restoration is can be also be al	of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. copen-ended and spot 25 x to surface. Cut off
OTHER: 13. Describe proposed or composed of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and	WH. NU BOP. POOl hole w/plugging much perforate squeeze hole pool. RIH and spot cleaned location.	H w/tubing. I. Spot 25 sx (des @ 2098'. It 25 sx @ 452 D AND ABAM	pertinent details, and le Completions: At App Liak surf @ 6814'. PUH to 40 RIH w/packer. Held'. POOH. RIH to 60 NDONED. FINAL est of my knowledge	tach wellbore diagram proved as to plugging polity under bond is cace restoration is can be also be al	of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. copen-ended and spot 25 x to surface. Cut off
OTHER: 13. Describe proposed or composed of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and I hereby certify that the information grade tank has been/will be constructed of O A	WH. NU BOP. POOl hole w/plugging much perforate squeeze hole pool. RIH and spot cleaned location.	H w/tubing. I. Spot 25 sx (des @ 2098'. If t 25 sx @ 452 D AND ABAN Inplete to the beoch guidelines [pertinent details, and le Completions: At App Liak surf @ 6814'. PUH to 40 RIH w/packer. Held'. POOH. RIH to 60 NDONED. FINAL est of my knowledge , a general permit	tach wellbore diagrams broved as to plugging bility under bond is cace restoration is can be a second of the secon	of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. open-ended and spot 25 ex to surface. Cut off retrify that any pit or below-ve OCD-approved plan
OTHER: 13. Describe proposed or composed was of starting any proposed was or recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and I hereby certify that the information	WH. NU BOP. POOl hole w/plugging much perforate squeeze hole pool. RIH and spot cleaned location.	H w/tubing. I. Spot 25 sx (des @ 2098'. If t 25 sx @ 452 D AND ABAN Inplete to the beoch guidelines [pertinent details, and le Completions: At App Liak surf @ 6814'. PUH to 40 RIH w/packer. Held'. POOH. RIH to 60 NDONED. FINAL est of my knowledge	tach wellbore diagrams broved as to plugging bility under bond is cace restoration is can be a second of the secon	of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. copen-ended and spot 25 x to surface. Cut off
OTHER: 13. Describe proposed or composed of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	WH. NU BOP. POOR Solution of the second of t	H w/tubing. I. Spot 25 sx (les @ 2098'. If t 25 sx @ 452 D AND ABAN The property of the book of the	pertinent details, and le Completions: At App Lial surf @ 6814'. PUH to 40 RIH w/packer. Held '. POOH. RIH to 60 NDONED. FINAL est of my knowledge a general permit Regulatory Complia	tach wellbore diagrams broved as to plugging bility under bond is cace restoration is cace restoration is call 1000#. POOH. RIH 0' and circulated 15 st. REPORT. The and belief. I further cor an (attached) alternation is call to the call the cal	of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. copen-ended and spot 25 ex to surface. Cut off retrify that any pit or belowive OCD-approved plan . DATE5-15-07
OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Stormi D.	WH. NU BOP. POOR Solution of the second of t	H w/tubing. I. Spot 25 sx (des @ 2098'. If t 25 sx @ 452 D AND ABAN Inplete to the beoch guidelines [pertinent details, and le Completions: At App Lial surf @ 6814'. PUH to 40 RIH w/packer. Held '. POOH. RIH to 60 NDONED. FINAL est of my knowledge a general permit Regulatory Complia	tach wellbore diagrams broved as to plugging bility under bond is cace restoration is cace restoration is call 1000#. POOH. RIH 0' and circulated 15 st. REPORT. The and belief. I further cor an (attached) alternation is call to the call the cal	of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. open-ended and spot 25 ex to surface. Cut off retrify that any pit or below-ve OCD-approved plan
OTHER: 13. Describe proposed or composed of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	WH. NU BOP. POOR Solution of the second of t	H w/tubing. I. Spot 25 sx (les @ 2098'. If t 25 sx @ 452 D AND ABAN The property of the book of the	pertinent details, and le Completions: At App Lial surf @ 6814'. PUH to 40 RIH w/packer. Held '. POOH. RIH to 60 NDONED. FINAL est of my knowledged, a general permit Regulatory Complia	tach wellbore diagrams broved as to plugging bility under bond is cace restoration is cace restoration is call 1000#. POOH. RIH 0° and circulated 15 statements of an (attached) alternation ince Technician Telephone N	core of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. open-ended and spot 25 ex to surface. Cut off retrify that any pit or below-ve OCD-approved plan . DATE 5-15-07 No. 505-748-1471
OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Stormi Difference of State Use Only	WH. NU BOP. POOR Solution of the second of t	H w/tubing. I. Spot 25 sx (les @ 2098'. If t 25 sx @ 452 D AND ABAN The property of the book of the	pertinent details, and le Completions: At App Lial surf @ 6814'. PUH to 40 RIH w/packer. Held '. POOH. RIH to 60 NDONED. FINAL est of my knowledged, a general permit Regulatory Complia	tach wellbore diagrams broved as to plugging bility under bond is cace restoration is cace restoration is call 1000#. POOH. RIH 0° and circulated 15 statements of an (attached) alternation ince Technician Telephone N	core of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. open-ended and spot 25 ex to surface. Cut off retrify that any pit or below-ve OCD-approved plan . DATE 5-15-07 No. 505-748-1471
OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Stormi Defor State Use Only APPROVED BY:	WH. NU BOP. POOR Solution of the second of t	H w/tubing. I. Spot 25 sx (les @ 2098'. If t 25 sx @ 452 D AND ABAN The property of the book of the	pertinent details, and le Completions: At App Lial surf @ 6814'. PUH to 40 RIH w/packer. Held '. POOH. RIH to 60 NDONED. FINAL est of my knowledged, a general permit Regulatory Complia	tach wellbore diagrams broved as to plugging bility under bond is ace restoration is accerstoration is accerstoration is accerstoration. Telephone Note to plugging bility under bond is accerstoration is accerstoration.	core of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. open-ended and spot 25 ex to surface. Cut off retrify that any pit or below-ve OCD-approved plan . DATE 5-15-07 No. 505-748-1471
OTHER: 13. Describe proposed or compost of starting any proposed wor recompletion. 5-4-07 MIRU all equipment. ND V 5-7-07 Set CIBP @ 8800'. Dump 5-9-07 RIH to 6814' and circulated 5-10-07 RIH and tagged @ 3500'. sx @ 2148'. POOH and WOC. 5-11-07 RIH and tagged @ 1969'. WH. Installed dry-hole marker and I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Stormi Difference of State Use Only	WH. NU BOP. POOR Solution of the second of t	H w/tubing. I. Spot 25 sx (les @ 2098'. If t 25 sx @ 452 D AND ABAN The property of the book of the	pertinent details, and le Completions: At App Lial surf @ 6814'. PUH to 40 RIH w/packer. Held '. POOH. RIH to 60 NDONED. FINAL est of my knowledged, a general permit Regulatory Complia	tach wellbore diagrams broved as to plugging bility under bond is cace restoration is cace restoration is call 1000#. POOH. RIH 0° and circulated 15 statements of an (attached) alternation ince Technician Telephone N	core of proposed completion g of the Well Bore. retained until completed. Circulated plugging mud. open-ended and spot 25 ex to surface. Cut off retrify that any pit or below-ve OCD-approved plan . DATE 5-15-07 No. 505-748-1471