i

007

			OCI	D-ARTES			
Do not use t	UNITED STAT DEPARTMENT OF THE BUREAU OF LAND MAN EXAMPLES AND REP his form for proposals t well, use Form 3160-3 (AF	INTERIOR JAGEMENT ORTS ON M		Month 21 MAY 3 200 MAY 3 OCO - WILESA		FORM API OMB No. 1 Empires Novem Serial No. iau, Allottee or	004-0135 ibar 30, 2000
	RPLICATE-Offer Inst					t or CA/Agreer	nent, Name and/or N
1. Type of Well							
2. Name of Operator	- Other		••••			Name and No. 18 – Fe	ederal #3
Pogo Producin	g Co.				9. API V		uerar _m j
3a. Address 3b. Phone No P.O. Box 10340, Midland, TX 432-6			No. (include area - 617-02(a code)	30-025-32324 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec					~	ngston	• •
480 FNL + 330		TNS 22	2, S		11. Count LE	y or Parish, Sta	te
Range 32 E - (GL 3632.4'					l y Co.	N.M.
12. CHECK AI	PPROPRIATE BOX(ES) 1	O INDICATI	E NATURE O	OF NOTICE, R	EPORT, O	R OTHER	DATA
TYPE OF SUBMISSION			ТУРЕ С	TYPE OF ACTION			
	Acidize	Deepen		Production (Star	t/Resume)	Water S	Shut-Off
Notice of Intent	Alter Casing	Fracture 7	_	Reclamation		Well in	tegrity
Subsequent Report	Casing Repair Change Plans	New Con		Recomplete Temporarily At	andon	U Other	<u>.</u>
Ginal Abandonment Notice	Convert to Injection	D Plug Back		Water Disposal			
Attach the Bond under which the following completion of the intresting has been completed. F determined that the site is ready		ally, give subsurf rovide the Bond I on results in a mu	face locations and No. on file with altiple completion	BLM/BIA. Requi a or recompletion	e vertical de red subseque in a new inte	pths of all pertint nt reports shall rval, a Form 3 been complete to the state of the state of the state been complete to the state of the state of the state of the state to the state of	nent markers and 20 be filed within 30 (
Attach the Bond under which the following completion of the invite testing has been completed for the site is ready 1. Tag CIBI 2. Circulat 3. Cap CIBI 4. Spot a 5. Spot a 6. Cut & pu 7. Spot 65 8. Spot 65 9. Spot 65 10. Spot 30	the work will be performed or pr volved operations. If the operational Abandonment Notices shall	ally, give subsur- rovide the Bond 1 on results in a me be filed only aff Salt S cement. 05' - 6 78' - 4 m Free n & 50 ' - 1.2 - 705' ug.	ace locations an No. on file with litiple completion er all requirement (105' I , 378' - Point. out of 50'.	d measured and the BLM/BIA. Require n or recompletion sts, including reck mud. DV Tool. 3 5/8" casing	stub,	pths of all pertint reports shall rival, a Porm 33 been complet CV 110 CV 110 Tag.	nent markers and 20 be filed within 30 (
Attach the Bond under which the following completion of the invite testing has been completed for the site is ready 1. Tag CIBI 2. Circulat 3. Cap CIBI 4. Spot a 5. Spot a 6. Cut & pu 7. Spot 65 8. Spot 65 9. Spot 65 10. Spot 30	the work will be performed or pr volved operations. If the operation for final inspection.) P at 7,978'. te hole w/ 10# P w/ 25 sx of 30 sx Plug 6,2 55 sx Plug 4,4 all casing fro sx Plug 50 i sx Plug 1,350 sx Plug 800' sx Surface Pl	ally, give subsur- rovide the Bond 1 on results in a me be filed only aff Salt S cement. 05' - 6 78' - 4 m Free n & 50 ' - 1.2 - 705' ug.	ace locations an No. on file with litiple completion er all requirement (105' I , 378' - Point. out of 50'.	d measured and the BLM/BIA. Require n or recompletion sts, including reck mud. DV Tool. 3 5/8" casing	stub,	pths of all pertint reports shall rival, a Porm 33 been complet CV 110 CV 110 Tag.	JUN 2007 Received Hobbs
Attach the Bond under which the following completion of the im- testing has been completed. F determined that the site is ready 1. Tag CIBI 2. Circulat 3. Cap CIBI 4. Spot a 5 5. Spot a 6 6. Cut & pt 7. Spot 65 8. Spot 65 9. Spot 65 10. Spot 30 11. Install	the work will be performed or pr volved operations. If the operation inal Abandonment Notices shall for final inspection.) P at 7,978'. te hole w/ 10# P w/ 25 sx of 30 sx Plug 6,2 55 sx Plug 6,2 55 sx Plug 4,4 all casing fro sx Plug 50 i sx Plug 1,350 sx Plug 800' sx Surface Pl Dry Hole Mark	ally, give subsur- rovide the Bond 1 on results in a me be filed only aff Salt S cement. 05' - 6 78' - 4 m Free n & 50 ' - 1.2 - 705' ug.	ace locations an No. on file with litiple completion er all requirement (105' I , 378' - Point. out of 50'.	d measured and the BLM/BIA. Require n or recompletion sts, including reck mud. DV Tool. 3 5/8" casing	stub,	pths of all pertint reports shall rival, a Porm 33 been complet CV 110 CV 110 Tag.	JUN 2007 Received Hobbs
Attach the Bond under which the following completion of the im- testing has been completed. F determined that the site is ready 1. Tag CIBI 2. Circulat 3. Cap CIBI 4. Spot a 5 5. Spot a 6 6. Cut & pu 7. Spot 65 8. Spot 65 9. Spot 65 10. Spot 30 11. Install	the work will be performed or pr volved operations. If the operation inal Abandonment Notices shall for final inspection.) P at 7,978'. te hole w/ 10# P w/ 25 sx of 30 sx Plug 6,2 55 sx Plug 6,2 55 sx Plug 4,4 all casing fro sx Plug 50 i sx Plug 1,350 sx Plug 800' sx Surface Pl Dry Hole Mark	ally, give subsur- rovide the Bond 1 on results in a me be filed only aff Salt S cement. 05' - 6 78' - 4 m Free n & 50 ' - 1.2 - 705' ug.	ace locations an. No. on file with liple completio. er all requirement alt Gel , 105' E , 378' - Point. out of 50'. - 13 3/	d measured and the BLM/BIA. Require n or recompletion sts, including reck mud. DV Tool. 3 5/8" casing	stub,	pths of all pertint reports shall rival, a Porm 33 been complet CV 110 CV 110 Tag.	JUN 2007 Received Hobbs
Attach the Bond under which the following completion of the im- testing has been completed. F determined that the site is ready 1. Tag CIBI 2. Circulat 3. Cap CIBI 4. Spot a 5 5. Spot a 6 6. Cut & pu 7. Spot 65 8. Spot 65 9. Spot 65 10. Spot 30 11. Install	the work will be performed or pr volved operations. If the operation inal Abandonment Notices shall for final inspection.) P at 7,978'. te hole w/ 10# P w/ 25 sx of 30 sx Plug 6,2 55 sx Plug 6,2 55 sx Plug 4,4 all casing fro sx Plug 50 i sx Plug 1,350 sx Plug 800' sx Surface Pl Dry Hole Mark	ally, give subsur- rovide the Bond 1 on results in a me be filed only aff Salt S cement. 05' - 6 78' - 4 m Free n & 50 ' - 1.2 - 705' ug.	Acc locations ann No. on file with Lipple completion or all requirement all Gel , 105' I , 378' - Point. Out of 50'. - 13 3/	d measured and m BLM/BIA. Requi nor recompletion its, including rech 	stub,	pths of all pertint reports shall rival, a Porm 33 been complet CV 110 CV 110 Tag.	JUN 2007 Received Hobbs
Attach the Bond under which it following completion of the im- testing has been completed. F determined that the site is ready 1. Tag CIBI 2. Circulat 3. Cap CIBI 4. Spot a C 5. Spot a C 6. Cut & pu 7. Spot 65 8. Spot 65 9. Spot 65 9. Spot 65 10. Spot 30 11. Install 14. I hereby certify that the foregoin Name (Printed/Typed)	the work will be performed or pr volved operations. If the operation inal Abandonment Notices shall for final inspection.) P at 7,978'. te hole w/ 10# P w/ 25 sx of 30 sx Plug 6,2 55 sx Plug 6,2 55 sx Plug 4,4 all casing fro sx Plug 50 i sx Plug 1,350 sx Plug 800' sx Surface Pl Dry Hole Mark	ally, give subsur voide the Bond 1 on results in a me be filed only aff Salt S cement. 05' - 6 78' - 4 m Free n & 50 ' - 1.2 - 705' ug. er.	Acc locations ann No. on file with Lipple completio er all requirement all C Gel , 105' I , 378' - Point. out of 50'. - 13 3/ Title Ag Date 5/2	d measured and m BLM/BIA. Require nor recompletion bits, including reck W Tool. W Tool. Casing Casing '8" Shoe	stub, , Tag.	pths of all pertint reports shall rival, a Porm 33 been complet CV 110 CV 110 Tag.	JUN 2007 Received Hobbs
Attach the Bond under which it following completion of the ini- testing has been completed. F determined that the site is ready 1. Tag CIBI 2. Circulat 3. Cap CIBI 4. Spot a 3 5. Spot a 6 6. Cut & pu 7. Spot 65 8. Spot 65 9. Spot 65 9. Spot 65 10. Spot 30 11. Install 14. I hereby certify that the foregoin Name (Printed/Typed) How	the work will be performed or pr volved operations. If the operation inal Abandonment Notices shall of or final inspection.) P at 7,978'. te hole w/ 10# P w/ 25 sx of 30 sx Plug 6,2 55 sx Plug 6,2 55 sx Plug 4,4 all casing fro sx Plug 50 i sx Plug 1,350 sx Plug 800' sx Surface Pl Dry Hole Mark	ally, give subsur voide the Bond 1 on results in a me be filed only aff Salt S cement. 05' - 6 78' - 4 m Free n & 50 ' - 1.2 - 705' ug. er.	Acc locations ann No. on file with Lipple completio. er all requirement all C Gel , 105' I , 378' - Point. out of 50'. - 13 3/ Title Ag Date 5/2	d measured and m BLM/BIA. Require nor recompletion its, including rech with the second second DV Tool. Casing (8" Shoe ent 2/07	stub, stub, stub, stub, stub,	priss of all pertin nt reports shall be been completed CV 100 Tag. Tag.	JUN 2007 Received Hobbs
Attach the Bond under which it following completion of the im- testing has been completed. F determined that the site is ready 1. Tag CIBI 2. Circulat 3. Cap CIBI 4. Spot a C 5. Spot a C 6. Cut & pu 7. Spot 65 8. Spot 65 9. Spot 65 9. Spot 65 10. Spot 30 11. Install 14. I hereby certify that the foregoin Name (Printed/Typed)	the work will be performed or pr volved operations. If the operation in al Abandonment Notices shall for final inspection.) P at 7,978'. te hole w/ 10# P w/ 25 sx of 30 sx Plug 6,2 55 sx Plug 4,4 all casing fro sx Plug 50 i sx Plug 1,350 sx Plug 800' sx Surface Pl Dry Hole Mark mg is true and correct vard Boatright	ally, give subsur voide the Bond 1 on results in a me be filed only aff Salt S cement. 05' - 6 78' - 4 m Free n & 50 ' - 1.2 - 705' ug. er. Comparison Comparis	Acc locations ann. No. on file with liple completio. cr all requirement alt Gel , 105' E , 378' - Point. out of 50'. - 13 3/ Title Ag Date 5/2 Completion Title Ag	d measured and m BLM/BIA. Require nor recompletion its, including rech with the second second DV Tool. Casing (8" Shoe ent 2/07	stub, stub, stub, stub, stub,	pths of all pertint reports shall rival, a Porm 33 been complet CV 110 CV 110 Tag.	JUN 2007 Received Hobbs
Attach the Bond under which the following completion of the important string has been completed. Factor and the site is ready 1. Tag CIBI 2. Circulat 3. Cap CIBI 4. Spot a 5. Spot a 5. Spot a 5. Spot a 6. Cut & pt 7. Spot 65 8. Spot 65 9. Spot 65 9. Spot 65 10. Spot 30 11. Install 14. I hereby certify that the foregoin Name (Printed/Typed) How Signature Approved by Conditions of approval, if any, are certify that the splicant bolds leg	the work will be performed or pr volved operations. If the operation in al Abandomment Notices shall for final inspection.) P at 7,978'. te hole w/ 10# P w/ 25 sx of 30 sx Plug 6,2 55 sx Plug 4,4 all casing fro sx Plug 50 i sx Plug 1,350 sx Plug 800' sx Surface Pl Dry Hole Mark mg is true and correct vard Boatright	ally, give subsur voide the Bond 1 on results in a me be filed only aff Salt S cement. 05' - 6 78' - 4 m Free n & 50 ' - 1.2 - 705' ug. er. Com FEDERS ice does not warn hts in the subject	Acc locations ann. No. on file with liple completio. cr all requirement alt Gel , 105' II , 378' - Point. out of 50'. - 13 3/ Title Ag Date 5/2 Completion Title Title Title Completion Completi	d measured and m BLM/BIA. Requi nor recompletion its, including rech - g 5/8" - g 5/8" - casing '8" Shoe ent 2/07	stub, , Tag.	prits of all pertin nt reports shall be been completed Tag. Tag. Tag.	nent markers and zo be filed vining and file of the second second second states and jun 2007 Received Hobbs OCD

