Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

9. Pool name or Wildcat EUNICE 7 RUVERS QUEEN SO. 4. Well Location Unit Letter 0 : 660 Feet From The SOUTH Line and 1650 Feet From The EAST Line Section 21 Township 22S Range 36E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB		OTT CONTORDATA	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
DISTRICTI PSO Driver DD, Artesia, NM 8210 SINDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A OFFERENT RESERVOIR, USE 'REPUBLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A OFFERENT RESERVOIR, USE 'REPUBLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A OFFERENT RESERVOIR, USE 'REPUBLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS TO THER INJECTION 1. Type of Well: WELL OTHER INJECTION 2. Name of Operator SERCK OPERATING, CORP. 3. Address of Operator BERCK OPERATING, CORP. 3. Address of Operator Unit Letter O: 660 Feet From The SOUTH Line and 1650 Feet From The EAST Line Section 21 Township 225 Range 36E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB DITHER: 12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proword) SEE RULE 1103. 8. 22: 0.3 PERF & SQUEEZE @ 358 25 SKS W.O.C. & TAG @ 1556 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 1556 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEEZE & 1724 ' 35 KSS W.O.C. & TAG @ 156 PERF & SQUEE				
DISTRICTIII 1000 Ris Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (IDO NOT USE THIS FORM POR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS T. Type of Welt (IDI				
SUNDRY NOTICES AND REPORTS ON WELLS Go Not Use This Form Proposals to Deflet On the Dependence of Different Preservoir, use APPLICATION FOR PENMIT! GORAC -101) FOR SUCH PROPOSALS	P.O. Drawer DD, Artesia, NM 88210	-		5. Indicate Type of Lease STATE FFF X
CDO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: (Fig. 1)	SUNDRY NOT	FICES AND REPORTS OF	N WELLS	
2. Name of Operator BRECK OPERATING CORP. 3. Address of Operator P. O. BOX 911 BRECKERRIDGE TEXAS 76424 4. Well Location Unit Letter 0: 660 Feet From The SOUTH Line and 1650 Feet From The EAST Line Section 21 Township 22S Range 36E NMPM LEA COUNTY 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SPERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB DITHER: 12. Describe Proposed or Completed Operations Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proworks) SEE RULE 1103. 8-21-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 1556 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 SPERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 1	DIFFERENT RESE (FORM C-	RVOIR. USE "APPLICATION FO		7. Lease Name or Unit Agreement Name
BRECK OPERATING CORP. 3 Address of Operators 9. Pool name or Wildcat EUNICE 7 RUVERS QUEEN SO. 4. Well Location Unit Letter 0 : 660 Feet From The SOUTH Line and 1650 Feet From The EAST Line Schion 21 Township 22S Range 36E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DITHER: DI	1. Type of Well: OIL GAS WELL WELL	OTHER INC	DECTION	
4. Well Location Unit Letter 0: 660 Feet From The SOUTH Line and 1650 Feet From The EAST Line Section 21 Township 22S Range 36E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations/Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prowords SEE RULE 1103. 8-21-03 CIBP @ 3500 W / 25 SKS ONTOP SPOT 25 SKS 3050' W. O. C. & TAG @ 2900 8-22-03 PERF & SQUEEZE @ 1724' 35 SKS W. O. C. & TAG @ 1556 PERF \$ SQUEEZE @ 3590' SS SK W. O. C. & TAG @ 162 SPOT 10 SKS 60' SURFACE NSTALL P & A MARKER CIRC MUD Thereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE CEMENTER DATE 8-25-03	2. Name of Operator BRECK OPERATING CORP.			
4. Well Location Unit Letter 0 : 660 Feet From The SOUTH Line and 1650 Feet From The EAST Line Section 21 Township 225 Range 36E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations/Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prowork) SEE RULE 1103. 8-21-03 CIBP @ 3500 W / 25 SKS ONTOP SPOT 25 SKS 3050 W.O.C. & TAG @ 2900 8-22-03 PERF & SQUEEZE @ 1724 ' 35 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290 ' 25 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290 ' 25 SKS W.O.C. & TAG @ 162 Approved as to plugging of the Well Bore. Liability under bond is retained until gurface restoration is completed. Thereby certify that the information above is true and complete to the best of my knowledge and belief. Thereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE CEMENTER DATE 36E DATE ASSOCIATION DATE 36E-300 BEST ON TOWN AND THE STAND CEMENTER DATE 36E-300 BEST ON TOWN AND THE STAND CEMENTER DATE 36E-300 BEST ON TOWN AND THE STAND CEMENTER DATE 36E-300 BEST ON TOWN AND THE STAND CEMENTER DATE 36E-300 BEST ON TOWN AND THE STAND CEMENT AND THE STAND CEMENT BEST OF THE S	3. Address of Operator			9. Pool name or Wildcat
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operation Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prowork) SEE RULE 1103. 8-21-03 CIBP @ 3500 W/ 25 SKS ONTOP SPOT 25 SKS W.O.C. & TAG @ 2900 8-22-03 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 1556 PERF \$ SQUEEZE @ 358 25 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 Approved as to plugging of the Well Bore. Liability under bond is retained until aurface restoration is completed. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE ATTILE CEMENTER BATE 8-25-03	4. Well Location		TU 101	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JO	Unit Letter U : 660	Feet From TheSUUI	Line and 16	Feet From The <u>EAS1</u> Line
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: DERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CHANGE SER FULLE 1103. 8-21-03 CIBP @ 3500 W/ 25 SKS ONTOP SPOT 25 SKS 3050' W.O.C. & TAG @ 2900 8-22-03 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 300 8-22-03 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 NSTALL P & A MARKER CIRC MUD Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE CEMENTER DATE 8-25-03	Section 21	Township 22S	Range 36E	NMPM LEA County
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT OTHER: 12. Describe Proposed or Completed Operations Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prowork SEE RULE 1103. 8-21-03 CIBP @ 3500 W/ 25 SKS ONTOP SPOT 25 SKS W.O.C. & TAG @ 1556 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 1556 PERF & SQUEEZE @ 358 25 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 SPOT 10 SKS 60'-SURFACE SPOT 10 SKS 60'-SURFACE Liability under bond is retained until surface restoration is completed. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE CEMENTER DATE 8-25-03		10. Elevation (Show v	vhether DF, RKB, RT, GR, etc	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT OTHER: 12. Describe Proposed or Completed Operations Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prowork SEE RULE 1103. 8-21-03 CIBP @ 3500 W/ 25 SKS ONTOP SPOT 25 SKS W.O.C. & TAG @ 1556 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 1556 PERF & SQUEEZE @ 358 25 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 SPOT 10 SKS 60'-SURFACE SPOT 10 SKS 60'-SURFACE Liability under bond is retained until surface restoration is completed. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE CEMENTER DATE 8-25-03	11. Check At	opropriate Box to Indi	icate Nature of Noti	ce. Report, or Other Data
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operation Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prowork) SEE RULE 1103. 8 - 21 - 03 CIBP @ 3500 W/ 25 SKS ONTOP SPOT 25 SKS W.O.C. & TAG @ 2900 8 - 22 - 03 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 1556 PERF & SQUEEZE @ 358 25 SKS W.O.C. & TAG @ 300 8 - 25 - 03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 SPOT 10 SKS 60' -SURFACE SPOT 10 SKS 60' -SURFACE Liability under bond is retained until surface restoration is completed. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE CEMENTER DATE 8 - 25 - 03	-	· • •		•
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prowork) SEE RULE 1103. 8-21-03 CIBP @ 3500 W/ 25 SKS ONTOP SPOT 25 SKS 3050' W.O.C. & TAG @ 2900 8-22-03 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 1556 PERF \$ SQUEEZE @ 358 25 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 SPOT 10 SKS 60' SURFACE NSTALL P & A MARKER CIRC MUD Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE CEMENTER DATE 8-25-03		Г	-	
CASING TEST AND CEMENT JOB OTHER: OT	PERFORM REMEDIAL WORK	PLUG AND ABANDON L	☐ REMEDIAL WORK	☐ ALTERING CASING ☐
DTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prowork) SEE RULE 1103. 8 · 21 · 03 CIBP @ 3500 W/ 25 SKS ONTOP SPOT 25 SKS 3050' W.O.C. & TAG @ 2900 8 · 22 · 03 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 1556 PERF \$ SQUEEZE @ 358 25 SKS W.O.C. & TAG @ 300 8 · 25 · 03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 SPOT 10 SKS 60' SURFACE NSTALL P & A MARKER CIRC MUD Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE CEMENTER DATE 8 · 25 · 03	TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. U PLUG AND ABANDONMENT
12. Describe Proposed or Completed Operations Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prowork) 8-21-03 CIBP @ 3500 W/ 25 SKS ONTOP SPOT 25 SKS 3050' W.O.C. & TAG @ 2900 8-22-03 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 1556 PERF \$ SQUEEZE @ 358 25 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 SPOT 10 SKS 60'-SURFACE NSTALL P & A MARKER CIRC MUD Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE CEMENTER DATE 8-25-03	PULL OR ALTER CASING		CASING TEST AND CE	EMENT JOB L
8-21-03 CIBP @ 3500 W/ 25 SKS ONTOP SPOT 25 SKS 3050' W.O.C. & TAG @ 2900 8-22-03 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 1556 PERF \$ SQUEEZE @ 358 25 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 SPOT 10 SKS 60'-SURFACE NSTALL P & A MARKER CIRC MUD Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE CEMENTER DATE 8-25-03	OTHER:		OTHER:	
CIBP @ 3500 W/ 25 SKS ONTOP SPOT 25 SKS 3050' W.O.C. & TAG @ 2900 8-22-03 PERF & SQUEEZE @ 1724' 35 SKS W.O.C. & TAG @ 1556 PERF \$ SQUEEZE @ 358 25 SKS W.O.C. & TAG @ 300 8-25-03 PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 SPOT 10 SKS 60'-SURFACE NSTALL P & A MARKER CIRC MUD Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE CEMENTER DATE 8-25-03	12. Describe Proposed or Completed O work) SEE RULE 1103.	peration \$Clearly state all pertine	nt details, and give pertinent	
PERF & SQUEEZE @ 290' 25 SKS W.O.C. & TAG @ 162 SPOT 10 SKS 60'-SURFACE NSTALL P & A MARKER CIRC MUD Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE CEMENTER DATE 8-25-03			<i>B</i> • F • · · · · · · · · · · · · · · · · ·	dates, including estimated date of starting any pro
SIGNATURE TITLE CEMENTER DATE 8-25-03	CIBP @ 3500 W/ 25 SKS ON SPOT 25 SKS 3050' W.O.C. 8-22-03 PERF & SQUEEZE @ 1724' 3 PERF \$ SQUEEZE @ 358 25	& TAG @ 2900 5 SKS W.O.C. & TAG @ 15		dates, including estimated date of starting any pro
SIGNATURE TITLE CEMENTER DATE 8-25-03	CIBP @ 3500 W/ 25 SKS ON SPOT 25 SKS 3050' W.O.C. 8-22-03 PERF & SQUEEZE @ 1724' 3 PERF \$ SQUEEZE @ 358 25 8-25-03 PERF & SQUEEZE @ 290' 25 SPOT 10 SKS 60'-SURFACE NSTALL P & A MARKER	& TAG @ 2900 35 SKS W.O.C. & TAG @ 15 SKS W.O.C. & TAG @ 300	56 Approved as to pluggir Liability under bond is	ng of the Well Bore. retained until
1900 PRINT NAME JEFF KESTER TELEPHONE NO. 132-517-2026	CIBP @ 3500 W/ 25 SKS ON SPOT 25 SKS 3050' W.O.C. 8-22-03 PERF & SQUEEZE @ 1724' 3 PERF \$ SQUEEZE @ 358 25 8-25-03 PERF & SQUEEZE @ 290' 25 SPOT 10 SKS 60'-SURFACE NSTALL P & A MARKER CIRC MUD	& TAG @ 2900 35 SKS W.O.C. & TAG @ 15 SKS W.O.C. & TAG @ 300 5 SKS W.O.C. & TAG @ 162	Approved as to pluggir Liability under bond is surface restoration is c	ng of the Well Bore.
	CIBP @ 3500 W/ 25 SKS ON SPOT 25 SKS 3050' W.O.C. 8-22-03 PERF & SQUEEZE @ 1724' 3 PERF \$ SQUEEZE @ 358 25 8-25-03 PERF & SQUEEZE @ 290' 25 SPOT 10 SKS 60'-SURFACE NSTALL P & A MARKER CIRC MUD	& TAG @ 2900 35 SKS W.O.C. & TAG @ 15 SKS W.O.C. & TAG @ 300 5 SKS W.O.C. & TAG @ 162	Approved as to pluggir Liability under bond is surface restoration is o	ng of the Well Bore. retained until completed.