| Submit 3 Copies To Appropriate District   | State of New Mexi   |  | Form C-103  |
|---|---|--|---|
| Office<br><u>District I</u>   | Energy, Minerals and Natura   | I Resources                                    | March 4, 2004<br>ELL API NO.  |
| 1625 N. French Dr., Hobbs, NM 88240<br>District II  |   | 1  | 30-025-28609  |
| 1301 W. Grand Ave., Artesia, NM 88210   | OIL CONSERVATION DIVISION   |  | Indicate Type of Lease  |
| District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Azzec, NM 87410 South St. Francis Dr.  |   | IS Dr.   | STATE TEE   |
| District IV   | Santa Fe, NM 875  | 05 6.  | State Oil & Gas Lease No.   |
| 1220 S. St. Francis Dr., Santa Fe, NM<br>87505  |   |  | V-0732  |
| SUNDRY NOTIC  | ES AND REPORTS ON WELLS   |  | Lease Name or Unit Agreement Name   |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH   |   | SUCH   | N.M. ST. D.L.   |
| PROPOSALS.)   |   | 8.   | Well Number   |
| 1. Type of Well: Oil Well 🔼 . Gas Well 🗌 Other  |   |  | 4 .   |
| 2 Name of Operator  |   | 9.   | OGRID Number  |
| PRONGHORN MANAGEMENT CORPORATION  |   | ON   | 122811  |
| 3. Address of Operator P. O. BO   | X 1772 HOBBS, NM 882  |  | Pool name or Wildcat CRUZ DELAWARE  |
| 4. Well Location  |   |  |   |
| 3   | 330 feet from the South   | line and                                       | feet from theline   |
| 10  | Township 23S Rang   | 33E NO   | MPM County LEA  |
| Section 10  | 11. Elevation (Show whether DR, R   |  | VIFIN County 11111  |
|   | 3701' GR  | 7  |   |
| Pit or Below-grade Tank Application (For  | nit or below-grade tank closures, a form C-                                 | -144 must be attached)                         |   |
| Pit Location: ULSectTwp   | RngPit typeDept   | h to Groundwater                               | Distance from nearest fresh water well  |
| Distance from nearest surface water   | Below-grade Tank Location UL  | SectTwp  | _Rng;   |
| feet from theline and   | feet from theline ,   |  |   |
| NOTICE OF INT   | PLUG AND ABANDON  |  | QUENT REPORT OF:  ALTERING CASING  GOPNS. PLUG AND  ABANDONMENT                     |
| POLE ON ALTER CASING [  |   | CEMENT JOB                                     |   |
| OTHER:  |   | OTHER:   | 2345670   |
| <ol> <li>Describe proposed or comple<br/>of starting any proposed work<br/>or recompletion.</li> </ol>  | ted operations. (Clearly state all per<br>c). SEE RULE 1103. For Multiple ( | tinent details, and giv<br>Completions: Attach | e pertinent dates, including estimated date wellbore diagram of proposed completion |
| hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan []. |   |  |   |
| and talk has decident de constructed of cit   |   |  | (attached) alternative OCD-approved plan ∐.   |
| SIGNATURE JANAUW  | TITLE P   | RESIDENT                                       | DATE7/18/07   |
| Type or print name  |   |  |   |
| ypo or print indice   | E-mail addre  | <u> </u>                                       | Telephone No.   |
| This space for State use)   | 1/1 l   |  |   |
|   | E-mail addre  |  | Telephone No.  BUSTAFF MARAGES  |

- 1. Move in and rig up. POOH with rods and pump.
- 2. Swab well. Check for production and fluid level.
- 3. Install B.O.P. POOH with tubing.
- 4. Perforate additional pay in Ramsey Sand.
- 5. TIH with frac tubing and packer.
- 6. Rig up BJ. Frac well.
- 7. Flow and swab test well.
- 8. Put well on production.
- 9. Clean location. Rig down. Move out.