

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <u>025</u> <u>80-252-21868</u>
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <u>Injector</u>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <u>Merit Energy</u>		6. State Oil & Gas Lease No.
3. Address of Operator <u>13272 NOEL RD Dallas T.X. 75240 STE 500</u>		7. Lease Name or Unit Agreement Name: <u>Mesacero Lidge 35 #16</u> <u>891007 1658</u>
4. Well Location Unit Letter <u>0</u> : <u>990</u> feet from the <u>South</u> line and <u>1650</u> feet from the <u>East</u> line Section <u>35</u> Township <u>19S</u> Range <u>34E</u> NMPM County <u>LEA</u>		8. Well No. <u>35 # 16</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat <u>Pearl Queen</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Circulate well w/ mud set CIP @ 4600' w 35' cement
2. Perf. 5qz 100' plug from 3440 to 3340' (Base of salt) 3391' woc CMT TAG
3. Perf. 5qz 100' plug from 2530 to 2430' (Top of salt 2484') woc TAG
4. Perf. 5 1/2 csg @ 1640' 5qz 100' plug
5. Perf. 5 1/2 csg @ 300' (9 5/8" shoe @ 250') 5qz 100' plug woc TAG
6. Perf. 5 1/2 csg @ 60' circulate cement to surface.
7. Cutt off well Head install dry hole marker.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

B Ripley

TITLE

lead pump

DATE

9-25-03

Type or print name

Brandon Ripley

Telephone No.

420-5502

(This space for State use)

APPROVED BY

Larry W. Wink

TITLE

DISTRICT SUPERVISOR/GENERAL MANAGER

DATE

OCT 08 2003