Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N French Dr , Hobbs, NM 88240		WELL API NO.
<u>District II</u> 1301 W. Grand Ave , Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-08826
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd, Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
<u>District IV</u> 1220 S St Francis Dr , Santa Fe, NM	5anta į C, 141VI 67505	6. State Oil & Gas Lease No.
87505	-	·
SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR USE "APPLIC PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FOR SUCH	State A A/C 2
_	Gas Well Other	8. Well Number 20
2. Name of Operator	dus wen one	9. OGRID Number
Petrohawk Operating Company		194849
3. Address of Operator		10. Pool name or Wildcat
1000 Louisiana, Suite 5600 Hous	ston TX 77002	Jalmat Tansill Yates 7 Rvrs Queen
	111 //002	Januar Tanshi Tates / Tevis Queen
4. Well Location		
Unit Letter	1980feet from theSouth line and	
Section 7	Township 22S Range 36	
	11. Elevation (Show whether DR, RKB, RT, GR, e	etc.)
Pit or Below-grade Tank Application 0	r Closure	
Pit typeDepth to Groundw	aterDistance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil		Construction Material
12. Check A	Appropriate Box to Indicate Nature of Notic	e, Report or Other Data
NOTICE OF IN	TENTION TO	
NOTICE OF IN		JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL W	<u> </u>
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE [DRILLING OPNS.□ P AND A 🛛
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMI	ENT JOB
_	_	ENT JOB
OTHER:	□ OTHER:	
OTHER: 13. Describe proposed or comp	OTHER: letted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp of starting any proposed wo	□ OTHER:	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp	OTHER: letted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion.	OTHER: leted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cent on CIBP @ 3560'. Run tbg @ 3500' & circula	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run view.	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circula wireline & perf 1745' (OCD rep Buddy Hill said we	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'.
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#,	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circula vireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline.	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: ' cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfa	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run tce. Buddy Hill request pump 20 sks cmt dn csg
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circula vireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run tce. Buddy Hill request pump 20 sks cmt dn csg
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: leted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15. Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run tce. Buddy Hill request pump 20 sks cmt dn csg
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: ' cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfa	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: leted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15. Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: leted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15. Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'c cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15. Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2 1 0 6 Approved as to plugging of the Well Bore	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2 1 0 6 Approved as to plugging of the Well Bore	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: leted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2 1 0 6 Approved as to plugging of the Well Bord Liability under bond is retained until	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2 1 0 6 Approved as to plugging of the Well Bore	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: leted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2 1 0 6 Approved as to plugging of the Well Bord Liability under bond is retained until	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg &	OTHER: leted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2 1 0 6 Approved as to plugging of the Well Bord Liability under bond is retained until	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg & wellhead & anchors. RDMO.	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'comt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2 1 0 6 Approved as to plugging of the Well Born Liability under bond is retained until surface restoration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg & wellhead & anchors. RDMO.	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'comt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2 1 0 6 Approved as to plugging of the Well Born Liability under bond is retained until surface restoration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg & wellhead & anchors. RDMO.	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'comt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2 1 0 6 Approved as to plugging of the Well Born Liability under bond is retained until surface restoration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ce. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg & wellhead & anchors. RDMO.	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: or	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ice. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg & wellhead & anchors. RDMO.	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'comt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2 1 0 6 Approved as to plugging of the Well Born Liability under bond is retained until surface restoration is completed.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ice. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg & wellhead & anchors. RDMO.	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ice. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off dge and belief. I further certify that any pit or below—or an (attached) alternative OCD-approved plan DATE9-20-07
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg & wellhead & anchors. RDMO.	OTHER: letted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: or	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ice. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off dge and belief. I further certify that any pit or below—or an (attached) alternative OCD-approved plan DATE9-20-07
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg & wellhead & anchors. RDMO.	leted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'c cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ice. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off or an (attached) alternative OCD-approved plan DATE9-20-07
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg & wellhead & anchors. RDMO.	leted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'c cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ice. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off dge and belief. I further certify that any pit or below—or an (attached) alternative OCD-approved plan DATE9-20-07
OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Run wireline & dump bail 35 sks cmt 3175'-2975'. Pull tbg. Run v Pressure up on perf 1745' to 2000#, wireline perf @ 463'. Pull wireline. & displace to 200'. WOC. Run tbg & wellhead & anchors. RDMO.	leted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions: 'c cmt on CIBP @ 3560'. Run tbg @ 3500' & circular wireline & perf 1745' (OCD rep Buddy Hill said we unable to pump into perf. Spot 25 sks cmt 1795'-15 Pump dn csg @ 250# & unable to circulate out surfact tag TOC @ 250'. Pull tbg @ 60' & spot 10 sks cm 2	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion te hole w/ 10 ppg gel. Pull tbg @ 3175'. Spot 25 need to perf here). Run tbg & set pkr @ 1315'. 95'. Run tbg & tag TOC 1520'. Pull tbg. Run ice. Buddy Hill request pump 20 sks cmt dn csg t to surface. Pull tbg. Hole standing full. Cut off or an (attached) alternative OCD-approved plan DATE9-20-07