Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office	L CONSERVATION DIVI	SION
<u>DISTRICT I</u> P.O. Box 1980, Hobbs NM 88241-1980	2040 Pacheco St.	WELL API NO. 30 - 025 - 03179
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM 87505	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE (STATE Oil & Gas Lease No.
	S AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPO: DIFFERENT RESERVOII (FORM C-101) F	SALS TO DRILL OR TO DEEPEN OR PLUG BAC R. USE "APPLICATION FOR PERMIT" FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name EAST PEARL QUEEN UNIT
1. Type of Well: OIL GAS WELL X WELL	OTHER	
2. Name of Operator XERIC OIL & GAS CORP.		8. Well No.
3. Address of Operator P.O., Box 352, Midland, TX	79702	9. Pool name or Wildcat PEARL QUEEN
4. Well Location Unit Letter G : 2310 F	Feet From The NORTH Line and	2310 Feet From The EAST Line
Section 22	Cownship 19 S Range 35 I	
	10. Elevation (Show whether DF, RKB, RT	7, GR, etc.)
NOTICE OF INTEN		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON REMEDIAL WO CHANGE PLANS CASING TEST OTHER:	ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT X FAND CEMENT JOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. 9-17-03 SPOT 25SKS @ 4050' OK'D BY E PERF @ 1700' SQUEEZE 50 SKS II	PLUG AND ABANDON REMEDIAL WO CHANGE PLANS CASING TEST OTHER: On (Clearly state all pertinent details, and give p	ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT X T AND CEMENT JOB Description of the control of the
EMPORARILY ABANDON ULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. 9-17-03 SPOT 25SKS @ 4050' OK'D BY E PERF @ 1700' SQUEEZE 50 SKS 9-19-03 PERF @ 148' CIRC 75 SKS TO SI INSTALL P & A MARKER CIRC MUD	PLUG AND ABANDON COMMENCE COMM	ORK DRILLING OPNS. PLUG AND ABANDONMENT TAND CEMENT JOB Dertinent dates, including estimated date of starting any properties. Well Bore. Luntil H. Hobbs OCD
PERFORM REMEDIAL WORK PEMPORARILY ABANDON PULL OR ALTER CASING DITHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. 9-17-03 SPOT 25SKS @ 4050' OK'D BY E PERF @ 1700' SQUEEZE 50 SKS IN 9-19-03 PERF @ 148' CIRC 75 SKS TO SI INSTALL P & A MARKER CIRC MUD	PLUG AND ABANDON COMMENCE COMM	ORK ALTERING CASING DRILLING OPNS. PLUG AND ABANDONMENT X T AND CEMENT JOB Description of the control of the