Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office	OPD * 7 1 PT O 3 1 PT T O 5 0	
<u>DISTRICT'I</u> OIL CON P.O. Box 1980, Hobbs NM 88241-1980	SERVATION DIVISIO 2040 Pacheco St.	WELL API NO.
<u>DISTRICT II</u>	Santa Fe, NM 87505	30 - 025 - 03292
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III		5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No. E-5887
SUNDRY NOTICES AND RE	PORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRI DIFFERENT RESERVOIR. USE "APPI (FORM C-101) FOR SUCH PI	LICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name EAST PEARL QUEEN UNIT
1. Type of Well: OIL GAS WELL WELL WELL	OTHER INJECTION	
2. Name of Operator XERIC OIL & GAS CORP.		8. Well No. 51
3. Address of Operator P. O. Box 352, Midland, TX 797802	2	9. Pool name or Wildcat PEARL QUEEN
4. Well Location Unit Letter L : 1980 Feet From The	SOUTH Line and	660 Feet From The WEST Line
Section 34 Township 10. Elev	19 S Range 35 E ation (Show whether DF, RKB, RT, GR,	NMPM LEA County
	: SU	
EMPORARILY ABANDON CHANGE PLA	BANDON REMEDIAL WORK COMMENCE DRILLI CASING TEST AND	
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Operation (Clearly state)	BANDON REMEDIAL WORK ANS COMMENCE DRILLI CASING TEST AND OTHER:	OPNS. PLUG AND ABANDONMENT CEMENT JOB
EMPORARILY ABANDON CHANGE PLA	BANDON REMEDIAL WORK COMMENCE DRILLI CASING TEST AND OTHER: ate all pertinent details, and give pertine	PLUG AND ABANDONMENT CEMENT JOB CEMENT JOB Cent dates, including estimated date of starting any prop
EMPORARILY ABANDON CHANGE PLA PULL OR ALTER CASING THER: 12. Describe Proposed or Completed Operation (Clearly stawork) SEE RULE 1103. 10-7-03 TAG PLUG @ @ 4425' PERF @ 1700' SQUEEZE 50 SKS W.O.C. & T	BANDON REMEDIAL WORK COMMENCE DRILLI CASING TEST AND OTHER: ate all pertinent details, and give pertine	ent dates, including estimated date of starting any property of the Well Bore.
EMPORARILY ABANDON CHANGE PLA ULL OR ALTER CASING THER: 12. Describe Proposed or Completed Operation (Clearly stawork) SEE RULE 1103. 10-7-03 TAG PLUG @ @ 4425' PERF @ 1700' SQUEEZE 50 SKS W.O.C. & TPERF @ 150' CIRC 50 SKS TO SURFACE. INSTALL P & A MARKER	BANDON REMEDIAL WORK COMMENCE DRILLI CASING TEST AND OTHER: ate all pertinent details, and give pertine FAG @ 1590' Approved as to plugging Liability under bond is	ent dates, including estimated date of starting any prop
EMPORARILY ABANDON CHANGE PLA ULL OR ALTER CASING THER: 12. Describe Proposed or Completed Operation (Clearly stawork) SEE RULE 1103. 10-7-03 TAG PLUG @ 4425' PERF @ 1700' SQUEEZE 50 SKS W.O.C. & TPERF @ 150' CIRC 50 SKS TO SURFACE. INSTALL P & A MARKER CIRC MUD	BANDON REMEDIAL WORK COMMENCE DRILLI CASING TEST AND OTHER: ate all pertinent details, and give pertine FAG @ 1590' Approved as to plugging Liability under bond is a surface restoration is co	ent dates, including estimated date of starting any prop
EMPORARILY ABANDON CHANGE PLA ULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation (Clearly stawork) SEE RULE 1103. 10-7-03 TAG PLUG @ @ 4425' PERF @ 1700' SQUEEZE 50 SKS W.O.C. & TPERF @ 150' CIRC 50 SKS TO SURFACE. INSTALL P & A MARKER	BANDON REMEDIAL WORK COMMENCE DRILLI CASING TEST AND OTHER: ate all pertinent details, and give pertine FAG @ 1590' Approved as to plugging Liability under bond is a surface restoration is co	ent dates, including estimated date of starting any prop