Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

	OIL CONSERVATION DIVISION	\cap N
<u>DISTRICT I</u> P.O. Box 1980, Hobbs NM 88241-1980	2040 Pacheco St.	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM 87505	30 - 025 - 03293 5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
	TICES AND REPORTS ON WELLS	E-5887
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name EAST PEARL QUEEN UNIT
1. Type of Well: OIL GAS WELL GAS WELL	OTHER INJECTION	
2. Name of Operator XERIC OIL & GAS CORP.		8. Well No. 53
3. Address of Operator P. O. Box 352, Midland	I, TX 79702	9. Pool name or Wildcat PEARL QUEEN
4. Well Location Unit LetterN:2310	Feet From The WEST Line and	990 Feet From The SOUTH Line
Section 34	Township 19 S Range 35 E	NMPM LEA County R, etc.)
-	ppropriate Box to Indicate Nature of N	· · · · · · · · · · · · · · · · · · ·
NOTICE OF INT	TENTION TO:	SUBSEQUENT REPORT OF:
ERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
	FEOG AND ABANDON — REWEDIAL WORK	ALTERING CASING
	CHANGE PLANS COMMENCE DRIL	
EMPORARILY ABANDON		LING OPNS. PLUG AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING	CHANGE PLANS COMMENCE DRIL	LING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING DTHER:	CHANGE PLANS COMMENCE DRIL	LLING OPNS. PLUG AND ABANDONMENT D
PULL OR ALTER CASING THER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 10-6-03 TAG PLUG @ 4633	CHANGE PLANS COMMENCE DRILL CASING TEST AN OTHER: Operation Clearly state all pertinent details, and give pertinent details. SKS W.O.C. & TAG @ 1520'	LLING OPNS. PLUG AND ABANDONMENT
DEMPORABILY ABANDON PULL OR ALTER CASING DITHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 10-6-03 TAG PLUG @ 4633' PERF @ 1700' SQUEEZE 50 10-7-03	CHANGE PLANS COMMENCE DRILL CASING TEST AN OTHER: Operation Clearly state all pertinent details, and give pertinent details. SKS W.O.C. & TAG @ 1520'	LLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Owork) SEE RULE 1103. 10-6-03 TAG PLUG @ 4633' PERF @ 1700' SQUEEZE 50 10-7-03 PERF @ 150' CIRC 75 SKS INSTALL P & A MARKER	CHANGE PLANS COMMENCE DRILL CASING TEST AN OTHER: Operation Clearly state all pertinent details, and give pertinent details. SKS W.O.C. & TAG @ 1520'	PLUG AND ABANDONMENT ID CEMENT JOB Inent dates, including estimated date of starting any property of the Hobbs and
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 10-6-03 TAG PLUG @ 4633' PERF @ 1700' SQUEEZE 50 10-7-03 PERF @ 150' CIRC 75 SKS INSTALL P & A MARKER CIRC MUD	CHANGE PLANS COMMENCE DRILL CASING TEST AN OTHER: Operation (Clearly state all pertinent details, and give pertinent details) SKS W.O.C. & TAG @ 1520' TO SURFACE. Approved as to plugging of the V Liability under bond is retained to	PLUG AND ABANDONMENT ID CEMENT JOB Inent dates, including estimated date of starting any property of the Hobbs and
PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 10-6-03 TAG PLUG @ 4633' PERF @ 1700' SQUEEZE 50 10-7-03 PERF @ 150' CIRC 75 SKS INSTALL P & A MARKER CIRC MUD	CHANGE PLANS COMMENCE DRILL CASING TEST AN OTHER: Operation Clearly state all pertinent details, and give pertinent details. SKS W.O.C. & TAG @ 1520' TO SURFACE. Approved as to plugging of the V. Liability under bond is retained usurface restoration is completed.	PLUG AND ABANDONMENT ID CEMENT JOB Inent dates, including estimated date of starting any property of the Hobbs and