Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

OCT 2 1 2003

				R	evised March 25, 1999
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 OIL CONSERVATION DIVISION DISTRICT II				WELL API NO.	
DISTRICT II 811 South First, Artesia NM 88210		P.O. Box 2088		30-025-29430	
DISTRICT III Santa Fe, New Mexico 87504-2088 1000 Rio Brazos Rd., Aztec, NM 87410				5. Indicate Type of Lease STATE	M []
DISTRICT IV				6. State Oil & Gas Lease No.	E 🛛 FEE 🗆
2040 South Pacheco, Sante Fe, NM 87505				8015	·
	TICES AND RE				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"				7. Lease Name or Unit Agreement Name	
	1 C-101) FOR SUCH	PROPOSALS)		Bridges State	
1. Type of Well: Oil	Gas 🗖		,		
Well 🔼		controlic	ction Comp.		
2. Name of Operator	ing Adi	vision of Exxon	•	8. Well No. <b>286</b>	
Mobil Producing TX E NM INC & on behalf of  3. Address of Operator P.O. Box 4358 Mobil Producing TX & NM Inc.					
Houston		TX 77210		9. Pool name or Wildcat Vacuum; Grayburg-San	Andres
4. Well Location Unit Letter 540	Feet From Th	ne south	Line and 1930	Feet From The east	Line
Section 26	Township 17		0.45	 NMPH	Lea County
	////////////// 10. Eleva	tion (Show whether I	DR, RKB, RT, GR, etc.)	\//////	
		' G.L. <del>.5' D.F.        403</del>	3.5' K.B.		
11.Check A	appropriate Box	x to Indicate l	Nature of Notice, R	deport, or Other Data	
NOTICE OF IN				QUENT REPORT O	F:
PERFORM REMEDIAL WORK $\Box$	PLUG AND ABA	ANDON □	REMEDIAL WORK		NG CASING
TEMPORARILY ABANDON	CHANGE PLAN	√S ∐	COMMENCE DRILLIN	IG OPNS. 🔲 PLUG &	ABANDONMENT L
TEMPORARILY ABANDON L  PULL OR ALTER CASING	CHANGE PLAN MULTIPLE		COMMENCE DRILLIN CASING TEST AND C		ABANDONMENT 🗆
			CASING TEST AND C	EMENT JOB	
PULL OR ALTER CASING  OTHER:	MULTIPLE COMPLETION		CASING TEST AND COTHER: Temporaril	EMENT JOB □  y Abandon Well	🛛
PULL OR ALTER CASING  OTHER:	MULTIPLE COMPLETION		CASING TEST AND COTHER: Temporaril	EMENT JOB □  y Abandon Well	🛛
OTHER:  12. Describe proposed or completed operat work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP.	MULTIPLE COMPLETION ions. (Clearly state all e Completions: Attach Tested OK.	pertinent details, and wellbore diagram of	CASING TEST AND COTHER: Temporaril digive pertinent dates, include f proposed completion or recommendation of the completion of the comple	y Abandon Well  ding estimated date of starting and completion)	y proposed
OTHER:  12. Describe proposed or completed operat work) SEE RULE 1103. (For Multipl 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg	MULTIPLE COMPLETION ions. (Clearly state all e Completions: Attach Tested OK. anchor. RIH w/	I pertinent details, are wellbore diagram of	CASING TEST AND COTHER: Temporaril digive pertinent dates, include from proposed completion or recommendation of proposed completion of proposed completion of proposed completion or recommendation	y Abandon Well  ding estimated date of starting any completion)  er run. Dumped 20' cmt	y proposed
OTHER:  12. Describe proposed or completed operate work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach  Tested OK. anchor. RIH w/	I pertinent details, are wellbore diagram of	CASING TEST AND COTHER: Temporaril digive pertinent dates, include from proposed completion or recommendation of proposed completion of proposed completion of proposed completion or recommendation	y Abandon Well  ding estimated date of starting any completion)  er run. Dumped 20' cmt	y proposed
OTHER:  12. Describe proposed or completed operat work) SEE RULE 1103. (For Multipl 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach  Tested OK. anchor. RIH w/	I pertinent details, are wellbore diagram of	CASING TEST AND COTHER: Temporaril digive pertinent dates, include from proposed completion or recommendation of proposed completion of proposed completion of proposed completion or recommendation	y Abandon Well  ding estimated date of starting any completion)  er run. Dumped 20' cmt	y proposed
OTHER:  12. Describe proposed or completed operate work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach  Tested OK. anchor. RIH w/	I pertinent details, are wellbore diagram of	CASING TEST AND COTHER: Temporaril digive pertinent dates, include from proposed completion or recommendation of proposed completion of proposed completion of proposed completion or recommendation	y Abandon Well  ding estimated date of starting any completion)  er run. Dumped 20' cmt	y proposed
OTHER:  12. Describe proposed or completed operate work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach  Tested OK. anchor. RIH w/	I pertinent details, are wellbore diagram of	CASING TEST AND COTHER: Temporaril digive pertinent dates, include from proposed completion or recommendation of proposed completion of proposed completion of proposed completion or recommendation	y Abandon Well  ding estimated date of starting any completion)  er run. Dumped 20' cmt	y proposed
OTHER:  12. Describe proposed or completed operate work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach  Tested OK. anchor. RIH w/	I pertinent details, are wellbore diagram of	CASING TEST AND COTHER: Temporaril digive pertinent dates, include from proposed completion or recommendation of proposed completion of proposed completion of proposed completion or recommendation	y Abandon Well  ding estimated date of starting an completion)  er run. Dumped 20' cmt in.	y proposed  on top of CIBP.
OTHER:  12. Describe proposed or completed operate work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach  Tested OK. anchor. RIH w/	I pertinent details, are wellbore diagram of	CASING TEST AND COTHER: Temporaril digive pertinent dates, include from proposed completion or recommendation of proposed completion of proposed completion of proposed completion or recommendation	y Abandon Well  ding estimated date of starting an completion)  er run. Dumped 20' cmt in.	y proposed  on top of CIBP.
OTHER:  12. Describe proposed or completed operate work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach  Tested OK. anchor. RIH w/-7/8" tbg/ RIH v n. RDMO.	pertinent details, are wellbore diagram of CIBP and set of w/ 16 joints for	CASING TEST AND COTHER: Temporaril and give pertinent dates, include proposed completion or recomplete and the second sec	y Abandon Well  ding estimated date of starting an completion)  er run. Dumped 20' cmt in.	y proposed  on top of CIBP.
OTHER:  12. Describe proposed or completed operate work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach  Tested OK. anchor. RIH w/ -7/8" tbg/ RIH w/ n. RDMO.	I pertinent details, are wellbore diagram of	CASING TEST AND COTHER: Temporaril and give pertinent dates, include proposed completion or recomplete and the second sec	y Abandon Well  ding estimated date of starting an completion)  er run. Dumped 20' cmt in.	y proposed  on top of CIBP.  1011 12 70 70 Proposed  WED  Hobbs
OTHER:  12. Describe proposed or completed operate work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach  Tested OK. anchor. RIH w/ -7/8" tbg/ RIH w/ n. RDMO.	I pertinent details, are wellbore diagram of / CIBP and set of / CIBP and / CIBP	CASING TEST AND COTHER: Temporaril and give pertinent dates, include proposed completion or recomplete and the second sec	y Abandon Well  ding estimated date of starting an completion)  er run. Dumped 20' cmt in.	y proposed  on top of CIBP.  1011 12 70 70 Proposed  WED  Hobbs
OTHER:  12. Describe proposed or completed operate work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach  Tested OK. anchor. RIH w/ -7/8" tbg/ RIH w/ n. RDMO.	I pertinent details, are wellbore diagram of / CIBP and set of / CIBP and / CIBP	CASING TEST AND COTHER: Temporaril and give pertinent dates, include proposed completion or recomplete and the second sec	y Abandon Well  ding estimated date of starting an completion)  er run. Dumped 20' cmt in.	y proposed  on top of CIBP.  1011 12 70 70 Proposed  WED  Hobbs
OTHER:  12. Describe proposed or completed operat work) SEE RULE 1103. (For Multipl 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-01/21/03. ND BOP. Close well in	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach Tested OK. anchor. RIH w/ -7/8" tbg/ RIH v n. RDMO.	pertinent details, are wellbore diagram of CIBP and set of 16 joints for ent Expires	CASING TEST AND COTHER: Temporaril ad give pertinent dates, inclusify proposed completion or recompletion. Made 1 bailed kill string. Close well apparary	y Abandon Well ding estimated date of starting any completion) er run. Dumped 20' cmt in.	y proposed  on top of CIBP.  10111223  WED  Hobbs 000
PULL OR ALTER CASING  OTHER:  12. Describe proposed or completed operat work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-01/21/03. ND BOP. Close well in the second secon	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach tested OK. anchor. RIH w/-7/8" tbg/ RIH vn. RDMO.  This Apprahamore.	i pertinent details, and wellbore diagram of / CIBP and set of / CIBP and / C	CASING TEST AND COTHER: Temporaril and give pertinent dates, include proposed completion or recomplete and the second sec	y Abandon Well  ding estimated date of starting an completion)  er run. Dumped 20' cmt in.	y proposed  on top of CIBP.  1011 12 732  WED  Hobbs 0CD  07/09/2003
OTHER:  12. Describe proposed or completed operat work) SEE RULE 1103. (For Multipl 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-01/21/03. ND BOP. Close well in the second	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach tested OK. anchor. RIH w/-7/8" tbg/ RIH vn. RDMO.  This Apprahamore.	pertinent details, are wellbore diagram of CIBP and set of 16 joints for ent Expires	CASING TEST AND COTHER: Temporaril ad give pertinent dates, inclusify proposed completion or recompletion. Made 1 bailed kill string. Close well apparary	y Abandon Well ding estimated date of starting any completion) er run. Dumped 20' cmt in.	y proposed  on top of CIBP.  1011 12 732  WED  Hobbs 0CD  07/09/2003
PULL OR ALTER CASING  OTHER:  12. Describe proposed or completed operat work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-01/21/03. ND BOP. Close well in the second secon	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach tested OK. anchor. RIH w/-7/8" tbg/ RIH vn. RDMO.  This Apprahamore.	i pertinent details, are wellbore diagram of / CIBP and set of / CIBP and set of / 16 joints for ent Expires	CASING TEST AND COTHER: Temporaril ad give pertinent dates, include proposed completion or red (2006) Made 1 baile kill string. Close well aff Office Assistant	y Abandon Well ding estimated date of starting any completion) er run. Dumped 20' cmt in.  DATE_ TELEPHONE NO. (281	y proposed  on top of CIBP.  1011 12 73  WED  Hobbs 000  07/09/2003
OTHER:  12. Describe proposed or completed operat work) SEE RULE 1103. (For Multipl 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-01/21/03. ND BOP. Close well in the second	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach tested OK. anchor. RIH w/-7/8" tbg/ RIH vn. RDMO.  This Apprahamore.	i pertinent details, are wellbore diagram of / CIBP and set of / CIBP and set of / 16 joints for ent Expires	CASING TEST AND COTHER: Temporaril ad give pertinent dates, include proposed completion or red (2006) Made 1 baile kill string. Close well aff Office Assistant	y Abandon Well ding estimated date of starting any completion) er run. Dumped 20' cmt in.  DATE_ TELEPHONE NO. (281	y proposed  on top of CIBP.  1011 12 73  WED  Hobbs 000  07/09/2003
OTHER:  12. Describe proposed or completed operate work) SEE RULE 1103. (For Multiple 01/15/03 - RU WSU. Test BOP. 01/16/03 - POOH w/ tbg and tbg 01/20/03 - POOH w/ 220 joints 2-01/21/03. ND BOP. Close well in 1 hereby certify that the information above is true and compared to the structure of the space for State Use)	MULTIPLE COMPLETION  ions. (Clearly state all e Completions: Attach tested OK. anchor. RIH w/-7/8" tbg/ RIH vn. RDMO.  This Apprahamore.	i pertinent details, are wellbore diagram of / CIBP and set of / CIBP and set of / 16 joints for ent Expires	CASING TEST AND COTHER: Temporaril ad give pertinent dates, include proposed completion or red (2006) Made 1 baile kill string. Close well aff Office Assistant	y Abandon Well  ding estimated date of starting an completion)  er run. Dumped 20' cmt in.	y proposed  on top of CIBP.  1011 12 73  WED  Hobbs 0CD  07/09/2003  1) 654-1948  CCT 2 1 20

