Office	bmit 3 Copies To Appropriate District fice State of New Mexico Energy, Minerals and Natural Resources					Form C			
District I 1625 N. French Dr., Hobbs, NM 88240	Energ	gy, Minerals a	nd Natura	I Resources		ELL API NO	Rev	ised March	25
District II		CONSERVA		MUGION		30-025-03			
1301 W. Grand Ave., Artesia, NM 8821 District III		1220 South			5.	Indicate Ty			
1000 Rio Brazos Rd., Aztec, NM 87410)					STATE		FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		Santa Fe,	NIVI 8/30	05	6.	State Oil & E-6504	k Gas Lea	se No.	
SUNDRY NO	DTICES AND F	REPORTS ON	WELLS	<u></u>	7	Lease Name	or Unit A		
(DO NOT USE THIS FORM FOR PRO	POSALS TO DRU			BACK TO A	/.	Lease Maine		(greement)	N
DIFFERENT RESERVOIR. USE "APP PROPOSALS.)	LICATION FOR	PERMIT" (FORM	C-101) FOR :	SUCH		Vacuum A	bo Unit		
1. Type of Well:						Battery 1,			
Oil Well Gas Well	Other								
2. Name of Operator					8.	Well No.			
ConocoPhillips Co. 3. Address of Operator	· · · · · · · · · · · · · · · · · · ·					#1			
4001 Penbrook, Odessa, T	V 707/2				9.	Pool name o	r Wildcat	······	
4. Well Location	X /9/02					Vacuum Al	oo Reef		
Unit Letter K_:	1,980_feet from	n the <u>South</u>	line	e and1,9	80	feet from (theW	/est	
Section 5		Township 18	S Ra	ange 3	5E	NMPM	Lea	Coun	ty
	10. Eleva	tion (Show whe	ether DR, F	RKB, RT, GR	R, etc.)				Ń
11 Check	Appropriate	3,958' GL							
NOTICE OF I	Appropriate	Box to Indi	cate Natu	re of Noti	ce, Rep	ort or Othe	er Data		
		i TU: Dabandon [_	S	UBSE	QUENT R	EPORT	OF:	
		ABANDON L	XI R	EMEDIAL W	/ORK		ALTER	ING CASIN	10
TEMPORARILY ABANDON		PLANS (OMMENCE					
		-		OMMENCE	DRILLIN		PLUG A	AND ONMENT	
			1						
PULL OR ALTER CASING			⊐ c/	ASING TES	T AND		ADANU	ONNENT	
PULL OR ALTER CASING	MULTIPLE COMPLET			ASING TES [.] EMENT JOE	T AND		ADANU	ONMENT	
OTHER:	COMPLET	ION		EMENT JOE THER:	3			·	
OTHER: 12. Describe proposed or complete	COMPLET	ION [EMENT JOE THER:	3				
OTHER: 12. Describe proposed or complete	COMPLET	ION [EMENT JOE THER:	3	Ttinent dates,			di
OTHER:	COMPLET	ION [EMENT JOE THER:	3	rtinent dates, e diagram of			di di
OTHER: 12. Describe proposed or complet starting any proposed work).	COMPLET	ION [EMENT JOE THER:	3	rtinent dates, e diagram of			di
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110	ION (Clearly state a)3. For Multip		EMENT JOE THER:	3	e diagram of	including proposed	estimated completion	d
OTHER: 12. Describe proposed or complet starting any proposed work).	COMPLET ted operations. SEE RULE 110	ION (Clearly state a)3. For Multip		EMENT JOE THER:	3	e diagram of	including proposed	estimated completion	di di
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110	ION (Clearly state a)3. For Multip		EMENT JOE THER:	3	e diagram of		estimated completion	da 1 d
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110	ION (Clearly state a)3. For Multip		EMENT JOE THER:	3	e diagram of $\sqrt{2^2}$	including proposed	estimated completion	da h d
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110	ION (Clearly state a)3. For Multip		EMENT JOE THER:	3	e diagram of $\sqrt{2^2}$	including proposed	estimated completion	di di
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110	ION (Clearly state a)3. For Multip		EMENT JOE THER:	3	e diagram of $\sqrt{2^2}$	including proposed	estimated completion	di
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110	ION (Clearly state a)3. For Multip		EMENT JOE THER:	3	e diagram of	including proposed	estimated completion	
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110 wellbore dia	ION (Clearly state a)3. For Multip) agrams.	all pertinen le Completi	EMENT JOE THER: t details, and ions: Attach	d give pe n wellbor	e diagram of $\sqrt{2^2}$	including proposed	estimated completion	
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110 wellbore dia	ION (Clearly state a)3. For Multip) agrams.	all pertinen le Completi	EMENT JOE THER: t details, and ions: Attack	d give pe n wellbor	e diagram of $\sqrt{2^2}$	including proposed	estimated completion	
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110 wellbore dia	ION (Clearly state a)3. For Multip) agrams. HE COMMISS HOURS PRIOT	GION MUS TO THE PERATION	EMENT JOE THER: t details, and ions: Attack	d give pe n wellbor	e diagram of $\sqrt{2^2}$	including proposed	estimated completion	d
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110 wellbore dia	ION (Clearly state a)3. For Multip) agrams.	GION MUS TO THE PERATION	EMENT JOE THER: t details, and ions: Attack	d give pe n wellbor	e diagram of $\sqrt{2^2}$	including proposed	estimated completion	d
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation.	COMPLET ted operations. SEE RULE 110 wellbore dia	ION (Clearly state a)3. For Multip) agrams. HE COMMISS HOURS PRIOT	GION MUS TO THE PERATION	EMENT JOE THER: t details, and ions: Attack	d give pe n wellbor	e diagram of $\sqrt{2^2}$	including proposed	estimated completion	di
OTHER: 12. Describe proposed or complet starting any proposed work). S recompilation. See attached procedure &	COMPLET ted operations. SEE RULE 110 wellbore dia	ION (Clearly state a)3. For Multip) (Grams. Grams. (URS PRIOF (UUGGING O O BE APPRO)	SION MUS TO THE PERATION VED.	EMENT JOE THER: t details, and ions: Attach ions: Attach BEGINNIP IS FOR THE	Hed 24 NG OF C-103	e diagram of	including proposed	estimated completion	di
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation. See attached procedure &	COMPLET ted operations. SEE RULE 110 wellbore dia	ION (Clearly state a) 3. For Multip) agrams. HE COMMISS HOURS PRIOF LUGGING O O BE APPROF IND COMPLETE TO	GION MUS TO THE PERATION VED.	EMENT JOE THER: t details, and ions: Attach ions: Attach BEGINNIN IS FOR THE	H give pe n wellbor NG OF C-103 dge and	e diagram of	including proposed	estimated completion	d
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation. See attached procedure & Thereby certify that the information SIGNATURE	COMPLET ted operations. SEE RULE 110 wellbore dia	ION (Clearly state a)3. For Multip) (Grams. Grams. (URS PRIOF (UUGGING O O BE APPRO)	GION MUS TO THE PERATION VED.	EMENT JOE THER: t details, and ions: Attach ions: Attach BEGINNIP IS FOR THE	H give pe n wellbor NG OF C-103 dge and	e diagram of	including proposed ,45678 030 sqqo _H 134 (2007 1007	estimated completion	
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation. See attached procedure & I hereby certify that the information SIGNATURE Type or print name James F. New	COMPLET ted operations. SEE RULE 110 wellbore dia	ION (Clearly state a) 3. For Multip) agrams. HE COMMISS HOURS PRIOF LUGGING O O BE APPROF IND COMPLETE TO	SION MUS CI all pertinen le Completi SION MUS TO THE PERATION VED.	EMENT JOE THER: t details, and ions: Attach ions: Attach BEGINNIN IS FOR THE	H give pe n wellbor NG OF C-103 dge and	belief.	including proposed (A5678 020 134:5578 020 134:5578 0007 1007 1007 1000 2007 1000 2007	estimated completion	
OTHER: 12. Describe proposed or complete starting any proposed work). So recompilation. See attached procedure & I hereby certify that the information SIGNATURE	COMPLET ted operations. SEE RULE 110 wellbore dia	ION (Clearly state a) 3. For Multip) agrams. THE COMMISS HOURS PRIOF PLUGGING O TO BE APPRO IND COMPLETE TO TIT	SION MUS CI all pertinen le Completi SION MUS TO THE PERATION VED.	EMENT JOE THER: t details, and ions: Attach ions: Attach BEGINNIN IS FOR THE	H give pe n wellbor NG OF C-103 dge and	belief.	including proposed (A5678 020 134:5578 020 134:5578 0007 1007 1007 1000 2007 1000 2007	estimated completion	

ŝ

ConocoPhillips

Proposed Plugging Procedure Page 1 of 2

Second Second

Vacuum Abo Unit #14-1 Vacuum Abo Reef Field Section 5, T18S, R35E Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

SI injector - CIBP set @ 8,190' on 11/04/92

- Notify BLM & OCD 24 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- 1. Set steel pit and flow well down as needed.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 3,000# manual BOP. RIH w/ workstring tbg to CIBP @ 8,190'.
- 3. RU cementer and circulate hole w/ mud, pump 25 sx C cmt on CIBP 8,190 8,050'. Abo plug
- 4. POOH w/ tbg to 6,250' and pump 25 sx C cmt 6,250 6,150'. Glorieta plug
- 5. POOH w/ tbg to 4,630' and pump 25 sx C cmt 4,630 4,530'. Grayburg plug
- 6. RIH w/ wireline and cut 5½" casing @ +/- 3,189', POOH w/ wireline. ND wellhead and RU csg tools, POOH w/ 5½" casing. If casing is not free, pull based on stretch measurements.
- 7. RIH w/ tbg to 3,239' and pump 60 sx C cmt w/ 2% CaCl₂ @ 3,239'. WOC and tag this plug. Casing stub and intermediate shoe plug
- 8. POOH w/ tbg to 3,090' and pump 35 sx C cmt 3,090 2,990'. base of salt plug
- **9.** RIH w/ wireline and perforate casing @ 1,542' w/ four 3½" strip-jet charges. POOH w/ wireline.
- **10.** RIH w/ 8-5/8" AD-1 packer to 1,300' and establish rate into perforations, squeeze 60 sx C cmt 1,542 1,442'. **Top of salt plug**
- 11. RIH w/ wireline and perforate casing @ 352'. POOH w/ wireline.
- **12.** RIH w/ 8-5/8" AD-1 packer to 120'. RU cementer and load hole w/ mud, set packer. Establish rate into perforations and squeeze 115 sx C cmt w/ 2% CaCl₂ 352 - 252'. WOC and tag this plug. **surface casing shoe plug**



1

ConocoPhillips

Proposed Plugging Procedure Page 2 of 2

Vacuum Abo Unit #14-1 Vacuum Abo Reef Field Section 5, T18S, R35E Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

13. RIH w/ wireline and perforate 8-5/8" casing @ 60'. POOH w/ wireline.

- **14.** ND BOP and NU wellhead. Establish circulation and 20 sx C cmt 60' to surface. **surface plug**
- 15. SI well. RDMO. Clean steel pit and dispose of bottoms.

16. Cut off wellhead and anchors, level location. Leave location clean and free of trash.

1

 $(-1) = \frac{1}{2\pi} \frac{L_{n_1,n_2}}{m_{n_1,n_2}} + \frac{1}{2\pi} \frac{L_{n_2,n_2}}{m_{n_2,n_2}} + \frac{1}{2\pi}$



