

Submit 3 Copies To Appropriate
District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30 025 28320
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E 8712
7. Lease Name or Unit Agreement Name Gulf State
8. Well Number 1
9. OGRID Number 20713
10. Pool name or Wildcat: Vacuum; Grayburg-SA 62180

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other (Injection) ☐	7. Lease Name or Unit Agreement Name Gulf State
2. Name of Operator Shinnery Oil Co., Inc.	8. Well Number 1
3. Address of Operator 606 W. Tennessee, Suite 107, Midland, TX 79701	9. OGRID Number 20713
4. Well Location (Surface) Unit Letter <u>B</u> : <u>990</u> feet from the <u>North</u> line and <u>2310</u> feet from the <u>East</u> line Section <u>21</u> Township <u>17S</u> Range <u>34E</u> NMPM Lea County	10. Pool name or Wildcat: Vacuum; Grayburg-SA 62180
11. Elevation (Show whether DR, RKB, RT, GR, etc.): <u>4061'</u>	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER:


SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103 For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Propose to P & A as follows:

1. Set CIBP @ 4400' w/35' cement on top-tag.
2. Stretch 4 1/2" csg. cut @ 3500', set plug from 3450-3550' w/30 sx - tag
3. 50 sx plug from 1324-1500' (8 5/8" casing shoe)-tag.
4. 30 sx plug from ~~900-1000'~~ - tag 400'-300' (FRESH WATER)
5. 10 sx plug @ surface - WOC & set P & A Marker.
Class C/Poz cement or type as specified by OCD.
Wellbore Diagram attached.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Regulatory Agent DATE: 10-18-07

Type or print name Ann E. Ritchie E-mail address: ann.ritchie@wtor.net Telephone No. 432 684-6381

(This space for State use)

APPROVED BY [Signature] TITLE OCD FIELD OPERATIVE WORK MANAGER DATE OCT 26 2007
Conditions of approval, if any:

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.

Gulf State #1
Vacuum Field

Wellbore
Proposed - P&A

Unit "B" Sec 21, T17S, R34E
Lea Co., New Mexico

30 025 28320

spud 8-23-83

Surface plug w/10SX

12 1/4"
Hole

30 SX plug
from 1000' to 900'
TAG

TAG
?

50 SX plug
from 1324'
to 1500'
(50' Above Set)

8 5/8" 24# J-55 set @
1374' w/50SX cement
Cmt was circulated.

7 7/8"
Hole

Stretch & cut 4 1/2" CSG
@ 3300' ± Set Plug Inside
& outside stub w/30SX

Est (Calc)
Max TOC @ 3300' w/100% fill

Set
CIBP @ 4400' w/35' cmt on Top TAG

perts 4448'

to

SAN Andres

5008'

4 1/2" 9.5# J-55 set @
5044' w/400SX cmt
(380)

TD @ 5050'

