Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Revised March 25, 1999
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Emorgy, remotate and tratutal resources		WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-21401
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE THE TEE THE TEE STATE TEE THE T
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	·		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			7. Lease Name or Unit Agreement Name: J. F. B/ACK
The state of the s			8. Well No.
PRONGhORN Mg	Mgt. CORp.		5
3. Address of Operator D. D. Roy 1777, 4144 Al. M. 887.40 505-342-2495		9. Pool name or Wildcat	
2. Name of Operator Rowg hown Mgt. CORp. 8. Well No. 3. Address of Operator 9. Pool name or Wildcat P. D. Box 1772 Hobbs N. M. 88240 505-392-2495 Langlic Mattix Seven Rivers 4. Well Location Queen			
Unit Letter K: 1980 feet from the F5L line and 1030 feet from the FWL line			
Section 2/ Township 245 Range 37 E NMPM LEA County			
10. Elevation (Show whether DR, RKB, RT; GR, etc.)			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSPERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		BEQUENT REPORT OF:	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND	
PULL OR ALTER CASING	MULTIPLE COMPLETION	ABANDONMENT CASING TES'I AND CEMENT JOB	
CTHER:		OTHER:	П
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 			
1. Move in And Rig up. Install B.O.P.			
1 Postorate Jalmut Vates zone. Stimulate As Necessary			
3. Return well to production.			
12 ~ 0(1 3002 ° 0)			
E FIGGOIVED 28			
			Nobbs Och
			07.00
			8/90+07\
hereby certify that the information above is true and complete to the best of my knowledge and belief.			
IGNATURE /MMlen MM TITLE PART NEW DATE/0/19/07			
ype or print name G.A.B.4	. ////		505
This space for State use)	y ev		Telephone No. 342-2495
OC DISTRICT SUPERVISOR/GENERAL MANAGER			
PPPROVED BY DATE OCT O			
conditions of approval, if any Must file on APD & Plat for plugback 2007			
Chrildeliens 10/2007			
		M	us coreceases 10/26/07