I Type of Well Gas Well Other RNM113 I Type of Well Gas Well Other 8. Well Name and No. I Type of Operator PicChfork Ranch 28 1 Image: Picch 2000 (Include area code) 30 Address 9. API Well No. 9. API Well No. 3a Address 915 686 3689 910 - 025-28488 4 Location of Well (Footage, Sec. T. R. M. or Survey Description) Sec 28, T-24-S, R-34-E Image: Virite Completed Science Completed Notice Completed Science Completed Science Completed Science Completed Science Completed Operation (Star/Resume) Water Shut-Off 11. COUNT of Intent Actize Deepen Production (Star/Resume) Water Shut-Off Image: Subsequent Notice Charge Plans Plag Active Treat Reclamation Well Integrity Image: Subsequent Notice Convert to Injection Plag Back Water Disposal Well From and there is and zono science of provide the Bond Notice 13 Describe Proposed or Completed Operation (clearly state all pertinent details, including or science of provide the Bond Noto on the with BM/BIA. Required subsequent reports stall the field within 30 days of blowing completein on on the with the openal in a multiple completeine or science with the Bond State State Complete Integring State State State State State Note State Sta	Fðrm 3160- (February 2	005) DEPARTME	proposals to drill	ON WELL	ter an	BS	FORM APPROVED OMB NO. 1004-0137 Expires March 31, 2007 5. Lease Serial No. NM -19452 6 If Indian, Allottee or Tribe Name		
Image: Solution of Operator 8. Well Name and No. 2 Name of Operator 8. Well Name and No. BOG Resourcess Inc. 3a. Adduess P.O. Box 2267 Midland, Texas 79702 915 686 3689 4 Location of Well (Footage, Sec, T, R, M, or Survey Description) 915 686 3689 Sec 28, T-24-S, R-34-E Unit 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Image: Source of latent Addres Image: Source of latent Addres Image: Source of latent Addres Image: Source of latent Chain Repair Image: Source of or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereoff 13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof filde with 30 days following completion of the involved operation. 13 Describe Proposed or Completed Operation. (If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filded once texting has been completed on fild and handon which the bood under which the work will be performed or provide the Bood No. on file with BLMHABLA. Receind subsequent reports shall be filded once texting has been completed on fild anthano	SUBMIT IN TRIPLICATE - Other instructions on reverse side						7. If Unit or CA/Agreement, Name and/or No. RNM113		
3a Address 3b. Phone No. (include area code) 30-025-28488 P.O. Rox 2267 Midland, Texas 79702 915 686 3689 10. Field and Pool, or Exploratory Area 4 Location of Well (Footage, Sec. T. R. M. or Survey Description) Sec 28, T-24-S, R-34-E Unit 6 Sec 28, T-24-S, R-34-E Unit 6 11. County or Parsh, State Load Intervention Intervention YPE OF SUBMISSION TYPE OF ACTION Image: Subsequent Report Atter Casing Production (Star/Resume) Water Shut-Off Subsequent Report Casing Repair New Construction Recomplete Other Image: Subsequent Notice Convert to Injection Plug Back Water Disposal Water Shut-Off Image: Subsequent Report Convert to Injection Plug Back Water Osposal Other Mater Saudon Image: Subsequent Notice Convert to Injection Plug Back Water Osposal Water Shut-Off Image: Subsequent to Mather Subsequent Notice Convert to Injection Plug Back Water Osposal Mater Saudon Image: Subsequent Report Convert to Injection Plug Back Water Osposal Mater Saudon Image: Subsequent Notice	X Oil Well Gas Well Other 2 Name of Operator Image: Contract of Operator					Pitchfork Ranch 28 1			
P.O. Box 2267 Midland, Texas 79702 915 686 3689 10. Field and Pool, or Exploratory Area 4 Location of Well (Footage, Sec, T, R, M., or Survey Description) Sec 28, T-24-S, R-34-E Unit Sec Sec 28, T-24-S, R-34-E Unit Sec 11. County or Parsh, State Lea NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Image: Subsequent Report Actdize Deepen Subsequent Report Casing Repair New Construction Image: Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deeped directionally or recomplete hourset on file with BLMPIA. Required subsequent reports shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final size is aready for final inspection.) Proposed F&A procedure: 1. 14. Set 4 1/2" CIBP at 14750 + 35' cement cap									
4 Location of Well (Footage, Sec, T, R, M., or Survey Description) Pitchfork Ranch Morrow Sec 28, T-24-S, R-34-E Unit 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Image: Subsequent Report Acidize Subsequent Report Casing Repair Image: Final Abandonment Notice Charge Plans Image: Subsequent Report Casing Repair Image: Final Abandonment Notice Plug and Abandon Image: Subsequent Report Casing Repair Image: Final Abandonment Notice Plug and Abandon Image: Subsequent Report Casing Repair Image: Final Abandonment Notice Plug and Abandon Image: Subsequent Report Casing Repair Image: Subsequent Report Casing Repair <td colspan="4"></td> <td></td> <td>,</td> <td></td>						,			
Sec 28, T-24-S, R-34-E Unit G 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Image: Subsequent Report Acudize Image: Subsequent Report Casing Repair Image: Final Abundonment Notice Charge Plans Image: Subsequent to logication (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BLA. Required subsequent reports shall be filed within 30 days following completed Final Abundonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final is the stady of final inspection.) Proposed PEA procedures: 1. Set 4 1/2" CIBP at 14750 + 35' cement cap					000 3005				
TYPE OF SUBMISSION TYPE OF ACTION Image: Construction in the importance of the production of the production (Start/Resume) Water Shut-Off Image: Construction in the production of the production of the production of the production of the importance of the production.) Proposed P&A procedure: 1. Set 4 1/2" CIBP at 14750 + 35' cement cap	Sec 28						11. County or Parish, State		
Image: Subsequent Report Acidize Deepen Production (Start/Resume) Water Shut-Off Image: Subsequent Report Alter Casing Fracture Treat Reclamation Well Integrity Image: Casing Repair New Construction Recomplete Other Other Image: Final Abandonment Notice Change Plans Plug and Abandon Temporarily Abandon If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. Proposed P&A procedure: 1. Set: 4 1/2" CIEP at 14750 + 35' cement cap			BOX(ES) TO INL			· · · · · · · · · · · · · · · · · · ·			
Image: Subsequent Report Image: Alter Casing Fracture Treat Reclamation Well Integrity Image: Subsequent Report Image: Casing Repair New Construction Recomplete Other Image: Casing Repair Image: Final Abandonment Notice Image: Casing Repair New Construction Recomplete Other Image: Casing Repair Image: Cas									
 13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) Proposed P&A procedure: Set 4 1/2" CIBP at 14750 + 35' cement cap 	Subsequent Report				Fracture Treat Reclamation Well Integrity				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) Proposed P&A procedure: 1. Set 4 1/2" CIBP at 14750 + 35' cement cap							-		
1. Set 4 1/2" CIBP at 14750 + 35' cement cap	If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)								
 Spot 125 sx plug from 12515' - 12765'. Tag. Spot 80 sx plug from 9200' - 9400'. Spot 70 sx plug from 6300' - 6500'. Cut and pull 7" casing at +/- 5700'. Spot 120 sx plug from 5600' - 5800'. Tag. Spot 120 sx plug from 2150' - 5350'. Tag. Spot 45 sx plug from 2150' - 2250'. Spot 45 sx plug from 545' - 645'. Tag. Spot 25 sx surface plug. Cut off casing and weld on P&A marker. Clean and restore location. 		_	' cement cap						
 3. Spot 80 sx plug from 9200' - 9400'. 4. Spot 70 sx plug from 6300' - 6500'. 5. Cut and pull 7" casing at +/- 5700'. 6. Spot 120 sx plug from 5600' - 5800'. Tag. 7. Spot 120 sx plug from 5150' - 5350'. Tag. 8. Spot 45 sx plug from 545' - 645'. Tag. 10. Spot 25 sx surface plug. 11. Cut off casing and weld on P&A marker. Clean and restore location. 			-						
 4. Spot 70 sx plug from 6300' - 6500'. 5. Cut and pull 7" casing at +/- 5700'. 6. Spot 120 sx plug from 5600' - 5800'. Tag. 7. Spot 120 sx plug from 5150' - 5350'. Tag. 8. Spot 45 sx plug from 2150' - 2250'. 9. Spot 45 sx plug from 545' - 645'. Tag. 10. Spot 25 sx surface plug. 11. Cut off casing and weld on P&A marker. Clean and restore location. 	3. Spot 80 sx plug from 9200' - 9400'.								
 5. Cut and pull 7" casing at +/- 5700'. 6. Spot 120 sx plug from 5600' - 5800'. Tag. 7. Spot 120 sx plug from 5150' - 5350'. Tag. 8. Spot 45 sx plug from 2150' - 2250'. 9. Spot 45 sx plug from 545' - 645'. Tag. 10. Spot 25 sx surface plug. 11. Cut off casing and weld on P&A marker. Clean and restore location. 	4. Spot 70 sx plug from 6300' - 6500'.								
 6. Spot 120 sx plug from 5600' - 5800'. Tag. 7. Spot 120 sx plug from 5150' - 5350'. Tag. 8. Spot 45 sx plug from 2150' - 2250'. 9. Spot 45 sx plug from 545' - 645'. Tag. 10. Spot 25 sx surface plug. 11. Cut off casing and weld on P&A marker. Clean and restore location. 		5. Cut and pull 7" casing at +/- 5700'.							
 7. Spot 120 sx plug from 5150' - 5350'. Tag. 8. Spot 45 sx plug from 2150' - 2250'. 9. Spot 45 sx plug from 545' - 645'. Tag. 10. Spot 25 sx surface plug. 11. Cut off casing and weld on P&A marker. Clean and restore location. 						12	NOV 2007 SA		
 8. Spot 45 sx plug from 2150' - 2250'. 9. Spot 45 sx plug from 545' - 645'. Tag. 10. Spot 25 sx surface plug. 11. Cut off casing and weld on P&A marker. Clean and restore location. 						တ္	Popping 11		
9. Spot 45 sx plug from 545' - 645'. Tag. 10. Spot 25 sx surface plug. 11. Cut off casing and weld on P&A marker. Clean and restore location.		9. Spot 45 sx plug from 545! - 645! Tag $\begin{pmatrix} 0 \\ - \\ - \\ - \\ - \\ - \\ - \\ - \\ - \\ - \\$							
10. Spot 25 sx surface plug. 11. Cut off casing and weld on P&A marker. Clean and restore location.			45'. Tag.			1E			
The call off casing and weld of Fax Marker. Crean and restore location.	11. Cut off casing and weld on P&A marker. Clean and restore location								
	11. (cut off casing and werd on Pa	A Marker. Clean	i and rest	ore locati	lon.	EV 21 1101 68 1.9		
14 I hereby certify that the foregoing is true and correct Title Name (Printed/Typed) 7 Reg Analyst	Name (Printed/Typed)			Title	Reg Anal	lyst			
Signature Stan Wassen Date 11/12/07									
THIS SPACE FOR FEDERAL OR STATE OFFICE USE	1.1	THIS	SPACE FOR FEDE			CEUSE			

Approved by /S/ DAVID R. GLASS	Title PETROLEUM ENGINEER Date NOV 2 0 2007						
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.							
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

s

[•] EOG RESOURCES, INC. 1,980[•] FNL & 1,980[•] FEL SEC. 28-T24S-R34E

PITCHFORK RANCH "28" FEDERAL COM. NO. 1 LEA CO., NEW MEXICO OCTOBER 29, 2007

WELLBORE SCHEMATIC



⁶ EOG RESOURCES, INC. 1,980' FNL & 1,980' FEL SEC. 28-T24S-R34E

12

PITCHFORK RANCH "28" FEDERAL COM. NO. 1 LEA CO., NEW MEXICO OCTOBER 29, 2007

WELLBORE SCHEMATIC



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220-6292 (505) 234-5972

.

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90th day provide the appropriate BLM office, prior to the 90th day, with the reason for not meeting the deadline and a date when the appropriate BLM office can expect the well to be plugged. Failure to do so will result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Eddy County call (505) 361-2822; for wells in Lea County call (505) 393-3612.

3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

Following the submittal and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval shall be developed and furnished to you.



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, NM 88220

Interim Reclamation Procedures for Permanently Abandoned Federal Wells

1. After Subsequent Report of Abandonment, Form 3160-5, is filed and approved by the BLM the surface protection specialist (SPS) will conduct a surface inspection of the abandonment. The SPS will establish the reclamation requirements the operator will need to complete. DO NOT START RECLAMATION UNTIL THE SPS HAS INSPECTED THE LOCATION.

2. The reclamation requirements will be given to an environmental protection specialist (EPS). The EPS will issue the operator a Notice of Written Order outlining the reclamation requirements. DO NOT START RECLAMATION UNTIL A NOTICE OF WRITTEN ORDER FOR RECLAMATION HAS BEEN RECEIVED. The EPS will be responsible for all further abandonment work and inspections.

3. <u>Notification:</u> CONTACT THE EPS 3 DAYS PRIOR TO RECLAMATION WORK. This notification gives the EPS an opportunity to discuss by phone or on location the reclamation requirements, any special concerns and the timeframes. It also allows the EPS an opportunity to witness various aspects of the reclamation work to determine if an adequate seedbed has been prepared and all reclamation requirements have been completed. CONTACT THE EPS AT LEAST 3 DAYS PRIOR TO SEEDING. This allows the EPS to witness the seeding operation to make sure the location is seeded properly and with the appropriate seed mixture. DO NOT START RECLAMATION UNTIL THE EPS HAS BEEN NOTIFIED.

4. After reclamation work has been completed, submit the I & E copy of the Notice of Written Order to the BLM. It will need to be signed by a company representative and dated. Also submit one original and five copies of the Final Abandonment Notice, Form 3160-5. The report should state that all reclamation work has been completed, and the location is ready for a final abandonment inspection.

5. The BLM will continue to monitor the location to ensure the location vegetates successfully, and salts from the reserve pit do not leach to the surface. The location will be monitored until such time as vegetation (20%) is established evenly across the location (including the reserve pit and access road). Once EPS determines that vegetation (20%) is evenly spread across the location, final abandonment will be authorized.

If there are any questions please feel free to contact any of the following:

Jim Amos Supervisory Environmental Protection Specialist (505) 234-5909

Barry Hunt Surface Protection Specialist (505) 234-5965

Todd Suter Surface Protection Specialist (505) 234-5987

Trishia Bad Bear Natural Resource Specialist – Lea County (505) 393-3612 Cody Layton Natural Resource Specialist (505) 234-5959

Paul Evans Environmental Protection Specialist (505) 234-5977

Terry Gregston Environmental Protection Specialist (505) 234-5958

10/18/2006