	1	
Submit 3 Copies To Appropriate District State of New Mexico Office Energy Minerals and Natural Resources	Form C-103	
Office Energy, Minerals and Natural Resources District 1 1625 N French Dr., Hobbs, NM 87240	May 27, 2004	
District II 1301 W. Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-28600	
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505 District IV	STATE X FEE	
1220 S St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS )	7. Lease Name or Unit Agreement Name: NORTH VACUUM ABO UNIT	
1. Type of Well:	8. Well Number	
Oil Well X Gas Well Other		
2. Name of Operator XTO Energy, Inc.	9. OGRID Number 005380	
3. Address of Operator	10. Pool name or Wildcat	
200 N. Loraine, Ste. 800 Midland, TX 79701	VACUUM; ABO; NORTH	
4. Well Location		
Unit Letter I feet from the South line and	665 feet from the East line	
Section 26 Township 17S Range 34E	NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, et	c.) Lot in the second s	
Pit or Below-grade Tank Application or Closure	a state to the second	
Pit type Depth to Groundwater Distance from nearest fresh water well Dis	stance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	Report, or Other Data SEQUENT REPORT OF: ALTERING CASING	
TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE       CASING TEST AND         COMPLETION       CEMENT JOB	NG OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION		
PULL OR ALTER CASING     MULTIPLE COMPLETION     CASING TEST AND CEMENT JOB       OTHER:     0AP/STIMULATION     Image: Completion	ABANDONMENT	
PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION	ABANDONMENT	
PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       0AP/STIMULATION       Image: Complete operation in the second secon	ABANDONMENT	
PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       0AP/STIMULATION       Image: Complete of the second s	ABANDONMENT	
PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       0AP/STIMULATION       X       OTHER:         13.       Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion.	ABANDONMENT	
PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       0AP/STIMULATION       Image: Complete and the second complete and the second complete and the second completion and the second completion and the second completion and the second completion.       Image: Complete and the second complete and the second completion and the second compl	ABANDONMENT	
PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       0AP/STIMULATION       Image: Complete of the second s	ABANDONMENT	
PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       0AP/STIMULATION       Image: Complete and the second complete and the second complete and the second completion and the second completion and the second completion and the second completion.       Image: Complete and the second complete and the second completion and the second compl	ABANDONMENT	
PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OAP/STIMULATION       OTHER:         13.       Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.         1.       RU PU. TOH W/rods & pump.         2.       Tag to determine fill. Clean out fill if necessary. TOH w/prod. to See Attached         Thereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit	ABANDONMENT	
PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       0AP/STIMULATION       Image: Complete complete complete complete completions of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.         1.       RU PU. TOH W/rods & pump.         2.       Tag to determine fill. Clean out fill if necessary. TOH w/prod. to See Attached         I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit         SIGNATURE       Image: Complete comple	ABANDONMENT	
PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion.         1. RU PU. TOH W/rods & pump.         2. Tag to determine fill. Clean out fill if necessary. TOH w/prod. t See Attached         1 hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE         MULTIPLE       Regulator E-mail address:	ABANDONMENT	

Conditions of Approval, if any:



3. RU WL. RIH W/csg guns loaded 2 SPF. Correlate to Gamma Ray Correlation log ran on 5/11/1984. Perf following Abo intervals.

I)	8584'-8588'	4'	8 total holes	
II)	8594'-8600'	6'	12 total holes	
III) 8616'-8627'		11'	22 total holes	
IV)	8632'-8637'	5'	10 total holes	
Totals		26'	52 total holes	
RD WL after perforating.				

- 4. TIH w/pkr. Set RBP below new perfs (+/- 8650'). PUH \* set pkr @ +/-8570'. Bottom perf of isoloated pay is 8564'.
- 5. RU Pumping services.

## ACID BREAKDOWN OF 8584'-8637' INTERVAL

Pump 5000 gal 20% HCL & 100 Ball Sealers @ 6BPM. Max pressure should be 5000 psi. Drop ball sealers in groups of 10 every 9 bbls throughout last <sup>3</sup>/<sub>4</sub> of acid job. If ballout occurs, surge ball sealers off & continue w/acid job. After acid is pumped, flush to bottom perf with fresh water. Surge well after breakdown to ensure all ball sealers are off of perforations.

## **ULTRAGEL STIMULATION OF 8584'-8637' INTERVAL**

Pump 10000 gal (238 bbls) 20% Ultragel & 39 BS per the attached pump schedule @ 8 BPM. Maximum pressure should be 5000 psi. Flush to bottom perf (~51 bbl) with fresh water. Overflush with 30 bbls fresh water.

- 6. Leave well SI for a minimum of 2 hours to allow acid to spend. Flow well back with steel lines to frac tanks until well dies.
- Release packer & TIH to RBP. Release RBP & PUH w/ WS. Set RBP @ +/- 8480'. PUH & set packer & +/- 8300'.



## ULTRAGEL STIMULATION OF 8362'-8466' INTERVAL

RU Pumping Services. Pump 10,000 gallons 20% Ultragel in 5 stages per the attached treating schedule @ 8 BPM. The schedule has 1750# rock salt stages. If no block action is noticed on the initial stage then increase salt to 2000#-2500# per stage. Maximum pressure should be 5000 psi. After acid is pumped, flush with fresh water. Overflush with 30 bbls fresh water. Shut down and obtain 5, 10, 15 min SI pressures. RD punping srvc.

 $\cap$ 

- 9. Leave well SI for min of 2 hrs to allow acid to spend. Flow well back.
- 10. Release packer & TOH w/ WS & pkr.
- 11. TIH w/ WS to RBP. Latch onto & release RBP. POH w/ WS & RBP.

 $\sim$ 

12. TIH w/ prod tbg. RD PU. RWTP.



PREPARED BY. Richard Lauderdale DATE 5/29/07