Submit 3 Copies To Appropriate District State of New Mexico	Form C-103				
Office Energy, Minerals and Natural Resources	May 27, 2004				
	WELL API NO.				
District II 1301 W Grand Ave, Arthury 44, 20 CAN WILL CONSERVATION DIVISION	30-025-05204				
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease				
1000 Rio Brazos Rd, Aztec, NM 87410	STATE FEE 6. State Oil & Gas Lease No.				
District IV 1220 S St Francis Dr., Santa Fe, MAR 1 4 2008 Santa Fe, NM 87505	o. State on & Gus Eeuse No.				
SLEVER SEALS AND SEPORTS ON WELLS (DO NOT USE THIS FORM SOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name				
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	W.T .Mann "A"				
PROPOSALS)	8. Well Number #2				
1. Type of Well: Oil Well Gas Well Other	9. OGRID Number				
2. Name of Operator Americo Energy Resources, LLC	228051				
3. Address of Operator	10. Pool name or Wildcat				
7575 San Felipe, Suite 200, Houston, TX 77063	Denton (Devonian)				
4. Well Location					
Unit Letter B :660feet from theNorth line and	2310 feet from the East line				
	Zeast NMPM Lea County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
Pit or Below-grade Tank Application 🗋 or Closure 🗌					
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest fresh wat	ance from nearest surface water				
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Co	nstruction Material				
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data				
12. Check Appropriate Dox to indicate reatine of rotice,	Report of Other Data				
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:				
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔲 🛛 REMEDIAL WOR					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A					
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN					
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN					
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER:	г јов				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	T JOB				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.	T JOB				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At	T JOB				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL.	T JOB				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit.	T JOB				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7'	T JOB				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string.	T JOB				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7'	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion casing to 12621'. laid down bit and scraper. # for 15 MTS. Held, OK.				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string. 4- Gih with packer on tubing string . set packer at 10000'. Tested casing 500 3- Rig up swab tools, swabbed well for 2 days. Recovered 85 bbl fluid 1% 4- Pooh and laid down 2-7/8", N80 tubing in singles. Rig down service rig.	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion casing to 12621'. laid down bit and scraper. f for 15 MTS. Held, OK. oil cut, and 99% water.				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string. 4- Gih with packer on tubing string . set packer at 10000'. Tested casing 500 3- Rig up swab tools, swabbed well for 2 days. Recovered 85 bbl fluid 1% 4- Pooh and laid down 2-7/8", N80 tubing in singles. Rig down service rig. 5- MIRU Baker Atlas Eline. Ran PDK-100, & GR/CCL log from 12550'-9	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion casing to 12621'. laid down bit and scraper. f for 15 MTS. Held, OK. oil cut, and 99% water.				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string. 4- Gih with packer on tubing string . set packer at 10000'. Tested casing 500 3- Rig up swab tools, swabbed well for 2 days. Recovered 85 bbl fluid 1% 4- Pooh and laid down 2-7/8", N80 tubing in singles. Rig down service rig. 5- MIRU Baker Atlas Eline. Ran PDK-100, & GR/CCL log from 12550'-5 CBL/CCL/VDL/GR log from 12550'-10000'.	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion casing to 12621'. laid down bit and scraper. f for 15 MTS. Held, OK. oil cut, and 99% water.				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string. 4- Gih with packer on tubing string . set packer at 10000'. Tested casing 500 3- Rig up swab tools, swabbed well for 2 days. Recovered 85 bbl fluid 1% 4- Pooh and laid down 2-7/8", N80 tubing in singles. Rig down service rig. 5- MIRU Baker Atlas Eline. Ran PDK-100, & GR/CCL log from 12550'-9 CBL/CCL/VDL/GR log from 12550'-10000'. 6- Pooh and rig down Baker Atlas.	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion casing to 12621'. laid down bit and scraper. f for 15 MTS. Held, OK. oil cut, and 99% water.				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string. 4- Gih with packer on tubing string . set packer at 10000'. Tested casing 500 3- Rig up swab tools, swabbed well for 2 days. Recovered 85 bbl fluid 1% 4- Pooh and laid down 2-7/8", N80 tubing in singles. Rig down service rig. 5- MIRU Baker Atlas Eline. Ran PDK-100, & GR/CCL log from 12550'-5 CBL/CCL/VDL/GR log from 12550'-10000'.	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion casing to 12621'. laid down bit and scraper. f for 15 MTS. Held, OK. oil cut, and 99% water.				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string. 4- Gih with packer on tubing string . set packer at 10000'. Tested casing 500 3- Rig up swab tools, swabbed well for 2 days. Recovered 85 bbl fluid 1% 4- Pooh and laid down 2-7/8", N80 tubing in singles. Rig down service rig. 5- MIRU Baker Atlas Eline. Ran PDK-100, & GR/CCL log from 12550'-9 CBL/CCL/VDL/GR log from 12550'-10000'. 6- Pooh and rig down Baker Atlas.	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion casing to 12621'. laid down bit and scraper. f for 15 MTS. Held, OK. oil cut, and 99% water.				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string. 4- Gih with packer on tubing string . set packer at 10000'. Tested casing 500 3- Rig up swab tools, swabbed well for 2 days. Recovered 85 bbl fluid 1% 4- Pooh and laid down 2-7/8", N80 tubing in singles. Rig down service rig. 5- MIRU Baker Atlas Eline. Ran PDK-100, & GR/CCL log from 12550'-9 CBL/CCL/VDL/GR log from 12550'-10000'. 6- Pooh and rig down Baker Atlas.	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion casing to 12621'. laid down bit and scraper. f for 15 MTS. Held, OK. oil cut, and 99% water.				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string. 4- Gih with packer on tubing string . set packer at 10000'. Tested casing 500 3- Rig up swab tools, swabbed well for 2 days. Recovered 85 bbl fluid 1% 4- Pooh and laid down 2-7/8", N80 tubing in singles. Rig down service rig. 5- MIRU Baker Atlas Eline. Ran PDK-100, & GR/CCL log from 12550'-50 CBL/CCL/VDL/GR log from 12550'-10000'. 6- Pooh and rig down Baker Atlas. 7- Closed well in Pending Well evaluation.	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion 'casing to 12621'. laid down bit and scraper. # for 15 MTS. Held , OK. oil cut, and 99% water. 300' and Ran				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string. 4- Gih with packer on tubing string . set packer at 10000'. Tested casing 500 3- Rig up swab tools, swabbed well for 2 days. Recovered 85 bbl fluid 1% 4- Pooh and laid down 2-7/8", N80 tubing in singles. Rig down service rig. 5- MIRU Baker Atlas Eline. Ran PDK-100, & GR/CCL log from 12550'-9 CBL/CCL/VDL/GR log from 12550'-10000'. 6- Pooh and rig down Baker Atlas.	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion 'casing to 12621'. laid down bit and scraper. # for 15 MTS. Held , OK. oil cut, and 99% water. 300' and Ran e and belief. I further certify that any pit or below-				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. INFORM OCD BEFORE RIGGING UP ON THE WELL. 1- MIRU service rig. Spotted reverse unit. 2- Bleed off 35 psi from casing string. GIH with bit and scraper, cleared 7' 3- Attempt to circulated well clean with out success pooh with tubing string. 4- Gih with packer on tubing string . set packer at 10000'. Tested casing 500 3- Rig up swab tools, swabbed well for 2 days. Recovered 85 bbl fluid 1% 4- Pooh and laid down 2-7/8", N80 tubing in singles. Rig down service rig. 5- MIRU Baker Atlas Eline. Ran PDK-100, & GR/CCL log from 12550'-5 CBL/CCL/VDL/GR log from 12550'-10000'. 6- Pooh and rig down Baker Atlas. 7- Closed well in Pending Well evaluation.	T JOB d give pertinent dates, including estimated date tach wellbore diagram of proposed completion 'casing to 12621'. laid down bit and scraper. # for 15 MTS. Held , OK. oil cut, and 99% water. 300' and Ran e and belief. I further certify that any pit or below-				

.

		0)	<u>p</u>		
Type or print name	-		E-mail address:			Telephone No.	
For State Use Only APPROVED BY:	Chis	William	OC DESTRICT SUP TITLE	TRANSONAG	ENERAL MANA	APR GEP _{DATE}	0 2 2008
Conditions of Approva		Meida Submit c	com of (y integri		Recore