	State of New Me			Form C-103
Office District I	Energy, Minerals and Natur	al Resources	WELL ADINO	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240			WELL API NO. 30-025-31560	
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease	
District III	· · · · · · · · · · · · · · · · · · ·		_ <del></del>	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8	/303		
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No	). 
I (DO NOT USE THIS FORM FOR PROPO	ES AND REPORTS ON WEL	OR PLUG BACK TO A	7. Lease Name or Unit Agre Arrowhead Grayburg Unit	
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ATION FOR PERMIT" (FORM C-10		<u> </u>	
1. Type of Well: Oil Well X Gas Well	Other	CEIVEL	8. Well Number 199	
2. Name of Operator XTO Energy, Inc.		JAN 2 5 2008	9. OGRID Number 005380	
3 Address of Operator		nno oo	10. Pool name or Wildcat	
200 N. Loraine, Ste. 800 4. Well Location	Midland, TX 79701	BBS UC	Agrowhead: Grayburg	
	2015		15501	
Unit Letter :_ a	2315' feet from the Nor	line and	feet from the	West line
Section 7	Township 22S	Range 37E	NMPM County	, Lea
And the state of t	11. Elevation (Show whether	DR, RKB, RT, GR, et	c.)	
Pit or Below-grade Tank Application				
Pit type Depth to Groundwater .	Distance from nearest fresh	water well Dis	tance from nearest surface water _	
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Construction	on Material	
12. Check A	ppropriate Box to Indicate	Nature of Notice,	Report, or Other Data	
NOTICE OF INTE	PLUG AND ABANDON	REMEDIAL WORK	SEQUENT REPORT C	RING CASING
			SEQUENT REPORT C  ALTER  NG OPNS.  PLUG	RING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	SEQUENT REPORT C  ALTER  NG OPNS.  PLUG	RING CASING  AND
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND	SEQUENT REPORT C  ALTER  NG OPNS.  PLUG	RING CASING  AND
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS COMPLETION C	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: rtinent details, and give	SEQUENT REPORT O  ALTER  NG OPNS. PLUG  ABAND  PROPERT OF THE PORT	AND DONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: Clean, Stimulate & Completed of starting any proposed work). or recompletion.	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS COMPLETION Wert to Injection X operations. (Clearly state all per SEE RULE 1103. For Multiple	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: ctinent details, and give	SEQUENT REPORT O  ALTER  NG OPNS. PLUG ABANE  Proposed Abane	AND DONMENT   imated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THE COMPONENT OF THE COMPONE	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS COMPLETION Wert to Injection Charles state all per SEE RULE 1103. For Multiple Court CIBP 3650'. Tag TD 3	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: ctinent details, and give	SEQUENT REPORT O  ALTER  NG OPNS. PLUG ABANE  Proposed Abane	AND DONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: Clean, Stimulate & Completed of starting any proposed work). or recompletion.	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS COMPLETION Wert to Injection Completion SEE RULE 1103. For Multiple 11 out CIBP 3650'. Tag TD 30 workstring.	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER:  rtinent details, and give completions: Attach	SEQUENT REPORT O  ALTER  NG OPNS. PLUG  ABANI  Pe pertinent dates, including est  wellbore diagram of proposed  Clean.	AND DONMENT   imated date d completion  4 - 834
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THE Clean, Stimulate & Comparison of Starting any proposed work). Or recompletion.  1. RUPU. Install BOP. Dril 2. TIH with Sonic Hammer of Ammer and open hammer open hole with 5	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS COMPLETION Wert to Injection Completion SEE RULE 1103. For Multiple 11 out CIBP 3650'. Tag TD 30 workstring.	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER:  ctinent details, and give completions: Attach	SEQUENT REPORT C  ALTER  NG OPNS. PLUG  ABAND  Pe pertinent dates, including est  wellbore diagram of proposed  clean.  Price pit. Close in backsi	AND DONMENT   imated date d completion   4 - 834  de and sonic
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THE Clean, Stimulate & Community Company Company Company Company Proposed or completed of starting any proposed work). Or recompletion.  1. RUPU. Install BOP. Dril 2. TIH with Sonic Hammer of Ammer and open hammer open hole with 5 30 bbls 9# brine.	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS COMPLETION  Wert to Injection X  Operations. (Clearly state all per SEE RULE 1103. For Multiple on workstring.  In out CIBP 3650'. Tag TD is not workstring.  In hole w/9# brine while complete the second of the s	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: rtinent details, and give c Completions: Attach	SEQUENT REPORT C  ALTER  NG OPNS. PLUG ABAND  Repertment dates, including est a wellbore diagram of proposed clean.  Price pit. Close in backsi lax on backside. Flush according to the control of the co	imated date d completion  4 - 834  de and sonic cid with
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THE COMPONS TO THE COMPONS	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  vert to Injection X  operations. (Clearly state all per SEE RULE 1103. For Multiple on workstring. en hole w/9# brine while complete w/9# brine while complete w/9# brine while complete w/9# acid in injector and new 2-3/8" IPC tube	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: ctinent details, and give Completions: Attach 3881' & circulate irculating to reve ction mode, 500# m	SEQUENT REPORT C  ALTER  NG OPNS. PLUG ABAND  Pe pertinent dates, including estrates wellbore diagram of proposed clean.  Perse pit. Close in backsi hax on backside. Flush acts and sackside. Flush acts and sackside. Second Sec	imated date d completion  de and sonic cid with dection line
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THE COMPONSITION OTHER: Clean, Stimulate & Components of Starting any proposed work). Or recompletion.  1. RUPU. Install BOP. Dril 2. TIH with Sonic Hammer of Sonic Hammer open hole with Sonic Hammer open ho	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS COMPLETION  Wert to Injection X  Operations. (Clearly state all per SEE RULE 1103. For Multiple on workstring.  En hole w/9# brine while complete w/9# brine w/9# bri	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER:  ctinent details, and give completions: Attach  3881' & circulate  irculating to revection mode, 500# m  ing. Set packer @ to PLC at Header a	SEQUENT REPORT C  ALTER  NG OPNS. PLUG  ABANI  Perpertinent dates, including est  wellbore diagram of proposed  clean.  Perse pit. Close in backsi  lax on backside. Flush ac  3625'. MIT well. Lay inj  and Wonderware. CTI. Star	imated date d completion  de and sonic cid with lection line et well in-
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING THE Clean, Stimulate & Community Company of Starting any proposed work).  1. RUPU. Install BOP. Dril 2. TIH with Sonic Hammer of 3. RU sonic hammer and open hammer open hole with 5. 30 bbls 9# brine.  4. RIH with injection pack and tie into header at jection @ 250 BWIPD for	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS COMPLETION  Wert to Injection X  Operations. (Clearly state all per SEE RULE 1103. For Multiple on workstring. On workstring. On hole w/9# brine while complete with the with the complete with the with the complete with the with th	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: rtinent details, and give c Completions: Attach 3881' & circulate irculating to reve ction mode, 500# m ing. Set packer @ to PLC at Header a 50 BWIPD until des	SEQUENT REPORT C  ALTER  NG OPNS. PLUG  ABAND  Repertment dates, including est  a wellbore diagram of proposed  clean.  Price pit. Close in backsi  ax on backside. Flush ac  3625'. MIT well. Lay inj  and Wonderware. CTI. Start  stred pressure of 736 psi	imated date d completion  de and sonic cid with jection line it well inits reached.
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Clean, Stimulate & Com  13. Describe proposed or completed of starting any proposed work). or recompletion.  1. RUPU. Install BOP. Dril 2. TIH with Sonic Hammer of an and open hammer open hole with 5 30 bbls 9# brine.  4. RIH with injection pack and tie into header at jection @ 250 BWIPD for I hereby certify that the information at the start of t	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Vert to Injection  Operations. (Clearly state all per SEE RULE 1103. For Multiple 11 out CIBP 3650'. Tag TD 30 on workstring.  On workstring.  On hole w/9# brine while complete with a complete with a complete to the lossed according to NMOCD guideline.	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: rtinent details, and give completions: Attach 3881' & circulate irculating to reve ction mode, 500# m ing. Set packer @ to PLC at Header a 50 BWIPD until des	SEQUENT REPORT C  ALTER  NG OPNS. PLUG  ABAND  Repertment dates, including est  a wellbore diagram of proposed  clean.  Price pit. Close in backsi  ax on backside. Flush ac  3625'. MIT well. Lay inj  and Wonderware. CTI. Startified pressure of 736 psi  e and belief. I further certify that	imated date d completion  de and sonice did with dection line t well inis reached.
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Clean, Stimulate & Com  13. Describe proposed or completed of starting any proposed work). or recompletion.  1. RUPU. Install BOP. Dril 2. TIH with Sonic Hammer of 3. RU sonic hammer and open hammer open hole with 5. 30 bbls 9# brine.  4. RIH with injection pack and tie into header at jection @ 250 BWIPD for I hereby certify that the information all	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Vert to Injection  Operations. (Clearly state all per SEE RULE 1103. For Multiple on workstring.  In out CIBP 3650'. Tag TD is not workstring.  On workstring.  On hole w/9# brine while complete with a complete on the losed according to NMOCD guideline.  TIT	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER:  rtinent details, and give completions: Attach  3881' & circulate  irculating to revection mode, 500# m  ing. Set packer @ to PLC at Header at 50 BWIPD until des  best of my knowledges best of my knowledges  , a general permit  LE Regulator	SEQUENT REPORT C  ALTER  NG OPNS. PLUG  ABAND  Proposed  Repertment dates, including est  Repertmen	imated date d completion  de and sonic cid with jection line is reached.  any pit or below- D-approved plan
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Clean, Stimulate & Com  13. Describe proposed or completed of starting any proposed work). or recompletion.  1. RUPU. Install BOP. Dril 2. TIH with Sonic Hammer of 3. RU sonic hammer and open hammer open hole with 5 30 bbls 9# brine.  4. RIH with injection pack and tie into header at jection @ 250 BWIPD for I hereby certify that the information at the constructed or complete	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Vert to Injection  I operations. (Clearly state all per SEE RULE 1103. For Multiple on workstring.  In out CIBP 3650'. Tag TD in workstring.  In hole w/9# brine while complete with a complete to the losed according to NMOCD guideline.  TIT  E-recorded.	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER:  rtinent details, and give completions: Attach  3881' & circulate  irculating to revection mode, 500# m  ing. Set packer @ to PLC at Header at 50 BWIPD until des  best of my knowledge s, a general permit  LE Regulator  nail address: kr	SEQUENT REPORT C  ALTER  NG OPNS. PLUG  ABAND  PROPOSE  Repertment dates, including estrates and backside. Flush act and backside. Flush act and backside and backside. Startified pressure of 736 pside and backside	imated date d completion  de and sonic cid with liection line is reached.  any pit or below- D-approved plan   01/16/08  432-620-6740
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Clean, Stimulate & Com  13. Describe proposed or completed of starting any proposed work). or recompletion.  1. RUPU. Install BOP. Dril 2. TIH with Sonic Hammer of 3. RU sonic hammer and open hammer open hole with 5 30 bbls 9# brine. 4. RIH with injection pack and tie into header at jection @ 250 BWIPD for  I hereby certify that the information also constructed or c	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Vert to Injection  I operations. (Clearly state all per SEE RULE 1103. For Multiple on workstring.  In out CIBP 3650'. Tag TD in workstring.  In hole w/9# brine while complete with a complete to the losed according to NMOCD guideline.  TIT  E-recorded.	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER:  rtinent details, and give completions: Attach  3881' & circulate  irculating to revection mode, 500# m  ing. Set packer @ to PLC at Header at 50 BWIPD until des  best of my knowledge s, a general permit  LE Regulator  nail address: kr	SEQUENT REPORT C  ALTER  NG OPNS. PLUG  ABAND  PROPOSE  Repertment dates, including estrates and backside. Flush act and backside. Flush act and backside and backside. Startified pressure of 736 pside and backside	imated date d completion  de and sonic cid with liection line is reached.  any pit or below- D-approved plan   01/16/08  432-620-6740
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Clean, Stimulate & Com  13. Describe proposed or completed of starting any proposed work). or recompletion.  1. RUPU. Install BOP. Dril 2. TIH with Sonic Hammer of 3. RU sonic hammer and open hammer open hole with 5 30 bbls 9# brine. 4. RIH with injection pack and tie into header at jection @ 250 BWIPD for  I hereby certify that the information also constructed or c	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Vert to Injection  I operations. (Clearly state all per SEE RULE 1103. For Multiple on workstring.  In out CIBP 3650'. Tag TD in workstring.  In hole w/9# brine while complete with a complete to the losed according to NMOCD guideline.  TIT  E-recorded.	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER:  rtinent details, and give completions: Attach  3881' & circulate  irculating to revection mode, 500# m  ing. Set packer @ to PLC at Header at 50 BWIPD until des  best of my knowledge s, a general permit  LE Regulator  nail address: kr	SEQUENT REPORT C  ALTER  NG OPNS. PLUG  ABAND  PROPOSE  Repertment dates, including est  a wellbore diagram of proposed  Clean.  Clean.  Proposed  Clean.  Clean	imated date d completion  de and sonic cid with liection line is reached.  any pit or below- D-approved plan   01/16/08  432-620-6740