Submit 3 Copies To Appropriate District Office		New Mexico and Natural Resources		Form C- May 27, 2	
District I 1625 N. French Dr., Hobbs, NM 87240	8,,		WELL API NO.	_	
District II	OIL CONSER	VATION DIVISION		5-34826	
1301 W. Grand Ave., Artesia, NM 88210 District III		h St. Francis Dr.	5. Indicate Type of	-	
1000 Rio Brazos Rd., Aztec, NM 87410		Fe, NM 87505	STATE	X FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 8'			6. State Oil & Ga	as Lease No.	
SUNDRY NO DO NOT USE THIS FORM FOR PR DIFFERENT RESERVOIR. USE "AP	TICES AND REPORTS OPOSALS TO DRILL OR TO PLICATION FOR PERMIT" (F	ON WELLS DEERENORFLOGBACK OF ORMOSION ROR SUCH	7. Lease Name or Eunice Monumen	r Unit Agreement Name It South Unit —	:
PROPOSALS.) 1. Type of Well:	_	MAD 0 - 2000	8. Well Number		
Oil Well X Gas Well	Other	MAR 0 7 2008	7	735 -	
 Name of Operator XTO Energy, Inc. 		HARRSO	9. OGRID Numbe	er 5380	
3. Address of Operator	· · · · · · · · · · · · · · · · · · ·		10. Pool name or		/
200 N. Loraine, Ste. 80	0 Midland, TX 7970	01		it: Grayburg-San And	<u>lre</u>
4. Well Location					
Unit Letter D:	275' feet from th	e North line and	1220' feet fro	om the West	lin
		21S Range 36E		County Lea	
Section 15		whether DR, RKB, RT, GR,			
				*	
Pit type Depth to Groundwa					
Pit Liner Thickness:	mil Below-Grade Tan	k: Volumebbls; Construc	ction Material		
12. Chec	k Appropriate Box to	Indicate Nature of Notic	e, Report, or Othe	er Data	
12. Chec	k Appropriate Box to	Indicate Nature of Notic	e, Report, or Othe	er Data	 3 [
12. Chec NOTICE OF IN PERFORM REMEDIAL WORK	k Appropriate Box to	Indicate Nature of Notic SU	e, Report, or Othe	er Data PORT OF: ALTERING CASING PLUG AND	 Э [
12. Chec NOTICE OF IN PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [* Appropriate Box to NTENTION TO: PLUG AND ABAND	Indicate Nature of Notic SU	e, Report, or Othe BSEQUENT RE C	er Data PORT OF: ALTERING CASING	
12. Chec NOTICE OF IN PERFORM REMEDIAL WORK	Image: Second State State Image: Second State Image: Seco	Indicate Nature of Notic SU ON C REMEDIAL WORK COMMENCE DRIL	e, Report, or Othe BSEQUENT RE C	er Data PORT OF: ALTERING CASING PLUG AND	 € [[
12. Chec NOTICE OF IN PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DTHER: Acid Stimulation 13. Describe proposed or compl	Image: Second state of the second s	Indicate Nature of Notic SU ON C REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB	e, Report, or Othe BSEQUENT RE LING OPNS. ID ID	er Data PORT OF: ALTERING CASING PLUG AND ABANDONMENT acluding estimated date	
12. Chec NOTICE OF IN PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DTHER: Acid Stimulation 13. Describe proposed or compl of starting any proposed wo or recompletion. 1. MIRU PU. Install BOI 2. RIH w/6-1/8" bit, 7	Image: Second state state Image: Second state Image: Seco	Indicate Nature of Notic SU ON REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB X OTHER: tate all pertinent details, and g or Multiple Completions: Atta (PBTD 3,921'). tbg. Circulate clean. P	ee, Report, or Othe BSEQUENT RE LING OPNS. ID give pertinent dates, in ach wellbore diagram of	er Data PORT OF: ALTERING CASING PLUG AND ABANDONMENT Including estimated date of proposed completion	l
12. Chec NOTICE OF IN PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DTHER: Acid Stimulation 13. Describe proposed or compl of starting any proposed wo or recompletion. 1. MIRU PU. Install BOI 2. RIH w/6-1/8" bit, 7' RU stripping head. N 3. SH perfs w/9# brine	Image: Second state of the second s	Indicate Nature of Notic SU ON CREMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB X OTHER: tate all pertinent details, and g or Multiple Completions: Atta	ee, Report, or Othe BSEQUENT RE LING OPNS. ID ive pertinent dates, in ach wellbore diagram of U & RIH w/Sonic H hole clean. Close	er Data EPORT OF: ALTERING CASING PLUG AND ABANDONMENT including estimated date of proposed completion lammer on 2-7/8" tbg in backside and Sh]
12. Chec NOTICE OF IN PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: Acid Stimulation 13. Describe proposed or compl of starting any proposed wo or recompletion. 1. MIRU PU. Install BOI 2. RIH w/6-1/8" bit, 7 RU stripping head. M 3. SH perfs w/9# brine perfs w/1,800 gals, 4. Flush acid with 25 M	Image: Second state state Image: Second state Image: Seco	Indicate Nature of Notic SU ON REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB X OTHER: tate all pertinent details, and g or Multiple Completions: Atta (PBTD 3,921'). tbg. Circulate clean. P st lines to 3,000 psi. reverse pit. Circulate	ee, Report, or Othe BSEQUENT RE LING OPNS. ID ib rive pertinent dates, in ach wellbore diagram of PU & RIH w/Sonic H hole clean. Close essure of 2,000# t n tool.	er Data EPORT OF: ALTERING CASING PLUG AND ABANDONMENT accluding estimated date of proposed completion lammer on 2-7/8" tbg in backside and Should be subing & 500# on bac	g. H
12. Chec NOTICE OF IN PERFORM REMEDIAL WORK [PERFORM REMEDIAL WORK [PULL OR ALTER CASING [OTHER: Acid Stimulation 13. Describe proposed or compl of starting any proposed wo or recompletion. 1. MIRU PU. Install BOI 2. RIH w/6-1/8" bit, 7 RU stripping head. M 3. SH perfs w/9# brine perfs w/1,800 gals, 4. Flush acid with 25 M 5. Flow back or RU swal rate. RWTP. RDMOPU.	Image: Second structure	Indicate Nature of Notic SU ON CREMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB XOTHER: tate all pertinent details, and gor Multiple Completions: Atta (PBTD 3,921'). tbg. Circulate clean. P st lines to 3,000 psi. reverse pit. Circulate jection mode w/a max pre p ball to shift sleeve i ad. ND BOP. NU WH. RIH w ete to the best of my knowled D guidelines , a general perm	ee, Report, or Othe IBSEQUENT RE LING OPNS. ID vive pertinent dates, in ach wellbore diagram of U & RIH w/Sonic H hole clean. Close essure of 2,000# t n tool. v/test sub sized f dge and belief. I furthe in or an (attached) and	er Data EPORT OF: ALTERING CASING PLUG AND ABANDONMENT ABANDON ABA].].].].].].].].].].].].].]
12. Chec NOTICE OF IN PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER: Acid Stimulation 13. Describe proposed or completed of starting any proposed wo or recompletion. 1. MIRU PU. Install BOI 2. RIH w/6-1/8" bit, 7 RU stripping head. M 3. SH perfs w/9# brine perfs w/1,800 gals, 4. Flush acid with 25 M 5. Flow back or RU swal	Image: Second structure	Indicate Nature of Notic SU ON REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB X OTHER: tate all pertinent details, and g or Multiple Completions: Atta (PBTD 3,921'). tbg. Circulate clean. P st lines to 3,000 psi. reverse pit. Circulate jection mode w/a max pre p ball to shift sleeve i ad. ND BOP. NU WH. RIH w ete to the best of my knowled D guidelines , a general perm TITLE Regulat	ee, Report, or Othe BSEQUENT RE LING OPNS. ID ID vive pertinent dates, in ach wellbore diagram of PU & RIH w/Sonic H hole clean. Close essure of 2,000# t n tool. 1/test sub sized f dge and belief. I furthe it or an (attached) alto tory Analyst	er Data EPORT OF: ALTERING CASING PLUG AND ABANDONMENT ABANDON ABAND	[[]
12. Chec NOTICE OF IN ERFORM REMEDIAL WORK [EMPORARILY ABANDON [FULL OR ALTER CASING [OTHER: Acid Stimulation 13. Describe proposed or compl of starting any proposed wo or recompletion. 1. MIRU PU. Install BOI 2. RIH w/6-1/8" bit, 7 RU stripping head. N 3. SH perfs w/9# brine perfs w/1,800 gals, 4. Flush acid with 25 N 5. Flow back or RU swal rate. RWTP. RDMOPU.	Image: Second structure Image: Second structure Image: Second structure Image: Second structure <td>Indicate Nature of Notic SU ON REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB X OTHER: tate all pertinent details, and g or Multiple Completions: Atta (PBTD 3,921'). tbg. Circulate clean. P st lines to 3,000 psi. reverse pit. Circulate jection mode w/a max pre p ball to shift sleeve i ad. ND BOP. NU WH. RIH w ete to the best of my knowled D guidelines , a general perm TITLE Regulat</td> <td>ee, Report, or Othe IBSEQUENT RE LING OPNS. ID ID ID V & RIH w/Sonic H hole clean. Close essure of 2,000# t n tool. //test sub sized f lige and belief. I furthe itor an (attached) alto tory Analyst kristy ward@xtoen</td> <td>er Data EPORT OF: ALTERING CASING PLUG AND ABANDONMENT ABANDON ABAND</td> <td>]]]]]]]]]]]]]]]]]]]</td>	Indicate Nature of Notic SU ON REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB X OTHER: tate all pertinent details, and g or Multiple Completions: Atta (PBTD 3,921'). tbg. Circulate clean. P st lines to 3,000 psi. reverse pit. Circulate jection mode w/a max pre p ball to shift sleeve i ad. ND BOP. NU WH. RIH w ete to the best of my knowled D guidelines , a general perm TITLE Regulat	ee, Report, or Othe IBSEQUENT RE LING OPNS. ID ID ID V & RIH w/Sonic H hole clean. Close essure of 2,000# t n tool. //test sub sized f lige and belief. I furthe itor an (attached) alto tory Analyst kristy ward@xtoen	er Data EPORT OF: ALTERING CASING PLUG AND ABANDONMENT ABANDON ABAND]]]]]]]]]]]]]]]]]]]

Conditions of Approval, if any:

,