
Office and the state of the sta	nit 3 Copies To Appropried Dispet State of New Mexico contents and Natural Resources					Form	C-103
1625 N. French Dr., Hobbs, NM 8824			WELL API NO. 30-025-2		1, 2007		
1301 W. Grand Ave., Artesia, NMAS	L CONSEI	ERVATION DIVISION outh St. Francis Dr.		5. Indicate Type	e of Lease		
1000 Rio Brazos Rd., Azus Maria Fe District IV 1220 S. St. Francis Dr., Sama Fe 87505					STATE 6. State Oil & O V-731		
SUNDRY N (DO NOT USE THIS FORM FOR PE DIFFERENT RESERVOIR. USE "A	DRILL OR TO DE			7. Lease Name or Unit Agreement Name New Mexico E.F. State			
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other					8. Well Number #3		
2. Name of Operator Pronghorn	ent Corpo	oration 9. OG		9. OGRID Num	GRID Number 122811		
3. Address of Operator P. 0. Box				10. Pool name o			
4. Well Location			· · · · · · · · · · · · · · · · · · ·				_
Unit LetterM	:990 :	feet from th	south	line and	330 'feet fr	om theWest	line
Section 17				ange 33 E		County Lea	
And the second s	11. El	evation (Show	whether DR,	, RKB, RT, GR, etc.,		e englisher i series Timo e englisher english	e and a
Pit or Below-grade Tank Application						and the second s	
Pit Location: ULSectT							
Distance from nearest surface wat	erBe	low-grade Tank I	ocation UL_	SectTwp	Rng	;	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL					SEQUENT RE	EPORT OF: ALTERING CASIN	lG □
TEMPORARILY ABANDON		IGE PLANS		COMMENCE DRI		PLUG AND ABANDONMENT	
PULL OR ALTER CASING	☐ MULT COMF	IPLE PLETION		CASING TEST AN CEMENT JOB	ND 🗆		
OTHER:				OTHER: Salt			X
13. Describe proposed or configuration of starting any proposed	dwork). SEI Move in	ERULE1103. and rig u	For Multipl p. Unse	e Completions: Att	ach wellbore diag	tes, including estima ram of proposed con bing and pack	nnletion
Re-dress packer. 3. Set packer Prepare well for	- pressur injectio	ce test ca on. 4. P	singc ressure	tubing. Pre kay. Circul	essure testi ate hole wi or Mechanica	ngokay. th packer flu 1 Integrity T	er
Re-dress packer. 3. Set packer Prepare well forOkay. 5. Rig	- pressur injection down. M	re test ca on. 4. P Move out.	sing,c ressure Clean I	tubing. Prebkay. Circul test well for location. (Cost of my knowledge stoff my knowledge	essure testi ate hole wi or Mechanica Chart enclos	ngokay. th packer flu 1 Integrity T ed.)	er
Re-dress packer. 3. Set packer Prepare well forOkay. 5. Rig mereby certify that the informate that has been/will be constructed. H. A.	- pressur injection down. M	re test ca on. 4. P Move out.	singc ressure Clean 1 ete to the be	tubing. Prebkay. Circul test well for location. (Cost of my knowledge stoff my knowledge	essure testi ate hole wi or Mechanica Chart enclos	ngokay. th packer flu 1 Integrity T ed.) Her certify that any pit o native OCD-approved p	id. est.
Re-dress packer. 3. Set packer Prepare well forOkay. 5. Rig	- pressur injectic down. N	re test ca on. 4. P Move out.	singc ressure Clean 1 ete to the be	tubing. Pre bkay. Circul test well for Location. (Construction) st of my knowledge characterist construction PARTNER	essure testi ate hole wi or Mechanica Chart enclos cand belief. I furth or an (attached) altern	ngokay. th packer flu 1 Integrity T ed.)	id. lest. r below-lan [].
Re-dress packer. 3. Set packer - Prepare well forOkay. 5. Rig mereby certify that the informate tank has been/will be constructed. GNATURE	- pressur injectic down. N	re test ca on. 4. P Move out.	singc ressure Clean I ete to the be guidelines	tubing. Pre bkay. Circul test well for Location. (Construction) st of my knowledge characterist construction PARTNER	essure testi ate hole wi or Mechanica Chart enclos cand belief. I furth or an (attached) altern	ngokay. th packer flu 1 Integrity T ed.) her certify that any pit o native OCD-approved p DATE11/07/	id. lest. r below-lan [].



Crossiffeer mand Ram mand 11/7/7 30 min chart