Submit 3 Copies To Appropriate District State of New Mex	ico Form C-103
Office District I 1625 N French Dr., Hobbs, NM87 (Fig. 1)	1 Resources May 27, 2004
1625 N French Dr., Hobbs, NM87	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. France	DIVISION 30-025-01014 '
District III 1220 South St. Fran	cis Dr. 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 8741 APR 3 7 2008 Santa Fe, NM 8741	STATE 🖫 FEE 🗆
District IV 1220 S. St. Francis Dr., Santa Fee M. 100 P. 1	6. State Oil & Gas Lease No. 24983
SUNDRY NOTICES AND REPORTS ON WELL	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) PROPOSALS.)	R PLUG BACK TO A STINITE BITD
1. Type of Well:	8. Well Number
Oil Well X Gas Well Other	1
2. Name of Operator	9. OGRID Number
PALADIN ENERGY CORP.	164070
3. Address of Operator	10. Pool name or Wildcat
10290 Monroe Drive, Suite 301, Dallas, TX 75229	BAGIEY - PENN; Permo; North
4. Well Location	/
Unit Letter <u>E</u> : 1980 feet from the NORT	H line and 660 feet from the WEST line
Section 34 Township 11 S R	ange 33 E NMPM County LEA
11. Elevation (Show whether D	
Pit or Below-grade Tank Application ☐ or Closure ☐	BMAを含まれた。 BMAを含まれた。 ATMAにおいて、 ATMAにおいて ATMAにおいて ATMAにおいて ATMAにおいて ATMAにおいて ATMAにおいて ATMAにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて ATMaにはいて
Pit type Depth to Groundwater Distance from nearest fresh	water well Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume	!
Pit Liner Inickness: mii Below-Grade Ialik: Volume_	
10 Ol 1 A Cata Danda Indiana	The CNI die December 2011 December 2011
NOTICE OF INTENTION TO:	Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO:	-
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON	SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND COMMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. COMMENCE DRILLING OPNS. COMMENT DESCRIPTION OF THE C
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pertof starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of 3-31-08 Tag & plug 5,231'. #3 3-31-08 - Cut & pull care	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Completions: Attach wellbore diagram of proposed completion N/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. sg. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/2%
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pertof starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of 3-31-08 Tag & plug 5,231'. #3 3-31-08 - Cut & pull can cacl. W.O.C. & tag a.m 4,186'. 4-2-08 #5 - 3,824'	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Intent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion A/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. ag. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/2% 60 sx. cmt. W.O.C. & tag. 4-3-08 Tag - 3,717'.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pertof starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of the starting and	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Intent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion A/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. sg. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/2% 60 sx. cmt. W.O.C. & tag. 4-3-08 Tag - 3,717'. -3-08 #7 - Perf. @380'. Sqz. 80 sx. cmt. W.O.C. to
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pertof starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of 3-31-08 Tag & plug 5,231'. #3 3-31-08 - Cut & pull can cacl. W.O.C. & tag a.m 4,186'. 4-2-08 #5 - 3,824'	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Intent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion A/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. sg. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/2% 60 sx. cmt. W.O.C. & tag. 4-3-08 Tag - 3,717'. -3-08 #7 - Perf. @380'. Sqz. 80 sx. cmt. W.O.C. to perface. Cement did not fall.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pertof starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of the starting and	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Intent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion A/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. sg. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/2% 60 sx. cmt. W.O.C. & tag. 4-3-08 Tag - 3,717'. -3-08 #7 - Perf. @380'. Sqz. 80 sx. cmt. W.O.C. to
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pertof starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of the starting and	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Intent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion N/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. sg. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/2% 1.60 sx. cmt. W.O.C. & tag. 4-3-08 Tag - 3,717'. 1.3-08 #7 - Perf. @380'. Sqz. 80 sx. cmt. W.O.C. to irrface. Cement did not fall Approved for plugging of well hore only. Liability under bona is retained pending receipt of C.103 (Subsequent Report of Well Plugging)
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pertof starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of 3-31-08 Tag & plug 5,231'. #3 3-31-08 - Cut & pull can Cacl. W.O.C. & tag a.m 4,186'. 4-2-08 #5 - 3,824' #6 - 1,744' - 40 sx. cmt. T.O.C. Calculate 1,600'. 4- tag. 4-4-08 Tag & plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx.	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING CASING ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Intent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion N/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. sg. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/2% 60 sx. cmt. W.O.C. & tag. 4-3-08 Tag - 3,717'. -3-08 #7 - Perf. @380'. Sqz. 80 sx. cmt. W.O.C. to Inface. Cement did not fall. Approved for plugging of well bore only Liability under bone is retained pending receipt of C.103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pertof starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of 3-31-08 Tag & plug 5,231'. #3 3-31-08 - Cut & pull caccacl. W.O.C. & tag a.m 4,186'. 4-2-08 #5 - 3,824' #6 - 1,744' - 40 sx. cmt. T.O.C. Calculate 1,600'. 4- tag. 4-4-08 Tag & plug @240'. 64' - pump 30 sx. to so I hereby certify that the information above is true and complete to the lateral of the la	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Completions: Attach wellbore diagram of proposed completion A/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. sg. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/2% 60 sx. cmt. W.O.C. & tag. 4-3-08 Tag - 3,717'. -3-08 #7 - Perf. @380'. Sqz. 80 sx. cmt. W.O.C. to inface. Cement did not fall Approved for plugging of well bore only. Liability under bone is retained pending receipt of C:00' (Subsequent Report of Well Plugging) which may be found at OCD Web Page under test of my knowledge and belief. Hurther certify that may pit or below-
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pertof starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of 3-31-08 Tag & plug 5,231'. #3 3-31-08 - Cut & pull can Cacl. W.O.C. & tag a.m 4,186'. 4-2-08 #5 - 3,824' #6 - 1,744' - 40 sx. cmt. T.O.C. Calculate 1,600'. 4- tag. 4-4-08 Tag & plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx. to starting and plug @240'. 64' - pump 30 sx.	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND ABANDONMENT OTHER: Intent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion A/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. ag. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/28 ag. 4,300'. 4-1-08 #4 - 4,350'. 5
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of 3-31-08 Tag & plug 5,231'. #3 3-31-08 - Cut & pull concern Cacl. W.O.C. & tag a.m 4,186'. 4-2-08 #5 - 3,824' #6 - 1,744' - 40 sx. cmt. T.O.C. Calculate 1,600'. 4- tag. 4-4-08 Tag & plug @240'. 64' - pump 30 sx. to start of the legrade tank has been/will be constructed or closed/according to NMOCD guidelines. SIGNATURE TITL	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING CASING ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND ABANDONMENT CEMENT JOB OTHER: Intent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion A/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. sg. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/2% A60 sx. cmt. W.O.C. & tag. 4-3-08 Tag - 3,717'. -3-08 #7 - Perf. @380'. Sqz. 80 sx. cmt. W.O.C. to irrface. Cement did not fall Approved for plugging of well bore only. Liability under bone is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under the properties of the perfect of the properties of the perfect of the p
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of 3-31-08 Tag & plug 5,231'. #3 3-31-08 - Cut & pull concern Cacl. W.O.C. & tag a.m 4,186'. 4-2-08 #5 - 3,824' #6 - 1,744' - 40 sx. cmt. T.O.C. Calculate 1,600'. 4- tag. 4-4-08 Tag & plug @240'. 64' - pump 30 sx. to start of the legrade tank has been/will be constructed or closed/according to NMOCD guidelines. SIGNATURE TITL	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND ABANDONMENT OTHER: Intent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion A/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. ag. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/28 ag. 4,300'. 4-1-08 #4 - 4,350'. 5
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of 3-31-08 Tag & plug 5,231'. #3 3-31-08 - Cut & pull case Cacl. W.O.C. & tag a.m 4,186'. 4-2-08 #5 - 3,824' #6 - 1,744' - 40 sx. cmt. T.O.C. Calculate 1,600'. 4-tag. 4-4-08 Tag & plug @240'. 64' - pump 30 sx. to sufficiently that the information above is true and complete to the legrade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE TITL Type or print name RANDALL MINEAR	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING CASING ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND ABANDONMENT COMMENT JOB OTHER: Part of the proposed completion N/M.L.F. #2 - 5500' - 25 sx. cmt. W.O.C. & tag a.m. seg. 4,300'. 4-1-08 #4 - 4,350'. 50 sx. cmt. w/2% 60 sx. cmt. W.O.C. & tag. 4-3-08 Tag - 3,717'. 3-08 #7 - Perf. @380'. Sqz. 80 sx. cmt. W.O.C. to irrface. Cement did not fall Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under lest of my knowledge and Delect. Harther retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under lest of my knowledge and Delect. Harther retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under lest of my knowledge and Delect. Harther retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under lest of my knowledge and Delect. Harther retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under lest of my knowledge and Delect. Harther retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under lest of my knowledge and Delect. Harther retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under lest of my knowledge and Delect. Harther retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under lest of my knowledge and Delect. Harther retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under lest of my knowledge and Delect. Harther retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under lest of my knowledge and Delect. Harther retained p
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 3-28-08 #1 - R.I.H. tbg. Tag 8,422'. Circulate hole of 3-31-08 Tag & plug 5,231'. #3 3-31-08 - Cut & pull case Cacl. W.O.C. & tag a.m 4,186'. 4-2-08 #5 - 3,824' #6 - 1,744' - 40 sx. cmt. T.O.C. Calculate 1,600'. 4-tag. 4-4-08 Tag & plug @240'. 64' - pump 30 sx. to sufficiently that the information above is true and complete to the legrade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE TITL Type or print name RANDALL MINEAR	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING CASING ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABAN