

MAY 2 3 2008	Form C-103
Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minoral and Matural Resources	May 27, 2004
District I French Dr. Hobbs NM 88240	WELL API NO
District II 1301 W. Grand Ave, Artesia, NM 88210 District III 1301 W. Grand Ave, Artesia, NM 88210 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III 1000 Rto Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM	
87505	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REFORMED ON PLUG BACK TO A (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Bagley
PROPOSALS.) 1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number 1
2. Name of Operator	9. OGRID Number 151323
Pride Energy Company 3. Address of Operator	10. Pool name or Wildcat N. Bagley Permo Penn
PO Box 701950, Tulsa, OK 74170	
4. Well Location Unit Letter A :560feet from theNorth line and560feet from theEast line	
Township 11S Range 33E	NMPM Lea County
Section 9 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4273' GR	
Pit or Below-grade Tank Application or Closure Distance from nearest surface water Distance from nearest surface water	
rit typebbls; C	onstruction Material
Pit Liner Thickness: mil Below-Grade Failt. Forume 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
SUBSEQUENT REPORT OF:	
TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OPNS.       PAND A       Commence Drilling opns.         PULL OR ALTER CASING       MULTIPLE COMPL       CASING/CEMENT JOB       Commence Drilling opns.	
	Drilling
OTHER: OT	
of starting any proposed work). SEE ROLL 1105. For Adding to a recompletion.	
Attempted to re-enter and wash down previously P&A'd wellbore. Unsuccessful in being able to get back inside of 8 5/8" casing at 827'.	
1. Give OCD 24 hours houce prior to communicity program of a 5/8" casing stub @ 827'. WOC, tag plug.	
<ol> <li>Circulate hole w/ 9.5 ppg mud.</li> <li>Spot a 100' cement plug across bottom of 13 3/8" casing, from 307' to 407', WOC 4 hrs, tag cement plug. Set a 10 sk cement</li> </ol>	
plug at surface. 5. Cut off casing and weld plate on casing. Erect standard 4' P&A marker. 6. Restore location.	
	1
	•
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-	
and tank has been/will be constructed of close second and the part of Dride Droduction ( 0 100.	
SIGNATURE	
Type or print name John W. Pride E-mail address: johnp@pride-energy.co	om Telephone No. 918-524-9200 リリド 0 5 2008
DATE	
APPROVED BY: <u>(Mus William</u> FIFEIns CT Suffering AV Alsana Com Conditions of Approval (if any): THE OIL CONSERVATION DIVISION <b>MUST</b>	
BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS	

