

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE 1 1 2008	OIL CONSERVATION DIVISIO	N
	1220 South St. Francis Dr.	WELL API NO.
DISTRICT 1625 WELLOW DELLOWS 8440	Santa Fe, NM 87505	30-025-28942
DISTRICT II	•	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210		STATE FEE FEE
DISTRICT III		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410		
SUNDRY NOTICES AND	D REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
1 1	O DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION	FOR PERMIT" (Form C-101) for such proposals)	Section 30
1 Type of Well:		8. Well No. 233
Oil Well Gas W	ell Other Injector	
2. Name of Operator		9. OGRID No. 157984
Occidental Permian Ltd.		10. Pool name or Wildcat Hobbs (G/SA)
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323		10.1 ool hame of whiteat Hoods (G/SA)
4. Well Location		
	n The South 1480	Feet From The West Line
Unit Letter K : 2455 Feet From	n The South 1480	Teet from the West Ellie
30	ownship 18-S Range	38-E NMPM Lea County
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	ation (Show whether DF, RKB, RT GR, etc.)	
3666' K	KB	
Pit or Below-grade Tank Application or C	Closure	
Pit Type Depth of Ground Water	i i	Distance from nearest surface water
	ade Tank: Volume bbls; Construction	
Pit Liner Thickness mil Below-Gra	ade Tank: Volumebois, Constituction	on Material
12	eta Dan ta Indianta Notura of Notica Domont	
12. Check Appropria	ate Box to Indicate Nature of Notice, Report	, or Other Data
NOTICE OF INTENTION		, or Other Data SUBSEQUENT REPORT OF:
NOTICE OF INTENTION	TO:	SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO PERFORM REMEDIAL WORK PLUG AN	TO: S D ABANDON REMEDIAL WORK	SUBSEQUENT REPORT OF: ALTERING CASING
NOTICE OF INTENTION TO PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE	TO: S D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING	GUBSEQUENT REPORT OF: ALTERING CASING GOPNS PLUG & ABANDONMENT
NOTICE OF INTENTION TO PERFORM REMEDIAL WORK PLUG AN	TO: S D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING	GUBSEQUENT REPORT OF: ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB
NOTICE OF INTENTION TO PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE	TO: S D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND CE	GUBSEQUENT REPORT OF: ALTERING CASING G OPNS PLUG & ABANDONMENT
NOTICE OF INTENTION OF PERFORM REMEDIAL WORK PLUG AND PLUG AND CHANGE PULL OR ALTER CASING Multiple COTHER:	TO: S D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND CE OTHER: High casi	GUBSEQUENT REPORT OF: ALTERING CASING GOPNS PLUG & ABANDONMENT EMENT JOB ing pressure X
PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Cleans)	TO: D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING completion CASING TEST AND CR OTHER: High casi carly state all pertinent details, and give pertinent	GUBSEQUENT REPORT OF: ALTERING CASING GOPNS PLUG & ABANDONMENT EMENT JOB ing pressure X dates, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Clear proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU.	TO: D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING CASING TEST AND CR OTHER: High casi early state all pertinent details, and give pertinent e Completions: Attach wellbore diagram of proportions	GUBSEQUENT REPORT OF: ALTERING CASING GOPNS PLUG & ABANDONMENT EMENT JOB ing pressure X dates, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Cleproposed work) SEE RULE 1103. For Multiple	TO: D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING CASING TEST AND CR OTHER: High casi early state all pertinent details, and give pertinent e Completions: Attach wellbore diagram of proportions	GUBSEQUENT REPORT OF: ALTERING CASING GOPNS PLUG & ABANDONMENT EMENT JOB ing pressure X dates, including estimated date of starting any
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple C OTHER: 13. Describe Proposed or Completed Operations (Cle proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well.	TO: D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING CASING TEST AND CR OTHER: High casi early state all pertinent details, and give pertinent e Completions: Attach wellbore diagram of proportions	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion.
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple C OTHER: 13. Describe Proposed or Completed Operations (Cle proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4. NU BOP.	TO: D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING CASING TEST AND CR OTHER: High casi early state all pertinent details, and give pertinent e Completions: Attach wellbore diagram of proportions	GUBSEQUENT REPORT OF: ALTERING CASING GOPNS PLUG & ABANDONMENT EMENT JOB ing pressure X dates, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Cleproposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4 NU BOP. 5. POOH w/tubing & injection equipment	TO: D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING CASING TEST AND COMMENCE And Completion OTHER: High casi Pull blanking plug.	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion.
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple C OTHER: 13. Describe Proposed or Completed Operations (Cle proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4. NU BOP.	TO: D ABANDON REMEDIAL WORK PLANS COMMENCE DRILLING CASING TEST AND COMMENCE And Completion OTHER: High casi Pull blanking plug.	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion.
PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Cleproposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4 NU BOP. 5. POOH w/tubing & injection equipment 6. Run back in hole w/new 4-1/2" Arrowset 1-X proposed works in the proposed works are removed.	TO: D ABANDON PLANS COMMENCE DRILLING CASING TEST AND COMPLET: OTHER: High casi Parly state all pertinent details, and give pertinent e Completions: Attach wellbore diagram of proportion properties. Pull blanking plug.	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion.
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple C OTHER: 13. Describe Proposed or Completed Operations (Cle proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4 NU BOP. 5. POOH w/tubing & injection equipment 6. Run back in hole w/new 4-1/2" Arrowset 1-X proposed works.	TO: D ABANDON PLANS COMMENCE DRILLING CASING TEST AND COMPLET: OTHER: High casi Parly state all pertinent details, and give pertinent e Completions: Attach wellbore diagram of proportion properties. Pull blanking plug.	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion.
PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Cleproposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4 NU BOP. 5. POOH w/tubing & injection equipment 6. Run back in hole w/new 4-1/2" Arrowset 1-X processor. 7. ND BOP. 8. Test casing to 540# and chart for the NMOCD. 9. RDPU & RU. Clean location.	TO: D ABANDON PLANS COMMENCE DRILLING CASING TEST AND COMPLET: OTHER: High casi Parly state all pertinent details, and give pertinent e Completions: Attach wellbore diagram of proportion properties. Pull blanking plug.	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion.
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple C OTHER: 13. Describe Proposed or Completed Operations (Cle proposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4 NU BOP. 5. POOH w/tubing & injection equipment 6. Run back in hole w/new 4-1/2" Arrowset 1-X proposed. 7. ND BOP. 8. Test casing to 540# and chart for the NMOCD.	TO: D ABANDON PLANS COMMENCE DRILLING CASING TEST AND COMPLET: OTHER: High casi Parly state all pertinent details, and give pertinent e Completions: Attach wellbore diagram of proportion properties. Pull blanking plug.	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion.
PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Cleproposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4 NU BOP. 5. POOH w/tubing & injection equipment 6. Run back in hole w/new 4-1/2" Arrowset 1-X promoted in the Number of Section 1. Rupu & Ru. 7. ND BOP. 8. Test casing to 540# and chart for the NMOCD. 9. RDPU & RU. Clean location. RUPU 04/25/08 RDPU 05/03/08	TO: D ABANDON PLANS COMMENCE DRILLING CASING TEST AND CHOOF DETERMINED COMPLETED C	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion. Packer set @4102'.
PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Cleproposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4 NU BOP. 5. POOH w/tubing & injection equipment 6. Run back in hole w/new 4-1/2" Arrowset 1-X processor. 7. ND BOP. 8. Test casing to 540# and chart for the NMOCD. 9. RDPU & RU. Clean location.	TO: D ABANDON PLANS COMMENCE DRILLING CASING TEST AND CHOOF DETERMINED COMPLETED C	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion. Packer set @4102'.
PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Cleproposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4 NU BOP. 5. POOH w/tubing & injection equipment 6. Run back in hole w/new 4-1/2" Arrowset 1-X promoted in the Normal Pool of the	TO: D ABANDON PLANS COMMENCE DRILLING CASING TEST AND CHOOF DETERMINED COMPLETED C	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion. Packer set @4102'.
PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Cleproposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4 NU BOP. 5. POOH w/tubing & injection equipment 6. Run back in hole w/new 4-1/2" Arrowset 1-X promoted in the Normal Pool of the	TO: D ABANDON PLANS COMMENCE DRILLING CASING TEST AND CE OTHER: High casi early state all pertinent details, and give pertinent the Completions: Attach wellbore diagram of proportion proportions. Pull blanking plug. Pull blanking plug.	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion. Packer set @4102'.
PERFORM REMEDIAL WORK PLUG AN TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING Multiple COTHER: 13. Describe Proposed or Completed Operations (Cleproposed work) SEE RULE 1103. For Multiple 1. RUPU & RU. 2. Set blanking plug @4106'. Test tubing. OK. 3. Kill well. 4 NU BOP. 5. POOH w/tubing & injection equipment 6. Run back in hole w/new 4-1/2" Arrowset 1-X promoted in the Normal Pool of the	TO: D ABANDON PLANS COMMENCE DRILLING CASING TEST AND CI OTHER: High casi Parly state all pertinent details, and give pertinent e Completions: Attach wellbore diagram of proport Pull blanking plug. Packer set on 129 jts of 2-7/8" Duoline tubing.	ALTERING CASING G OPNS PLUG & ABANDONMENT EMENT JOB ing pressure dates, including estimated date of starting any osed completion or recompletion. Packer set @4102'.


For State Use Only

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

THETROLEUM ENGINEER

_UNE 1 8 2008



Set # 32.13 4.06 CAL DALE 4.24.06

5-3-68-23 2-44-30-233 2-44-30-44-65