

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No 1004-0135  
Expires: September 30, 1990

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

LANEXCO, INC.

3. Address and Telephone No.

1105 WEST KANSAS, JAL, NM 88252 505-395-3056

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FSL, 1650' FWL

Sec. 33, T25S, R37E

Unit K

5. Lease Designation and Serial No.

LC-054667

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

EL PASO TOM FED. #4

9. API Well No.

30-025-26919

10. Field and Pool, or Exploratory Area

LANGLIE MATTIX ; 7 Rws -

11. County or Parish, State

LEA, NM

Grayburg

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

05-09-08: MIRU. ND well head. NU BOP. Run in hole with MMCPI workstring. Tag @ 2487'. Circulate plugging mud. Spot 25 sxs with CACLZ @ 2465'. Pull out of hole. WOC. Run in hole and tag @ 2248'. Pull out of hole. Spot 25 sxs @ 1200'. Pull out of hole. SDFD.

05-12-08 Run in hole and tag @ 947'. Pull up hole to 486'. Spot 40 sxs. Pull up hole to 97'. Circulate 20 sxs to surface. Rig down. Cut off well head and anchors. Install dryhole marker. Level location. Clean up location. SDFD.

RECEIVED

JUN 11 2008

HOBBS OCD

14. I hereby certify that the foregoing is true and correct

Signed

*John L. Manes*

Title PRODUCTION SUPT.

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

ACCEPTED FOR RECORD

JUN 7 2008

*J. Ames*

BUREAU OF LAND MANAGEMENT  
CARLSBAD FIELD OFFICE