Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N French Dr, Hobbs, NM 88240		WELL API NO.
<u>District II</u> 1301 W. Grand Ave, Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-32531
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr, Santa Fe, NM	Santa 1 c, 14141 67505	6. State Off & Gas Lease No.
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPL	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	J.R. Philips "A" Gas Com
PROPOSALS)  1. Type of Well: Oil Well	Gas Well 🕅 Other	8. Well Number 2
2. Name of Operator	Gas wen 🖂 Guiei	9. OGRID Number 000873
Apache Corporation		). Game (minor)
3. Address of Operator		10. Pool name or Wildcat
	1500, Tulsa, Oklahoma 74136-4224	Eumont Yates 7RQ
4. Well Location		
	660' feet from the North line and 1,980'	feet from the East line
Section 31	Township 19-S Range 37-E	NMPM Lea County
Section 31	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3582.3' GL	
Pit or Below-grade Tank Application ⊠		
	waterDistance from nearest fresh water wellDi	stance from nearest surface water
		Construction Material steel
12. Check	Appropriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF II	NTENTION TO: SUI	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON		RILLING OPNS. P AND A
PULL OR ALTER CASING	_	<del>_</del>
		_
OTHER:	DIAMETER   OTHER:	nd give pertinent dates, including estimated date
13. Describe proposed or com	pleted operations. (Clearly state all pertinent details, a	
13. Describe proposed or com of starting any proposed w		
13. Describe proposed or com	pleted operations. (Clearly state all pertinent details, a	
13. Describe proposed or com of starting any proposed w or recompletion.	pleted operations. (Clearly state all pertinent details, a	Attach wellbore diagram of proposed completion
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A	Attach wellbore diagram of proposed completion  AMS
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  8%" surface csg set @ 1,229', circ	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR	Attach wellbore diagram of proposed completion  AMS
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  85% surface csg set @ 1,229', circ perforations 3,404 – 3,564'	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'
<ul> <li>13. Describe proposed or com of starting any proposed wor recompletion.</li> <li>SEE ATTACHED CURRENT A</li> <li>8%" surface csg set @ 1,229', circle perforations 3,404 – 3,564'</li> <li>1. Set steel working pit, RU</li> </ul>	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ productio	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  85% surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ productio culate plugging mud, and pump 25 sx C cmt @ 3,35.	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  8%" surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,4	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35480' (base of salt @ 2,380')	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  8%" surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,4	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ U Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35.80° (base of salt @ 2,380°)	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  8%" surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,4	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ U Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35.80° (base of salt @ 2,380°)	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  8%" surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,4	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ U Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35.80° (base of salt @ 2,380°)	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  8%" surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,4 4. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt 1,284 6. Pump 25 sx C cmt @ 400	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35.80' (base of salt @ 2,380')  25' (DV tool @ 1,975')  — 1,184' WOC & TAG (surface casing shoe & top of the contraction of	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  85% surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,4 4. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 2,0 6. Pump 25 sx C cmt @ 400 7. Circulate 10 sx C cmt 60	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35680' (base of salt @ 2,380') 25' (DV tool @ 1,975') - 1,184' WOC & TAG (surface casing shoe & top of the courage of the	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  85% surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,4 4. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 2,0 6. Pump 25 sx C cmt @ 400 7. Circulate 10 sx C cmt 60	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35.80' (base of salt @ 2,380')  25' (DV tool @ 1,975')  — 1,184' WOC & TAG (surface casing shoe & top of the contraction of	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present  4'  of salt plug) — If NO RECORD TOO
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  85% surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,4 4. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 2,0 6. Pump 25 sx C cmt @ 400 7. Circulate 10 sx C cmt 60	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35680' (base of salt @ 2,380') 25' (DV tool @ 1,975') - 1,184' WOC & TAG (surface casing shoe & top of the courage of the	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  8%" surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,4 4. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 400 7. Circulate 10 sx C cmt 60 8. Cut off wellhead & anch	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ U Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35.80' (base of salt @ 2,380')  25' (DV tool @ 1,975')  — 1,184' WOC & TAG (surface casing shoe & top of the complete to the best of my knowled a above is true and complete to the best of my knowled a showled is true and complete to the best of my knowled a showled is true and complete to the best of my knowled a showled is true and complete to the best of my knowled in above is true and complete to the best of my knowled in the complete to the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the best of my knowled in the complete in the complete in the best of my knowled in the complete in the comp	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present  4'  of salt plug) — If NO RECORD TOO
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  8%" surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,4 4. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 400 7. Circulate 10 sx C cmt 60 8. Cut off wellhead & anch	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ productio culate plugging mud, and pump 25 sx C cmt @ 3,35.80' (base of salt @ 2,380')  25' (DV tool @ 1,975')  — 1,184' WOC & TAG (surface casing shoe & top of to surface ors, install dry hole marker, backfill cellar.  In above is true and complete to the best of my knowled or closed according to NMOCD guidelines \( \text{\tex{\tex	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present  4'  of salt plug) — If No Record Too  perfect to the proposed completion  ge and be fell in the centry that any pit of below- or an (all actually all trustices to approved plan   ].
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  8%" surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,0 4. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 400 7. Circulate 10 sx C cmt 60 8. Cut off wellhead & anch  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35.80' (base of salt @ 2,380')  25' (DV tool @ 1,975')  — 1,184' WOC & TAG (surface casing shoe & top of the control of th	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  n equipment as present  4'  of salt plug) — If wo record Too  ge and be fers in the certify that any pit of below- or an (all ache) alternative CD-approved plan  sic Energy Services) DATE 07/16/08
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  85%" surface csg set @ 1,229", circ perforations 3,404 – 3,564"  1. Set steel working pit, RU 2. Set CIBP @ 3,354". Circ 3. Pump 25 sx C cmt @ 2,4 4. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 400 7. Circulate 10 sx C cmt 60 8. Cut off wellhead & anch  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name James F. New	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ productio culate plugging mud, and pump 25 sx C cmt @ 3,35.80' (base of salt @ 2,380')  25' (DV tool @ 1,975')  — 1,184' WOC & TAG (surface casing shoe & top of to surface ors, install dry hole marker, backfill cellar.  In above is true and complete to the best of my knowled or closed according to NMOCD guidelines \( \text{\tex{\tex	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  In equipment as present  4'  Of salt plug) — If No Record Too  Sic Energy Services) DATE 07/16/08  Orgy Services.com Telephone No. 432-687-1994
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  8%" surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,0 4. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 400 7. Circulate 10 sx C cmt 60 8. Cut off wellhead & anch  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35.80' (base of salt @ 2,380')  25' (DV tool @ 1,975')  — 1,184' WOC & TAG (surface casing shoe & top of the content of th	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  In equipment as present  4'  Of salt plug) — If No Record Too  Sic Energy Services) DATE 07/16/08  Orgy Services.com Telephone No. 432-687-1994
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  85% surface csg set @ 1,229', circ perforations 3,404 – 3,564'  1. Set steel working pit, RU 2. Set CIBP @ 3,354'. Circ 3. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 400 7. Circulate 10 sx C cmt 60 8. Cut off wellhead & anch  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name James F. News For State Use Only	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35.80' (base of salt @ 2,380')  25' (DV tool @ 1,975')  — 1,184' WOC & TAG (surface casing shoe & top of the control of th	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  In equipment as present  4'  Of salt plug) — If No Record Too  Ge and be ferst in the certification pit of below- or an (alached) alternative obserption of plan    sic Energy Services) DATE 07/16/08  ergyServices.com Telephone No. 432-687-1994  /STAFF-MANAGER JUL 2 5 2008
13. Describe proposed or com of starting any proposed w or recompletion.  SEE ATTACHED CURRENT A  85%" surface csg set @ 1,229", circ perforations 3,404 – 3,564"  1. Set steel working pit, RU 2. Set CIBP @ 3,354". Circ 3. Pump 25 sx C cmt @ 2,4 4. Pump 25 sx C cmt @ 2,0 5. Pump 25 sx C cmt @ 400 7. Circulate 10 sx C cmt 60 8. Cut off wellhead & anch  I hereby certify that the information grade tank has been/will be constructed of SIGNATURE  Type or print name James F. New	pleted operations. (Clearly state all pertinent details, a york). SEE RULE 1103. For Multiple Completions: A ND PROPOSED PLUGGED WELLBORE DIAGR culated with 400 sx; 5½" 15.5# production csg set @ Basic plugging rig, NU BOP. POOH w/ production culate plugging mud, and pump 25 sx C cmt @ 3,35.80' (base of salt @ 2,380')  25' (DV tool @ 1,975')  — 1,184' WOC & TAG (surface casing shoe & top of the control of th	Attach wellbore diagram of proposed completion  AMS  3,580' with 1,000 sx (circ), DV tool @ 1,975'  In equipment as present  4'  Of salt plug) — If No Record Too  Sic Energy Services) DATE 07/16/08  Orgy Services.com Telephone No. 432-687-1994

## CURRENT WELLBORE SKETCH Apache Corporation



Date July 11, 2008

@	_		
@ @ 3,582'	_		
<u> </u>	<del>_</del>	Lease & Well No	J.R Phillips "A" Com #2
		Legal Description :	Unit Letter B, 660' FNL & 1,980' FEL, Section 31,
			T-19-S, R-31-E
		County:	Lea State New Mexico
		Field:	Eumont Yates Seven Rivers Queen
		Date Spudded	6/30/1994
		API Number Status:	30-025-32531
		Status.	
	11" hole		
	TT HOSE		
	Base Salt @ 1,230'		
	8-5/8" 24# csg @ 1,229' cmt'd w/ 400 sx, circ		
	DV4 -1 O 4 0751		
	DV tool @ 1,975'		
1			
1			
1   1			
	Base Salt @ 2,380'		
			THE PARTY AND STATE OF THE PARTY OF THE PART
	7-7/8" hole		RECEIVED
			ALL STATES OF THE PARTY OF THE
			JUL 1 8 2008
			HOBBS OCD
	open perforations		u de la companya de l
; <u> </u>	3,404 - 3,564'		
1	T 4/01/45 511 O 0 5001 /01/4 O 4 5550		
<b>1</b>   1	5-1/2" 15.5# csg @ 3,580' (DV tool @ 1,975')		
	cmt'd w/ 600 sx in 1st stage & 400 sx in 2nd st	age	

## PROPOSED PLUGGED WELLBORE SKETCH Apache Corporation



Date: July 11, 2008 \_\_\_

RKB @ \_\_\_\_\_ DF @ \_\_\_\_ GL @ \_\_\_3,582'

Pump 10 sx C cmt 60' to surface Pump 25 sx C cmt @ 400' 11" hole Base Salt @ 1,230' 8-5/8" 24# csg @ 1,229' cmt'd w/ 400 sx, circ Pump 25 sx C cmt @ 1,284 - 1,184' WOC & TAG DV tool @ 1,975' Pump 25 sx C cmt @ 2,025' Base Salt @ 2,380' Pump 25 sx C cmt @ 2,480' 7-7/8" hole Circulate plugging mud, pump 25 sx @ 3,354

open perforations 3,404 - 3,564'

5-1/2" 15.5# csg @ 3,580' (DV tool @ 1,975') cmt'd w/ 600 sx in 1st stage & 400 sx in 2nd stage

Lease & Well No. : Legal Description :

County
Field:
Date Spudded.
API Number:
Status:

J.R. Phillips "A	A" Com #2		
Unit Letter B,	660' FNL &	1,980' FEL, Section 31,	_
T-19-S, R-31-	E		
Lea	State ·	New Mexico	
Eumont Yates	Seven Rive	ers Queen	
6/30/1994			
30-025-32531			
PROPOSED	PLUGGED		

## PROPOSED PLUGGING PROCEDURE

- 1) Set CIBP @ 3,354'
- 2) Circulate plugging mud, pump 25 sx @ 3,354'
- 3) Pump 25 sx C cmt @ 2,480'
- 4) Pump 25 sx C cmt @ 2,025'
- 5) Pump 25 sx C cmt @ 1,284 1,184' WOC & TAG
- 6) Pump 25 sx C cmt @ 400'
- 7) Pump 10 sx C cmt 60' to surface

<u>Capacities</u>				
4½" 9.5# csg:	10.960	ft/ft3	0.0912	ft3/ft
51/2" 15.5# csg:	7.483	ft/ft3	0 1336	ft3/ft
51/2" 17# csg	7 661	ft/ft3	0.1305	ft3/ft
7" 23# csg	4 524	ft/ft3	0.221	ft3/ft
7%" 26 4# csg:	3 775	ft/ft3	0.2648	ft3/ft
8%" 24# csg <sup>-</sup>	2.797	ft/ft3	0.3575	ft3/ft
8%" 28# csg	2.853	ft/ft3	0.3505	ft3/ft
103/4" 40.5# csg:	1.815	ft/ft3	0 5508	ft3/ft
71/8" openhole.	2.957	ft/ft3	0 3382	ft3/ft
8¾" openhole	2 395	ft/ft3	0.4176	ft3/ft
121/4" openhole	1 222	ft/ft3	0 8185	ft3/ft



JUL 1 8 2009 HOBBS OCD



P&A Operations P.O. Box 10451 Midland, Texas 79702 432-687-1994 Fax 687-0066

16 July 2008

New Mexico Oil Conservation Division 1625 French Drive Hobbs, New Mexico 88240

re:

Intent to P&A C103 Apache Corporation

J.R. Phillips "A" Gas Com #2

660 FNL & 1,980 FEL Section 31, T-19-S, R-37-E Lea County, New Mexico

Please find attached an Intent to P&A the referenced wellbore.

Thank you, please advise with questions or comments.

Jim Newman P&A Manager

**Basic Energy Services** 

**Enclosure** 

C: Dianne Gilbreath, Apache Corporation

acceved

HOBBS OCD