Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIO BUREAU OF LAND MANAGEMENT


OCD


FORM APPROVED OMB NO 1004-0135 Expires July 31, 2010

1	Lease Serial No
	NMNM70988X

SUNDRY NOTICES AND REPORTS ON WELLS	NMNM70988X
De water a this fame for manager and to drill or to go ordide all 7 0000	6 If Indian, Allottee or Tribe Name
abandoned well. Use form 3160-3 (APD) for such proposals.	1005050

				CA 1.7 CA PO EL M	4247.8					
SUBMIT IN TRIF	PLICATE - Other instruc	tions on the			Unit or CA/Agreem ALJAMAR GRA	ent, Name and/or No YBURG				
I. Type of Well				8. W	ell Name and No. ALJAMAR GRAY	PURGUNIT 13				
☑ Oil Well ☐ Gas Well / ☐ Oth			·		5010 01111 10					
2 Name of Operator FOREST OIL CORPORATION	Contact. I / E-Mail: cabush@fo		30	PI Well No 0-025-00444 ,						
3a. Address 707 17TH STREET SUITE 360 DENVER, CO 80202)0	(include area code !-1554	M	field and Pool, or E ALJAMAR GRY	ABURG /					
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description		11 (ounty or Parish, an	d State					
Sec 3 T17S R32E 660FSL 66	OFEL /		L	EA COUNTY, N	м /					
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA										
TYPE OF SUBMISSION	YPE OF SUBMISSION TYPE OF ACTION									
- Notice of Intent	□ Acidize	□ Deep	en	Production (Start/Resu		□ Water Shut-Off				
g e	Alter Casing Fr			☐ Reclamation		□ Well Integrity				
☐ Subsequent Report	bsequent Report Casing Repair New Construction					□ Other				
☐ Final Abandonment Notice	Change Plans	Plug	and Abandon	☐ Temporarily A	Abandon					
_	Convert to Injection	□ Plug	Back	■ Water Dispos	al					
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Plugging Procedure: 1. MIRUPU. POOH w/downhole equipment as required 2. RIH w/tubing, set cement plug from PBTD to 3,592' 3. Displace wellbore w/heavy mud. Set cement plug bottom @1,347', top @ 900'. 4. Displace wellbore w/heavy mud, Set cement plug bottom @ 300', top @ surface 5. Cut off casing. Install dry hole marker 6. Remediate surface location as necessary Well bore Diagrams attached. SEE ATTACHED FOR CONDITIONS OF APPROVAL JAMES A. AMOS SUPERVISOR-EPS										
14. I hereby certify that the foregoing is true and correct. Electronic Submission #61278 verified by the BLM Well Information System For FOREST OIL CORPORATION, sent to the Hobbs										
Name (Printed/Typed) CINDY BU	ı	Title SR. REGULATORY TECH								
Signature (Electronic S	Date 07/08/2	2008								
THIS SPACE FOR FEDERAL OR STATE OFFICE USE										
					Data					
Approved By	· -	Title			Date					
Conditions of abyroval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to conditions.	uitable title to those rights in th	Office								
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.										





Forest Oil Corporation NMLC059576; Maljamar Greyburg Unit 13 660' FSL & 660' FEL Section 3, T.17 S., R.32 E. Lea County, New Mexico

RE: Plugging and Abandonment Requirements, Conditions of Approval

- 1. OK as is.
- OK as is.
 2.(a) Add plug to cover Base of Salt. Perforate the 5-1/2" casing @ 2350'.
 Squeeze with adequate cement from 2350'- 2230'. WOC and tag no lower than 2230'.
- 3. Perforate 5-1/2" casing @ 1310'. Squeeze with adequate cement from 1310'-1197' (Covers Top of salt and 8-5/8" shoe). WOC and tag no lower than 1197'.
- 4. Perforate 5-1/2" and 8-5/8" casings @ 300'. Circulate both casings to surface in/out.

See attached standard COA's.

James A. Amos 505-234-5909

7/13/08

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.