State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	ISION
DISTRICT I	WELL API NO
1625 N French Dr., Hobbs, NM 88240 Santa Fe, NM 87505	30-025-23035
DISTRICT II	5 Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	STATE FEE X
DISTRICT III	6 State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 8740400000	
SUNDRY NOTICE REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK T	O A North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposa	
1 Type of Well.	8 Well No. 232
Oil Well X Gas Well Other	
2 Name of Operator	9 OGRID No 157984
Occidental Permian Ltd.	
3 Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4 Well Location	
Unit Letter K 1980 Feet From The South 2060	0 Feet From The West Line
Section X 32 Township 18-S Range	38-E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3640' KB	
J040 KD	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water	well Distance from pearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Cons	struction Material
12. Check Appropriate Box to Indicate Nature of Notice, R	Peport or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	RK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DF	RILLING OPNS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST A	AND CEMENT JOB
OTHER OAP/Acid treat	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give per	rtinent dates, including estimated date of starting any
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram o	f proposed completion or recompletion.
1 Kill wall DOOH w/FSD equipment	
1 Kill well. POOH w/ESP equipment.	
2. Clean out to PBTD @4300'.	
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. 	
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. Perforate well. 	
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. Perforate well. Acid treat 	
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. Perforate well. Acid treat Perform scale squeeze. 	- ,
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. Perforate well. Acid treat 	- ,
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. Perforate well. Acid treat Perform scale squeeze. Run back in hole w/production equipment. 	- ,
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. Perforate well. Acid treat Perform scale squeeze. Run back in hole w/production equipment. 	- ,
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. Perforate well. Acid treat Perform scale squeeze. Run back in hole w/production equipment. 	- ,
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. Perforate well. Acid treat Perform scale squeeze. Run back in hole w/production equipment. Return well to production 	urther certify that any pit or below-grade tank has been/will be
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. Perforate well. Acid treat Perform scale squeeze. Run back in hole w/production equipment. Return well to production 	
 2. Clean out to PBTD @4300'. 3. Run CNL/GR/CCL log. 4. Perforate well. 5. Acid treat 6. Perform scale squeeze. 7 Run back in hole w/production equipment. 8. Return well to production 	urther certify that any pit or below-grade tank has been/will be f) alternative OCD-approved
 Clean out to PBTD @4300'. Run CNL/GR/CCL log. Perforate well. Acid treat Perform scale squeeze. Run back in hole w/production equipment. Return well to production 	
 2. Clean out to PBTD @4300'. 3. Run CNL/GR/CCL log. 4. Perforate well. 5. Acid treat 6. Perform scale squeeze. 7 Run back in hole w/production equipment. 8. Return well to production 	
 2. Clean out to PBTD @4300'. 3. Run CNL/GR/CCL log. 4. Perforate well. 5. Acid treat 6. Perform scale squeeze. 7 Run back in hole w/production equipment. 8. Return well to production I hereby certify that the information above is true and complete to the best of my knowledge and belief 1 fit constructed or closed according to NMOCD guidelines , a general permit or an (attached plan SIGNATURE MANAGE TITLE Adm 	alternative OCD-approved
 2. Clean out to PBTD @4300'. 3. Run CNL/GR/CCL log. 4. Perforate well. 5. Acid treat 6. Perform scale squeeze. 7 Run back in hole w/production equipment. 8. Return well to production I hereby certify that the information above is true and complete to the best of my knowledge and belief 1 fr constructed or closed according to NMOCD guidelines , a general permit or an (attached plan SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson E-mail address. mendy_johnson	alternative OCD-approved
 2. Clean out to PBTD @4300'. 3. Run CNL/GR/CCL log. 4. Perforate well. 5. Acid treat 6. Perform scale squeeze. 7 Run back in hole w/production equipment. 8. Return well to production I hereby certify that the information above is true and complete to the best of my knowledge and belief 1 fit constructed or closed according to NMOCD guidelines , a general permit or an (attached plan SIGNATURE 	alternative OCD-approved

CONDITIONS OF APPROVAL IF ANY.