Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

o Appropriate District Office		ATT	NI DIVIC	IONI				
<u>DISTRICT I</u>	OIL CONSERV					· ·· <del>·································</del>		
2.O. Box 1980, Hobbs NM 88241-1980	2040 Pacheco St. Santa Fe, NM 87505			WE	ELL API NO. 30	- 025 - 03285		
<u>DISTRICT II</u> .O. Drawer DD, Artesia, NM 88210	Santa Fe	e, NM	87505	5. 1	Indicate Typ		X	FEE
<u>DISTRICT III</u> 000 Rio Brazos Rd., Aztec, NM 87410				6. 5	State Oil & C	as Lease No.		
SUNDRY NOT	ICES AND REPORTS	ON WE	ILLS	////				
(DO NOT USE THIS FORM FOR PR DIFFERENT RESE		DEEPEN FOR PER	OR PLUG BACK	/.		or Unit Agreen QUEEN UNIT	nent Nar	ne
. Type of Well: OIL GAS WELL WELL WELL		INJECTI	ON		OT TEAKE	QOLLIN ONTT		
. Name of Operator		INOLUTI	OIV	8	Well No.			
ERIC OIL & GAS CORP.					42			
Address of Operator P. O. Box 352, Midland,	TX 79702				Pool name or ARL QUEEN			
. Well Location	N	IODTI I		1000				
Unit LetterB: 660	Feet From The N	URTH	Line and	1980	Feet Fro	om The	EAST	Line
Section 33	Township 19 S	D	35 E	N IN 4T	21.4	LEA		<i>C</i> .
Section	Township 19 S	Ran ow whethe		NMI GR, etc.)	<sup>2</sup> M	<i>V/////////</i>		County
NOTICE OF INT	ENTION TO:  PLUG AND ABANDON		REMEDIAL WOR		QUENT	REPORT		
ERFORM REMEDIAL WORK				RK ILLING OPI	NS		CASING	NMENT C
MOTICE OF INT  REFORM REMEDIAL WORK  MPORARILY ABANDON  JLL OR ALTER CASING  THER:  2. Describe Proposed or Completed Opwork) SEE RULE 1103.	PLUG AND ABANDON CHANGE PLANS		REMEDIAL WOR COMMENCE DR CASING TEST AI OTHER:	RK ILLING OPI ND CEMEN	NS. IT JOB	ALTERING C	ASING	
REFORM REMEDIAL WORK  MPORARILY ABANDON  JULI OR ALTER CASING  THER:  2. Describe Proposed or Completed Op	PLUG AND ABANDON CHANGE PLANS  Peration (Clearly state all per C & TAG @ 4510  SKS TAG @ 1560		REMEDIAL WOR COMMENCE DR CASING TEST AI OTHER:	RK ILLING OPI ND CEMEN	NS. IT JOB	ALTERING C	ASING	
PERFORM REMEDIAL WORK  MPORARILY ABANDON  JULI OR ALTER CASING  THER:  2. Describe Proposed or Completed Opwork) SEE RULE 1103.  10-15-03  SPOT 25 SKS @ 4650' W.O. (PERF @ 1700' SQUEEZE 50 SPERF @ 350' CIRC 50 SKS TINSTALL P & A MARKER	PLUG AND ABANDON CHANGE PLANS  Peration (Clearly state all per C & TAG @ 4510  SKS TAG @ 1560		REMEDIAL WOR COMMENCE DR CASING TEST AI OTHER:	RK ILLING OPI ND CEMEN	NS. IT JOB	PLUG AND A	ASING	
PERF @ 350 CIRC 50 SKS	PLUG AND ABANDON CHANGE PLANS  Decration (Clearly state all per C & TAG @ 4510 SKS TAG @ 1560 TO SURFACE.  App	tinent det	REMEDIAL WOR COMMENCE DR CASING TEST AI OTHER: ails, and give peri	RK  ILLING OPI  ND CEMEN  tinent dates	NS. IT JOB IT JO	ALTERING C	ASING	
MPORARILY ABANDON  LL OR ALTER CASING  THER:  2. Describe Proposed or Completed Opwork) SEE RULE 1103.  10-15-03  SPOT 25 SKS @ 4650' W.O.O  PERF @ 1700' SQUEEZE 50 S  PERF @ 350' CIRC 50 SKS	PLUG AND ABANDON CHANGE PLANS  Detration (Clearly state all per C & TAG @ 4510 SKS TAG @ 1560 TO SURFACE.  App Liab	tinent det	REMEDIAL WOR  COMMENCE DR  CASING TEST AI  OTHER:  ails, and give perform  s to plugging of the pond is ret	of the We	NS. IT JOB IT JO	PLUG AND A	of starti	ng any pro 6177079.
MPORARILY ABANDON  LL OR ALTER CASING  HER:  Describe Proposed or Completed Opwork) SEE RULE 1103.  10-15-03 SPOT 25 SKS @ 4650' W.O. (PERF @ 1700' SQUEEZE 50 SPERF @ 350' CIRC 50 SKS	PLUG AND ABANDON CHANGE PLANS  Detration (Clearly state all per C & TAG @ 4510 SKS TAG @ 1560 TO SURFACE.  App Liab	tinent det	REMEDIAL WOR COMMENCE DR CASING TEST AI OTHER: ails, and give peri	of the We	NS. IT JOB IT JO	PLUG AND A	of starti	
MPORARILY ABANDON  LL OR ALTER CASING  HER:  Describe Proposed or Completed Opwork) SEE RULE 1103.  10-15-03 SPOT 25 SKS @ 4650' W.O. (PERF @ 1700' SQUEEZE 50 SPERF @ 350' CIRC 50 SKS	PLUG AND ABANDON CHANGE PLANS  Detration (Clearly state all per C & TAG @ 4510 SKS TAG @ 1560 TO SURFACE.  App Liab	tinent det	REMEDIAL WOR  COMMENCE DR  CASING TEST AI  OTHER:  ails, and give perform  s to plugging of the pond is ret	of the We	NS. IT JOB IT JO	PLUG AND A	of starti	ng any pro 6177079.
PERFORM REMEDIAL WORK  MPORARILY ABANDON  JULI OR ALTER CASING  THER:  2. Describe Proposed or Completed Opwork) SEE RULE 1103.  10-15-03  SPOT 25 SKS @ 4650' W.O.O  PERF @ 1700' SQUEEZE 50 SEE PERF @ 350' CIRC 50 SKS  INSTALL P & A MARKER CIRC MUD	PLUG AND ABANDON CHANGE PLANS  Decration (Clearly state all per C & TAG @ 4510 SKS TAG @ 1560 TO SURFACE.  App Liab surf	proved a pility und	REMEDIAL WORK COMMENCE DR CASING TEST AL OTHER:  ails, and give performance s to plugging of the bond is retoration is com	of the We	NS. IT JOB IT JO	PLUG AND A	of starti	ng any pro 6177079.
PERFORM REMEDIAL WORK  MPORARILY ABANDON  JULI OR ALTER CASING  THER:  2. Describe Proposed or Completed Opwork) SEE RULE 1103.  10-15-03  SPOT 25 SKS @ 4650' W.O. (PERF @ 1700' SQUEEZE 50 SPERF @ 350' CIRC 50 SKS TINSTALL P & A MARKER	PLUG AND ABANDON CHANGE PLANS  Decration (Clearly state all per C & TAG @ 4510 SKS TAG @ 1560 TO SURFACE.  App Liab surf	proved a pility und ace resto	REMEDIAL WORK COMMENCE DR CASING TEST AL OTHER:  ails, and give performance s to plugging of the bond is retoration is com	of the We	NS. IT JOB IT JO	PLUG AND A	of starti	ng any pro 6177079.
MPORARILY ABANDON  LL OR ALTER CASING  HER:  Describe Proposed or Completed Orwork) SEE RULE 1103.  10-15-03 SPOT 25 SKS @ 4650' W.O.O PERF @ 1700' SQUEEZE 50 SPERF @ 350' CIRC 50 SKS  INSTALL P & A MARKER CIRC MUD	PLUG AND ABANDON CHANGE PLANS  Decration (Clearly state all per C & TAG @ 4510 SKS TAG @ 1560 TO SURFACE.  App Liab surf	proved a pility und ace resto	REMEDIAL WOR COMMENCE DR CASING TEST AI OTHER:  ails, and give period is to plugging of der bond is ret oration is com	of the We	NS. IT JOB IT JO	estimated date	of starti	ng any pro 6 17 70 70 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9