Submit 3 Copies To Appropriate District Office State of New Minerals and N		Form C-103
<u>District I</u> Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240		Revised March 25, 1999 WELL API NO.
District II 1301 W. Grand Avenue, Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-06324
District III 1000 Rio Brazos Rd Aztec NM 87410 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE
District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name:
1. Type of Well: Oil Well Gas Well Other		Eunice Monument South Unit
2. Name of Operator Chevron USA Inc		8. Well No. 156
3. Address of Operator 15 Smith Rd, Midland, TX, 79705		Pool name or Wildcat Eunice Monument Grayburg
4. Well Location		
Unit Letter K : 1980 feet from the So	uth line and	1880 _feet from the line
Section 32 Township 20-S	Range 37-E	NMPM Lea County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WOR	SEQUENT REPORT OF: K ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DR	
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AI	ABANDONMENT I
OTHER:	OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.		
		01310151617:07.0
 Notify OCD 24 hrs prior to MI and RU. RIH Tag CIBP at 3580, spot 30sx, plug 3580-3300 (Grayburg - SA) WOC Tag. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL. Spot 25sx, plug 2700-2500 (Yates, B-Salt) WOC Tag. 		
3. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL.		
4. Spot 25sx, plug 2700-2500 (Yates, B-Salt) WOC Tag. 5. Perf 4 holes at 1200, sqz 40sx, plug 1200-1100 (T-Salt) WOC Tag. 6. Perf 4 holes at 360, sqz 90sx, plug 360-Surf, 5 1/2" x 8 5/8" (8 5/8" Shoe, Surf) WOC Fag.		
6. Perf 4 holes at 360, sqz 90sx, plug 360-Surf, 5 1/2" x 8 5/8" (8 5/8" Shoe, Surf) WOO fag.		
7. Install dry hole marker.	SCIONINGE DE NIO	\ <u>\</u> \\\
LOUPS PRIC	SSION MUST BE NO OR TO THE BEGINI	NING OI
PLUGGING (DPERATIONS FOR I	HE C-103
TO BE APPRO	OVED.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE S.R. MechoTITL		
Type or print name G.R. Bledsoe		Telephone No. (432) 687-7153
(This space for State use)		
APPPROVED BY LOUIS TITLE	E	WETAFE MANAGER NOV 1 9 200
APPPROVED BY Conditions of approval, if any: OC FIELD REPRESENTATIVE 11/8TAFF MANAGER NOV 1 2 2003		
OC FIRTH I'M		

