Office	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural F	esources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL A	4
District II	OIL CONSERVATION DIV	ISION 30-025-2	
1301 W Grand Ave., Artesia, NM 8821 District III	1220 South St. Francis	5. Indica	ate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	٥.	TATE ☑ FEE □
District IV	Santa Fe, INIVI 87303	i i	Oil & Gas Lease No.
1220 S. St Francis Dr., Santa Fe, NM 87505		OG-866	
SUNDRY NO (DO NOT USE THIS FORM FOR PRO	TICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BA LICATION FOR PERMIT" (FORM C-101) FOR SU	CK TO A CH N.E. Ma	Name or Unit Agreement Name
1. Type of Well: Oil Well ⊠	Gas Well Other	8. Well	Number 1
2. Name of Operator		9. OGR	ID Number 014070
Marks & Garner Production Ltd	<u></u>	10	Pool name or Wildcat
3. Address of Operator P.O. Box 1089 Hobbs, NM 882	41		West Kennitz (W.C)
	, + 1		west Remintz (W.C)
4. Well Location			
Unit LetterI	: 1980 feet from the South	_line and600	feet from theEastline
Section 31	Township 16S Ran	ge 33E NN	IPM County Lea
	11. Elevation (Show whether DR, RKI	·	
	4235 GR	, , ,	
Pit or Below-grade Tank Application	or Closure		
Pit type Steel Depth to Grou	ndwaterDistance from nearest fresh water	well Distance from	nearest surface water
	nil Below-Grade Tank: Volume	bbls; Construction N	
· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · · · · · · · · ·
12. Checl	Appropriate Box to Indicate Natur	of Notice, Report o	r Other Data
NOTICE OF	INTENTION TO	OUDOFOUE	NT DEDODT OF
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐			
,,, _ , _ , _ , _ , _ , _ , _ , _ ,	!	MMENCE DRILLING OP	NS.L. PANDA L.
PULL OR ALTER CASING	☐ MULTIPLE COMPL ☐ CA	SING/CEMENT JOB	Ш
OTHER:	□ от	IER:	
OTHER: 13. Describe proposed or con	ot npleted operations. (Clearly state all pertin	HER: ent details, and give pert	
OTHER: 13. Describe proposed or corof starting any proposed	□ от	HER: ent details, and give pert	
OTHER: 13. Describe proposed or con	ot npleted operations. (Clearly state all pertin	HER: ent details, and give pert	
OTHER: 13. Describe proposed or corof starting any proposed or recompletion.	ot other properties of the pro	HER: ent details, and give pert	
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3	npleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Co	HER: ent details, and give pert	
OTHER: 13. Describe proposed or correct of starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It	npleted operations. (Clearly state all pertin work). SEE RULE 1103. For Multiple Co	HER: ent details, and give pertinpletions: Attach wellbook	
OTHER: 13. Describe proposed or correct of starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It is Spot 100' plug @ 7,900'	on pleted operations. (Clearly state all perting work). SEE RULE 1103. For Multiple Costs cement on top sole with fresh water gel	HER: ent details, and give pertinpletions: Attach wellbook	
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a	npleted operations. (Clearly state all pertin work). SEE RULE 1103. For Multiple Co. 5' cement on top tole with fresh water gel PERF 7 SQZ 25 3*5 and shot and pull at freepoint. Est. freepoint	HER: ent details, and give pertinpletions: Attach wellbook OC: TAG @ 4,450'	
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1	npleted operations. (Clearly state all pertin work). SEE RULE 1103. For Multiple Co. 5' cement on top tole with fresh water gel PERF 7 SQZ 25 3*5 and shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" sho	HER: ent details, and give pertinpletions: Attach wellbook OC: TAG @ 4,450' e. WOC and tag	
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @	npleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs cement on top tole with fresh water gel PERF 3 SQZ 25385 and shot and pull at freepoint. Est. freepoint (2" stub. Bring cement 50' above 8 5/8" shot (2200') PERF 5 SQZ	HER: ent details, and give pertinpletions: Attach wellbook OC TAG @ 4,450' e. WOC and tag	
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a	npleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs cement on top tole with fresh water gel PERF ; SQZ 25 5 5 6 6 2200' PERF 5 5 2 7 nd shot and pull at freepoint. Est. freepoint freepoint shot and pull at freepoint. Est. freepoint freepoint shot and pull at freepoint. Est. freepoint freepoint. Est. freepoint shot and pull at freepoint. Est. freepoint.	HER: ent details, and give pertinpletions: Attach wellbook OC TAG @ 4,450' e. WOC and tag	
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a	npleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF 2 SQZ 25 3*5 and shot and pull at freepoint. Est. freepoint 1/2" stub. Bring cement 50' above 8 5/8" shot 2200' PERF 5 SQZ nd shot and pull at freepoint. Est. freepoint 1/8" stub. TOS plug @ 1200'. WOC and tag	HER: ent details, and give pertinpletions: Attach wellbook OC TAG @ 4,450' e. WOC and tag	
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25 5*5 W and shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF > SQZ and shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag 15'. WOC and tag	HER: ent details, and give pertinpletions: Attach wellbook OC TAG @ 4,450' e. WOC and tag	ore diagram of proposed completion
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25 5*5 W and shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF > SQZ and shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag 15'. WOC and tag	HER: ent details, and give pertinpletions: Attach wellbook OC: TAG @ 4,450' e. WOC and tag DOC: TAG @ 1,200'	
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF 7 SQZ 25 3K5 Wand shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF 5 SQZ and shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag 15'. WOC and tag	HER: ent details, and give pertinpletions: Attach wellbook OC: TAG @ 4,450' e. WOC and tag DOC: TAG @ 1,200'	ore diagram of proposed completion
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF 7 SQZ 25 3K5 Wand shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF 5 SQZ and shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag 15'. WOC and tag	HER: ent details, and give pertinpletions: Attach wellbook OC: TAG @ 4,450' e. WOC and tag DOC: TAG @ 1,200'	ore diagram of proposed completion
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF 7 SQZ 25 3K5 Wand shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF 5 SQZ and shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag 15'. WOC and tag	HER: ent details, and give pertinpletions: Attach wellbook OC: TAG @ 4,450' e. WOC and tag DOC: TAG @ 1,200'	ore diagram of proposed completion
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF 7 SQZ 25 3K5 Wand shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF 5 SQZ and shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag 15'. WOC and tag	HER: ent details, and give pertinpletions: Attach wellbook OC: TAG @ 4,450' e. WOC and tag DOC: TAG @ 1,200'	ore diagram of proposed completion
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface Set dryhole marker. Clear	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25 3*5 Wand shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF > SQZ nd shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag 15'. WOC and tag and restore surface location for inspection	HER: ent details, and give pertinpletions: Attach wellbook OC: TAG @ 4,450' e. WOC and tag DOC: TAG @ 1,200'	AUG 2 6 2008 AUG 2 6 2008
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface Set dryhole marker. Clear	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25 3K5 Wand shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF > SQZ nd shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag 15'. WOC and tag and restore surface location for inspection on above is true and complete to the best of	HER: ent details, and give pertinpletions: Attach wellbook OC:TAG @ 4,450' e. WOC and tag LOC:TAG @ 1,200'	AUG 2 6 2009 AUG 2 6 2009 AUG 2 6 2009 To below-
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface Set dryhole marker. Clear	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25 3*5 Wand shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF > SQZ nd shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag 15'. WOC and tag and restore surface location for inspection	HER: ent details, and give pertinpletions: Attach wellbook OC:TAG @ 4,450' e. WOC and tag LOC:TAG @ 1,200'	AUG 2 6 2009 AUG 2 6 2009 AUG 2 6 2009 To below-
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It Spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface Set dryhole marker. Clear	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25 3K5 Wand shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF > SQZ nd shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag 15'. WOC and tag and restore surface location for inspection on above is true and complete to the best of	HER: ent details, and give pertinpletions: Attach wellbook OC:TAG @ 4,450' e. WOC and tag LOC:TAG @ 1,200'	AUG 2 6 2009 AUG 2 6 2009 AUG 2 6 2009 To below-
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It spot 100' plug @ 7,900' Freepoint 4 1/2" casing a spot 50' in and out at 4 1 spot 100' plug @ BOS @ Freepoint 8 5/8" casing a spot 50' in and out at 8 5 spot 100' shoe plug @ 4 spot 100' plug @ surface Set dryhole marker. Clear	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25 3*5 and shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" shot 2200' PERF > SQZ. Ind shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag is the stub. TOS plug @ 1200'. WOC and tag is and restore surface location for inspection on above is true and complete to the best of or closed according to NMOCD guidelines , a general personal process of the surface in the surface location for inspection or closed according to NMOCD guidelines , a general personal per	HER: ent details, and give pertinpletions: Attach wellbook OC: TAG @ 4,450' e. WOC and tag LOC: TAG @ 1,200' my knowledge and belieneral permit or an (attach	AUG 2 6 2008 AUG 2 6 2008 OBBS OCD f. I further certify that any pit or belowned) alternative OCD-approved plan
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface Set dryhole marker. Clear I hereby certify that the informatic grade tank has been/will be constructed SIGNATURE Type or print name Devin Garn	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25 5*5 and shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" shot 2200' PERF > SQZ Ind shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag is the study of the state of the section of the s	HER: ent details, and give pertinpletions: Attach wellbook OC: TAG @ 4,450' e. WOC and tag LOC: TAG @ 1,200' my knowledge and belieneral permit or an (attach	AUG 2 6 2008 AUG 2 6 2008 OBBS OCD f. I further certify that any pit or belowned) alternative OCD-approved plan
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It spot 100' plug @ 7,900' Freepoint 4 1/2" casing a spot 50' in and out at 4 1 spot 100' plug @ BOS @ Freepoint 8 5/8" casing a spot 50' in and out at 8 5 spot 100' shoe plug @ 4 spot 100' plug @ surface Set dryhole marker. Clear	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25 5*5 and shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" shot 2200' PERF > SQZ. Ind shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag is the stub. TOS plug @ 1200'. WOC and tag in and restore surface location for inspection or closed according to NMOCD guidelines a general address: E-mail address: Garneroile	MER: ent details, and give pertinpletions: Attach wellbook OC:TAG @ 4,450' e. WOC and tag DOC:TAG @ 1,200' my knowledge and belief meral permit or an (attach Agent Dyahoo.com	AUG 2 6 2008 AUG 2 6 2008 Turther certify that any pit or below- med) alternative OCD-approved plan DATE 8-25-08 Telephone No. (575) 631-4770
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface Set dryhole marker. Clear I hereby certify that the informatic grade tank has been/will be constructed SIGNATURE Type or print name Devin Garn For State Use Only	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25 5*5 and shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" shot 2200' PERF > SQZ. Ind shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag is the stub. TOS plug @ 1200'. WOC and tag in and restore surface location for inspection or closed according to NMOCD guidelines a general address: E-mail address: Garneroile	MER: ent details, and give pertinpletions: Attach wellbook OC TAG @ 4,450' e. WOC and tag DOC TAG @ 1,200' my knowledge and belieneral permit or an (attach Agent	AUG 2 6 2008 AUG 2 6 2008 Turther certify that any pit or below- med) alternative OCD-approved plan DATE 8-25-08 Telephone No. (575) 631-4770
OTHER: 13. Describe proposed or corof starting any proposed or recompletion. Set CIBP @ 10,380' w/3 TIH w/ tubing and circ. It spot 100' plug @ 7,900' Freepoint 4 1/2" casing a Spot 50' in and out at 4 1 Spot 100' plug @ BOS @ Freepoint 8 5/8" casing a Spot 50' in and out at 8 5 Spot 100' shoe plug @ 4 Spot 100' plug @ surface Set dryhole marker. Clear I hereby certify that the informatic grade tank has been/will be constructed SIGNATURE Type or print name Devin Garn	mpleted operations. (Clearly state all pertinwork). SEE RULE 1103. For Multiple Costs of cement on top tole with fresh water gel PERF ? SQZ 25385 and shot and pull at freepoint. Est. freepoint /2" stub. Bring cement 50' above 8 5/8" show 2200' PERF \$ SQZ. Ind shot and pull at freepoint. Est. freepoint /8" stub. TOS plug @ 1200'. WOC and tag is work. WOC and tag is work and restore surface location for inspection on above is true and complete to the best of or closed according to NMOCD guidelines , a grant TITLE E-mail address: Garneroil	MER: ent details, and give pertinpletions: Attach wellbook OC:TAG @ 4,450' e. WOC and tag DOC:TAG @ 1,200' my knowledge and belief meral permit or an (attach Agent Dyahoo.com	AUG 2 6 2008

8-25-08 N.E. Maljamar 31 165 33E 30-025-21291 Spot 100' cmt Plus From 100' to Surface 1134@ 395 Shot & Pull B% Css@ 1200'. SPot 50'in a cut@ 5146. TOS@ 1,200' SPOT 100' CM+ Plus @ 2200'. BOS 8 5/8@ 4430' Shot + Pull Cs5 @ 4450'. Spot 50'in + out XXXXXX at Stub. Will Bring ont 50' above 8% Shoe. 100' cmt Plug @ 7,900'

(IBP w/ 35' Cement@ Perfs @ 10,410-446

(IBP@ 10.530 Perfs @ 10,410-446

Perfs @ 10,684-812

4//2 @ 10,900

Spot 50' in 2 out @ 1134 Shoe

est toc