

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

PERMIT DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

SEP - 2 2008

HOBBS

WELL API NO. 30-025-34621
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. A-1375-45
7. Lease Name or Unit Agreement Name Lisa State
8. Well Number 2
9. OGRID Number 236790
10. Pool name or Wildcat Eumont Y-SR-Q

SUNDRY NOTICE AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator XOG OPERATING, LLC
3. Address of Operator P. O. BOX 352, MIDLAND, TX 79702
4. Well Location Unit Letter B : 660 feet from the North line and 1980 feet from the East line Section 19 Township 20S Range 36E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3634' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/22/06 Pull out of hole w/tbg.
7/6/08 Notify OCD.
7/7/08 MIRU Mayo Mars. ND well head. NU BOP. RIH with MMCPI workstring to 3,830' & spot 25 sacks cmt. Pull out of hole & wait on cement. Run in hole, no tag. Re-spot 25 sacks cmt. Pull out of hole. Wait on cement. SDFD.
7/8/08 RIH & tag@ 3,400'. Circ plugging mud. Test csg. Spot 25 sacks @ 2,000'. PUH to 431' & spot 50 sacks. POH. Top off with cement. Cut off well head, dig out cellar & install PA marker. RDMO.

Approved for plugging of well bore only.
Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.emurd.state.nm.us/oed.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 8/26/08
Type or print name Angie Crawford E-mail address: acrawford@xogoperating.com PHONE: 432-683-3171

For State Use Only

APPROVED BY: Tim M. Hill TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE SEP 03 2008
Conditions of Approval (if any):