State of New Mexico Form C-103	
FILE IN TRIPLICATE OIL CONSERVATION DIVISION	Revised 3-27-2004
DISTRICT I 1220 South St. Francis Dr.	WELL API NO.
DISTRICT II	30-025-36216 5. Indicate Type of Lease
DISTRICT II 1301 W Grand Ave, Artesil, NY1882 PPS ()	STATE X FEE
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals) 1. Type of Well	Section 30 8. Well No. 525
Oil Well X Gas Well Other	8. Well No. 525
2 Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd. 3 Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323 4 Well Location	
Unit Letter K : 1947 Feet From The South 2139 Feet From The West Line	
Section 30 Township 18-S Range 38-1 11. Elevation (Show whether DF, RKB, RT GR, etc.) 11. Elevation (Show whether DF, RKB, RT GR, etc.) 11. Elevation (Show whether DF, RKB, RT GR, etc.) 11. Elevation (Show whether DF, RKB, RT GR, etc.) 11. Elevation (Show whether DF, RKB, RT GR, etc.) 11. Elevation (Show whether DF, RKB, RT GR, etc.)	E NMPM Lea County
3666' KB	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thicknessmil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or ONOTICE OF INTENTION TO:	Dther Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB	
OTHER: Clean out/OAP/Acid treat X OTHER:	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of . Kill well.	completion or recompletion.
2. POOH w/ESP equipment.	
 Clean out to PBTD @4347'. Perforate hole. 	
 Acid treat we w/20 bbl of 15% PAD HCL acid. Perform scale squeeze. 	
 7. Run back on hole w/ESP equipment and return well to production. 	
	. '
·	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify	that any pit or below-grade tank has been/will be
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	e OCD-approved
SIGNATURE MANAGE Administrative	Associate DATE 09/16/2008
TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	TELEPHONE NO. 806-592-6280
For State Use Only	ENGINEER OF DO 2 2000
APPROVED BY TITLE	
	DSTEP 2 2 2008
CONDITIONS OF APPROVAL IF ANY:	

,