Office	State of New Mo		Form C-103	
District I	Energy, Minerals and Nati	ural Resources	WELL API NO.	1
1625 N. French Dr , Hoppe 144 3240 District II		!	30-025-28763	
1301 W Grand Ave., Artesia, NM 88210	OIL CONSERVATION	1 '	5. Indicate Type of Lease	\dashv
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra	ncis Dr.	STATE E FEE	
	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.	
District IV 1220 S. St. Francis Dr., Sand F. Pily 1 87505	2008		L-521	
	S AND REPORTS ON WELLS	S	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSAL	LS TO DRILL OR TO DEEPEN OR PL	LUG BACK TO A	- /	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		State "23" Com V		
1. Type of Well: Oil Well Gas Well 9ther			8. Well Number 2	
2. Name of Operator CrownQuest Operating, LLC		!	9. OGRID Number / 213190	
3. Address of Operator			10. Pool name or Wildcat	\dashv
303 Veterans Arprk Ln, Ste 5100 Midland, TX 79710			Tulk (Penn)	
4. Well Location				
Unit Letter N : 6	60' feet from the Sout	h line and 19	80' feet from the West line	/
Section 23	Township 14S R	ange 32E	NMPM County Lea 🗸	
	11. Elevation (Show whether DR	R, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application ☐ or C	4307' KB			
				-
	Distance from nearest fresh			
Pit Liner Thickness: mil		bbls; Cons		J
12. Check App	propriate Box to Indicate N	Nature of Notice, R	eport or Other Data	
NOTICE OF INTE	ENTION TO:	SUBS	EQUENT REPORT OF:	
	PLUG AND ABANDON	REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON 🗵 (CHANGE PLANS	COMMENCE DRILL	LING OPNS.□ P AND A □	
···· - · · · · · · · · · · · · · · ·		OOMMENTOE BITTEE		
	MULTIPLE COMPL	CASING/CEMENT	JOB	
PULL OR ALTER CASING		CASING/CEMENT	JOB	
PULL OR ALTER CASING OTHER:		CASING/CEMENT	_	_ te
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete	MULTIPLE COMPL Ged operations. (Clearly state all	CASING/CEMENT OTHER: pertinent details, and §	give pertinent dates, including estimated datch wellbore diagram of proposed completion	
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete	MULTIPLE COMPL Ged operations. (Clearly state all	CASING/CEMENT OTHER: pertinent details, and §	give pertinent dates, including estimated da	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion.	MULTIPLE COMPL ded operations. (Clearly state all). SEE RULE 1103. For Multip	CASING/CEMENT OF COTHER: pertinent details, and gole Completions: Attack	give pertinent dates, including estimated datch wellbore diagram of proposed completion	
PULL OR ALTER CASING NOTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h	MULTIPLE COMPL ded operations. (Clearly state all). SEE RULE 1103. For Multiples prior to commen	CASING/CEMENT COTHER: pertinent details, and gole Completions: Attached	give pertinent dates, including estimated datch wellbore diagram of proposed completion	
PULL OR ALTER CASING	ed operations. (Clearly state all). SEE RULE 1103. For Multipars prior to commens	CASING/CEMENT OTHER: pertinent details, and gole Completions: Attachnicement of TACON workstring	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure.	
PULL OR ALTER CASING	MULTIPLE COMPL ded operations. (Clearly state all). SEE RULE 1103. For Multiples prior to commen	CASING/CEMENT OTHER: pertinent details, and gole Completions: Attachnicement of TACON workstring	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h. 2. RIH w/bit, csg. 3. Set pkr ± 9670 h.	ed operations. (Clearly state all). SEE RULE 1103. For Multipars prior to commens	CASING/CEMENT OTHER: pertinent details, and gole Completions: Attachnoment of TACON workstring detest to 500	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. J. psi for 30 min.	
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h 2. RIH w/bit, csg 3. Set pkr ± 9670 h If test is go	ed operations. (Clearly state all). SEE RULE 1103. For Multip ars prior to comment scraper, and pkr of , load annulus and bood, release pkr and	CASING/CEMENT COTHER: pertinent details, and gole Completions: Attachnicement of TACON workstring ditest to 500 and POH w/BHA	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. J. psi for 30 min.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h 2. RIH w/bit, csg 3. Set pkr ± 9670 h If test is go 4. RIH w/CIBP on w	ed operations. (Clearly state all). SEE RULE 1103. For Multiputs prior to commensurable and pkr of a load annulus and pod, release pkr and vireline and set @	CASING/CEMENT. OTHER: pertinent details, and gole Completions: Attachnocement of TACON workstring detest to 500 and POH w/BHA ± 9670'.	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. J. psi for 30 min.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h. 2. RIH w/bit, csg. 3. Set pkr ± 9670' If test is go. 4. RIH w/CIBP on w. 6. Run MIT with ch.	ed operations. (Clearly state all). SEE RULE 1103. For Multip ars prior to comment scraper, and pkr of t, load annulus and bod, release pkr and vireline and set @ hart @ 500 psi for	CASING/CEMENT COTHER: pertinent details, and gole Completions: Attachnicement of TACON workstring dotest to 500 and POH w/BHA ± 9670'. 30 min.	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. J. psi for 30 min.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h. 2. RIH w/bit, csg. 3. Set pkr ± 9670' If test is go. 4. RIH w/CIBP on w. 6. Run MIT with ch.	ed operations. (Clearly state all). SEE RULE 1103. For Multiputs prior to commensurable and pkr of a load annulus and pod, release pkr and vireline and set @	CASING/CEMENT COTHER: pertinent details, and gole Completions: Attachnicement of TACON workstring dotest to 500 and POH w/BHA ± 9670'. 30 min.	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. J. psi for 30 min.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h. 2. RIH w/bit, csg. 3. Set pkr ± 9670' If test is go. 4. RIH w/CIBP on w. 6. Run MIT with ch.	ed operations. (Clearly state all). SEE RULE 1103. For Multipars prior to commensurate and pkr of an annulus and pod, release pkr and vireline and set @ nart @ 500 psi for Notice with chart	CASING/CEMENT COTHER: pertinent details, and gole Completions: Attachnicement of TACON workstring dotest to 500 and POH w/BHA ± 9670'. 30 min.	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. J. psi for 30 min.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h 2. RIH w/bit, csg 3. Set pkr ± 9670' If test is go 4. RIH w/CIBP on w 6. Run MIT with ch 7. Forward Sundry	ed operations. (Clearly state all). SEE RULE 1103. For Multiputs prior to commensurate and pkr of an analysis and pkr of an analysis and set @ vireline and set @ nart @ 500 psi for Notice with chart	CASING/CEMENT COTHER: pertinent details, and gole Completions: Attachnicement of TACON workstring dotest to 500 and POH w/BHA ± 9670'. 30 min.	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. J. psi for 30 min.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h. 2. RIH w/bit, csg. 3. Set pkr ± 9670' If test is go. 4. RIH w/CIBP on w. 6. Run MIT with ch. 7. Forward Sundry. Condition of App.	ed operations. (Clearly state all). SEE RULE 1103. For Multiputs prior to commensurate and pkr of the control	CASING/CEMENT. OTHER: pertinent details, and gole Completions: Attachnology of the completions of TA on workstring dotest to 500 and POH w/BHA ± 9670'. 30 min. to OCD.	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. J. psi for 30 min.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h. 2. RIH w/bit, csg. 3. Set pkr ± 9670' If test is go. 4. RIH w/CIBP on w. 6. Run MIT with ch. 7. Forward Sundry. Condition of App.	ed operations. (Clearly state all). SEE RULE 1103. For Multiputs prior to commensurate and pkr of an analysis and pkr of an analysis and set @ vireline and set @ nart @ 500 psi for Notice with chart	CASING/CEMENT. OTHER: pertinent details, and gole Completions: Attachnology of the completions of TA on workstring dotest to 500 and POH w/BHA ± 9670'. 30 min. to OCD.	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. J. psi for 30 min.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h 2. RIH w/bit, csg 3. Set pkr ± 9670' If test is go 4. RIH w/CIBP on w 6. Run MIT with ch 7. Forward Sundry Condition of Approfice 24 hours p	ed operations. (Clearly state all but of the comment of the commen	CASING/CEMENT. OTHER: pertinent details, and gole Completions: Attachnology of the Completions of TA on workstring dotest to 500 and POH w/BHA ± 9670'. 30 min. to OCD.	give pertinent dates, including estimated datch wellbore diagram of proposed completion of procedure. A procedure. J. D psi for 30 min. and tbg.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h 2. RIH w/bit, csg 3. Set pkr ± 9670' If test is go 4. RIH w/CIBP on w 6. Run MIT with ch 7. Forward Sundry Condition of Approfice 24 hours p	ed operations. (Clearly state all). SEE RULE 1103. For Multiputs prior to commensurate prior to commensurate and part of the secretary and part of the secretary and part of the secretary and set of the secretary and part of the secretary and set of the secretary and secretary	CASING/CEMENT. OTHER: pertinent details, and gole Completions: Attachnology of the Completions of TA on workstring dotest to 500 and POH w/BHA ± 9670'. 30 min. to OCD. Chart	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. 3. 3. 4. procedure. 5. 6. psi for 30 min. 6. and tbg.	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h. 2. RIH w/bit, csg 3. Set pkr ± 9670' If test is go 4. RIH w/CIBP on w 6. Run MIT with ch 7. Forward Sundry Condition of Approfice 24 hours p	ed operations. (Clearly state all bed operations.) SEE RULE 1103. For Multiputs prior to commensurate prior to commensurate and pkr of an analysis and prod, release pkr and pireline and set @ part @ 500 psi for Notice with chart proval: Notify OCD Hobbs prior to running MIT Test & cove is true and complete to the best according to NMOCD guidelines [CASING/CEMENT. OTHER: pertinent details, and gole Completions: Attachnology of the Completions of TA on workstring dotest to 500 and POH w/BHA ± 9670'. 30 min. to OCD. Chart Dest of my knowledge and, a general permit or	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. J. psi for 30 min. and tbg. and belief. I further certify that any pit or below an (attached) alternative OCD-approved plan	
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h 2. RIH w/bit, csg 3. Set pkr ± 9670 h If test is go 4. RIH w/CIBP on w 6. Run MIT with ch 7. Forward Sundry Condition of Approfice 24 hours p I hereby certify that the information aborder and the constructed or close SIGNATURE	ed operations. (Clearly state all). SEE RULE 1103. For Multiputs prior to comment scraper, and pkr of an annulus and pod, release pkr and vireline and set @ nart @ 500 psi for Notice with chart proval: Notify OCD Hobbs prior to running MIT Test & cove is true and complete to the best according to NMOCD guidelines [CASING/CEMENT. OTHER: pertinent details, and gole Completions: Attachnology of the completions of the constant of the constan	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. 3. 3. 4. procedure. 5. 6. psi for 30 min. 6. and tbg. and tbg. and tbg. Projects DATE 9/17/08	·
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h 2. RIH w/bit, csg 3. Set pkr ± 9670 h If test is go 4. RIH w/CIBP on w 6. Run MIT with ch 7. Forward Sundry Condition of Approfice 24 hours p I hereby certify that the information abording and tank has been/will be constructed or close SIGNATURE Don Rosers Type or print name	ed operations. (Clearly state all object of the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to Complete to Complete to the best according to Complete to Comple	CASING/CEMENT. OTHER: pertinent details, and gole Completions: Attachnology of the Completions of TARON workstring of test to 500 and POH w/BHA ± 9670'. 30 min. to OCD. Chart Lest of my knowledge and a general permit or	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. In a procedure. In a procedure. In and the procedure of proposed completion and the procedure. In and the procedure of proposed completion and the procedure. In and the procedure of proposed completion of procedure. In and the procedure of proposed completion of procedure. In and the procedure of proposed completion of procedure. In and the procedure of proposed completion of proposed c	on .
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h 2. RIH w/bit, csg 3. Set pkr ± 9670 h If test is go 4. RIH w/CIBP on w 6. Run MIT with ch 7. Forward Sundry Condition of Approfice 24 hours p I hereby certify that the information aborders of the start of t	ed operations. (Clearly state all object of the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to Complete to Complete to the best according to Complete to Comple	CASING/CEMENT. OTHER: pertinent details, and gole Completions: Attachnology of the Completions of TARON workstring of test to 500 and POH w/BHA ± 9670'. 30 min. to OCD. Chart Lest of my knowledge and a general permit or	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. In a procedure. In a procedure. In and the procedure of proposed completion and the procedure. In and the procedure of proposed completion and the procedure. In and the procedure of proposed completion of procedure. In and the procedure of proposed completion of procedure. In and the procedure of proposed completion of procedure. In and the procedure of proposed completion of proposed c	on .
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 1. Notify OCD 24 h 2. RIH w/bit, csg 3. Set pkr ± 9670 h If test is go 4. RIH w/CIBP on w 6. Run MIT with ch 7. Forward Sundry Condition of Approfice 24 hours p I hereby certify that the information abording and tank has been/will be constructed or close SIGNATURE Don Rosers Type or print name	ed operations. (Clearly state all object of the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to Complete to the best according to NMOCD guidelines [E-mail according to Complete to the best according to Complete to Complete to the best according to Complete to Comple	CASING/CEMENT. OTHER: pertinent details, and gole Completions: Attachnology of the completions of TA on workstring of test to 500 and POH w/BHA ± 9670'. 30 min. to OCD. Chart Test of my knowledge and a general permit or	give pertinent dates, including estimated datch wellbore diagram of proposed completion approach procedure. In a procedure. In a procedure. In a procedure. In a procedure. In and the projects of the pr	·

£2,