	ate of New Mexico inerals and Natural Resources	Form C-103 June 19, 2008
1625 N French Dr , Hobbs, NM 88240		WELL API NO. 30-025-26196
District II 1301 W Gran SAE, Articia, M2008 OIL CONSERVATION DIVISION District III 1000 Rio Brazos Rd, Aziec, NM 87410 District IV		5. Indicate Type of Lease
		STATE     FEE     Image: Constraint of the second s
1220 S St Fanal pr Hand of March 120 S		B-934
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS )		New Mexico AB State 🗸
1. Type of Well: Oil Well 🔲 Gas Well 📕 Other 🖌		8. Well Number 5
2. Name of Operator EnerVest Operating, L.L.C.		9. OGRID Number 143199
3. Address of Operator 1001 Fannin, Suite 800 Houston, TX 77002		10. Pool name or Wildcat Langlie Mattix (7R-Qn-Gb)
4. Well Location Unit Letter H . 1880 feet from the North line and 660 feet from the East line		
	om the <u>North</u> line and ship 24S Range 37E	660 feet from the East line NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3269' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
OTHER:       Refrac (Workover)       OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
<ol> <li>MIRU workover unit.</li> <li>RU to pull rods and downhole pump from well. POOH w/ pump and rods.</li> </ol>		
<ol> <li>Drop standing value and pressure test tubing to +/- 500 psig</li> </ol>		
<ol> <li>Release tubing anchor and pull tubing from well.</li> <li>RIH with RBP and set at +/- 3100'. Dump 10' of sand on top of RBP.</li> </ol>		
6. Pressure test casing to 1500#. RIH and retrieve RBP.		
<ol> <li>Acidize and refrac well. Current perfs = 3166-3422'.</li> <li>Open well to flow back on 10/64" choke.</li> </ol>		
9. If well fails to flow, run tubing, rods, and downhole pump into well.		
10. RDMO workover unit.		
11. Turn well to production.		
Spud Date: 03/16/1979	Rig Release Date:	03/25/1979
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Bridget Helfrich	TITLE Regulatory Tec	hDATE09/26/2008
Type or print name Bridget Helfrich	E-mail address:bhelfrich@en	I HONE
ALL I	PETROLEUM ENGINEE	0 CT 0 3 2008
APPROVED BY:		

• •