Submit 3 Copies To Appropriate District State of New Mexico Office	E 0.103
Enorgy Minorals and Natural Decourage	Form C-103 May 27, 2004
<u>District I</u> Energy, Minerals and Natural Resources 1625 N French Dr , Hobbs, NM 88240	WELL API NO.
District II 1301 W Grand Ave, Artes IN 8210 2008 IL CONSERVATION DIVISION	30-025-05135
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE BLM
District III 1000 Rio Brazos Respective for Stanta Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Lee Whitman A
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well Gas Well Other – Injection Well	8. Well Number #1
2. Name of Operator Americo Energy Resources, LLC	9. OGRID Number 228051
3. Address of Operator	10. Pool name or Wildcat
7575 San Felipe, Suite 200, Houston, TX 77063	Denton (Devonian)
4. Well Location	
Unit LetterG_:1980feet from theNorth line and19	80feet from theEastline /
Section 26 Township 14S Range 37E	
11. Elevation (Show whether DR, RKB, RT, GR, etc. 3800' GL	
Pit or Below-grade Tank Application or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water well Dis	ance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; C	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
	•
NOTICE OF INTENTION TO: SUE PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	SEQUENT REPORT OF: K ☐ ALTERING CASING ☐
	LLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	_
OTHER OTHER:	_
OTHER. OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion.	tach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to 	tach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring 	tach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon 	tach wellbore diagram of proposed completion
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' 	p of perf's @ 12,230' poh w/
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon 	p of perf's @ 12,230' poh w/
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' 	p of perf's @ 12,230' poh w/
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi for 	p of perf's @ 12,230' poh w/
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi for if test is good, n/d bop, n/u well head, run chart test to 50. 	p of perf's @ 12,230' poh w/
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi fc if test is good, n/d bop, n/u well head, run chart test to 500 min for OCD T/A status. Rdwor 	p of perf's @ 12,230' poh w/
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi for if test is good, n/d bop, n/u well head, run chart test to 500 min for OCD T/A status. Rdwor 	p of perf's @ 12,230' poh w/
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi fc if test is good, n/d bop, n/u well head, run chart test to 500 min for OCD T/A status. Rdwor 	p of perf's @ 12,230' poh w/
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi for if test is good, n/d bop, n/u well head, run chart test to 500 min for OCD T/A status. Rdwor 	p of perf's @ 12,230' poh w/
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi for if test is good, n/d bop, n/u well head, run chart test to 500 min for OCD T/A status. Rdwor 	p of perf's @ 12,230' poh w/
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi fc if test is good, n/d bop, n/u well head, run chart test to 500 min for OCD T/A status. Rdwor Condition of Approval: Notify OCD Hobbs Office 24 hours prior to running MIT Test & Chart	tach wellbore diagram of proposed completion p of perf's @ 12,230' poh w/ er 30 min 500 psi
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi for if test is good, n/d bop, n/u well head, run chart test to 5 For 30 min for OCD T/A status. Rdwor Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart	tach wellbore diagram of proposed completion p of perf's @ 12,230' poh w/ er 30 min 600 psi e and belief. I further certify that any pit or below-
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi for if test is good, n/d bop, n/u well head, run chart test to 500 min for OCD T/A status. Rdwor Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart I hereby certify that the information above is true and complete to the best of my knowledged tank has been/will be constructed or closed according to NMOCD guidelines , a general permit	e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon Rih w/ wire line tag top of cmt-if top of cmt at 12,175' r/d wire line trk, load csg and pressure test to 500 psi for if test is good, n/d bop, n/u well head, run chart test to 500 min for OCD T/A status. Rdwor Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart I hereby certify that the information above is true and complete to the best of my knowledged tank has been/will be constructed or closed according to NMOCD guidelines , a general permit	e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring 2) Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon 3) Rih w/ wire line tag top of cmt-if top of cmt at 12,175' 4) r/d wire line trk, load csg and pressure test to 500 psi for if test is good, n/d bop, n/u well head, run chart test to 50 psi for 30 min for OCD T/A status. Rdwor Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines a general permit SIGNATURE TITLE Labory A Type or print name: Ehsan Bayat A-mail address: ehsan.bayat@americeenergy.com T	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 9-26-08.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring 2) Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon 3) Rih w/ wire line tag top of cmt-if top of cmt at 12,175' 4) r/d wire line trk, load csg and pressure test to 500 psi for if test is good, n/d bop, n/u well head, run chart test to 5 for 30 min for OCD T/A status. Rdwor Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines a general permit SIGNATURE SIGNATURE TITLE TITL	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 9-26-08. elephone No. 713-984-9700
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 1) Miru wor, n/d wellhead n/u bop, rih w/ gauge ring to to gauge ring 2) Rih w/ bailer & dump 25'+cmt 12,200'-12,175' sdon 3) Rih w/ wire line tag top of cmt-if top of cmt at 12,175' 4) r/d wire line trk, load csg and pressure test to 500 psi for if test is good, n/d bop, n/u well head, run chart test to 50 for 30 min for OCD T/A status. Rdwor Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed or closed according to NMOCD guidelines a general permit according to the constructed or closed according to the constructe	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 9-26-08.