Office	State of New Me	exico	Form C-103
District I	Energy, Minerals and Natu	ıral Resources	May 27, 2004
1625 N. French The Highest N. 1882 10.			WELL API NO. 30-025-05222
1301 W. Grand Ave. Artesia NM 88210	OIL CONSERVATION		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd , Azite, NP87200	1220 South St. Fran		STATE FEE BLM
District IV	2008 Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr. Santar Fey M. 87505	ad a		
	S AND REPORTS ON WELLS	•	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA			B.C. Dickinson A1
DIFFERENT RESERVOIR USE "APPLICA" PROPOSALS)	TION FOR PERMIT (FORM C-101) FO	JR SUCH	
1. Type of Well: Oil Well Gas Well Other — Injection Well		/ell-	8. Well Number # 1
2. Name of Operator			9. OGRID Number
Americo Energy Resources, LLC			228051 10. Pool name or Wildcat
3. Address of Operator 7575 San Felipe, Suite 200, Houston, TX 77063		Denton (Wolfcamp)	
4. Well Location	, 17, 77003		benton (Woneamp)
Unit Letter L: 1980 feet from the South line and 660 feet from the West line			
Section 1 Township 15S Range 37E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
	3820' Drive Bushing	, MMD, M1, GM, e1c.)	
Pit or Below-grade Tank Application or			
Pit typeDepth to Groundwat	erDistance from nearest fresh w	vater well Dista	ance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Cou	nstruction Material
12 Check A	opropriate Box to Indicate N	lature of Notice 1	Report or Other Data
NOTICE OF INT			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	_
TEMPORARILY ABANDON	CHANGE PLANS	CASING/CEMENT	_
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB []
OTHER:		OTHER:	
			give pertinent dates, including estimated date
of starting any proposed wor			give pertinent dates, including estimated date ach wellbore diagram of proposed completion
of starting any proposed work or recompletion.	k). SEE RULE 1103. For Multip	le Completions: Att	ach wellbore diagram of proposed completion
of starting any proposed work or recompletion. 1) Miru wor, n/d wel	k). SEE RULE 1103. For Multip	le Completions: Att	
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau	k). SEE RULE 1103. For Multip lhead n/u bop, poh w/ 9 uge ring	le Completions: Att	ach wellbore diagram of proposed completion
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun	k). SEE RULE 1103. For Multip lhead n/u bop, poh w/ 9 uge ring 1p 25'+cmt 9300'-9275	le Completions: Att O1 jts 2 7/8" th "sdon	ach wellbore diagram of proposed completion
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau	k). SEE RULE 1103. For Multip lhead n/u bop, poh w/ 9 uge ring 1p 25'+cmt 9300'-9275	le Completions: Att O1 jts 2 7/8" th "sdon	ach wellbore diagram of proposed completion
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag	k). SEE RULE 1103. For Multip lhead n/u bop, poh w/ 9 uge ring up 25'+cmt 9300'-9275 top of cmt-if top of cm	le Completions: Att 91 jts 2 7/8" th " sdon 1t at 9275'	ach wellbore diagram of proposed completion oing, rih w/ gauge ring to top of
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa	k). SEE RULE 1103. For Multip Ihead n/u bop, poh w/ 9 uge ring up 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes	le Completions: Att Of jts 2 7/8" th orange of the completions: Att orange of the completio	ach wellbore diagram of proposed completion bing, rih w/ gauge ring to top of r 30 min
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih w	k). SEE RULE 1103. For Multip lhead n/u bop, poh w/ 9 uge ring up 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes / 2 7/8" tbing poh layin	le Completions: Att 91 jts 2 7/8" th " sdon 1t at 9275' t to 500 psi for ng down n/d be	ach wellbore diagram of proposed completion oing, rih w/ gauge ring to top of
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih w	k). SEE RULE 1103. For Multip Ihead n/u bop, poh w/ 9 uge ring up 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes	le Completions: Att 91 jts 2 7/8" th " sdon 1t at 9275' t to 500 psi for ng down n/d be	ach wellbore diagram of proposed completion bing, rih w/ gauge ring to top of r 30 min
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih w	k). SEE RULE 1103. For Multip lhead n/u bop, poh w/ 9 uge ring up 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes / 2 7/8" tbing poh layin	le Completions: Att 91 jts 2 7/8" th " sdon 1t at 9275' t to 500 psi for ng down n/d be	ach wellbore diagram of proposed completion bing, rih w/ gauge ring to top of r 30 min
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih wetest to 500 psi, For 3	k). SEE RULE 1103. For Multip lhead n/u bop, poh w/ 9 uge ring np 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes / 2 7/8" tbing poh layin 30 min for OCD T/A st	le Completions: Att 91 jts 2 7/8" th " sdon 1t at 9275' t to 500 psi for ng down n/d be	ach wellbore diagram of proposed completion bing, rih w/ gauge ring to top of r 30 min
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih we test to 500 psi, For 3	k). SEE RULE 1103. For Multip Ihead n/u bop, poh w/9 Ige ring Ip 25'+cmt 9300'-9275 I top of cmt-if top of cm Id csg and pressure tes If 2 7/8" tbing poh layin It with the companion of t	le Completions: Att 91 jts 2 7/8" th " sdon 1t at 9275' t to 500 psi for ng down n/d be	ach wellbore diagram of proposed completion bing, rih w/ gauge ring to top of r 30 min
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih wetest to 500 psi, For 3	k). SEE RULE 1103. For Multip Ihead n/u bop, poh w/9 Ige ring Ip 25'+cmt 9300'-9275 I top of cmt-if top of cm Id csg and pressure tes If 2 7/8" tbing poh layin It with the companion of t	le Completions: Att 91 jts 2 7/8" th " sdon 1t at 9275' t to 500 psi for ng down n/d be	ach wellbore diagram of proposed completion bing, rih w/ gauge ring to top of r 30 min
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih we test to 500 psi, For 3	k). SEE RULE 1103. For Multip Ihead n/u bop, poh w/9 Ige ring Ip 25'+cmt 9300'-9275 I top of cmt-if top of cm Id csg and pressure tes If 2 7/8" tbing poh layin It with the companion of t	le Completions: Att 91 jts 2 7/8" th " sdon 1t at 9275' t to 500 psi for ng down n/d be	ach wellbore diagram of proposed completion bing, rih w/ gauge ring to top of r 30 min
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih we test to 500 psi, For 3	k). SEE RULE 1103. For Multip Ihead n/u bop, poh w/9 Ige ring Ip 25'+cmt 9300'-9275 I top of cmt-if top of cm Id csg and pressure tes If 2 7/8" tbing poh layin It with the companion of t	le Completions: Att 91 jts 2 7/8" th " sdon 1t at 9275' t to 500 psi for ng down n/d be	ach wellbore diagram of proposed completion bing, rih w/ gauge ring to top of r 30 min
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih we test to 500 psi, For 3 Condition of Approval: Not office 24 hours prior to rur	lhead n/u bop, poh w/9 lge ring np 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes l/ 2 7/8" tbing poh laying 30 min for OCD T/A st tify OCD Hobbs nning MIT Test & Chart	le Completions: Att 21 jts 2 7/8" th 23 sdon 24 at 9275' 25 to 500 psi for 26 g down n/d be 26 atus. Rdwor	oing, rih w/ gauge ring to top of r 30 min op, n/u well head, run chart
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, log 5) if test is good, rih we test to 500 psi, For and test to 500 psi, For	lhead n/u bop, poh w/9 uge ring np 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes / 2 7/8" tbing poh layin 30 min for OCD T/A st tify OCD Hobbs nning MIT Test & Chart	ile Completions: Att 21 jts 2 7/8" th 31 sdon 11 at 9275' 12 to 500 psi for 13 gdown n/d be 14 at us. Rdwor	ach wellbore diagram of proposed completion oing, rih w/ gauge ring to top of r 30 min op, n/u well head, run chart e and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, log 5) if test is good, rih we test to 500 psi, For and test to 500 psi, For	lhead n/u bop, poh w/9 uge ring np 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes / 2 7/8" tbing poh layin 30 min for OCD T/A st tify OCD Hobbs nning MIT Test & Chart	ile Completions: Att 21 jts 2 7/8" th 31 sdon 11 at 9275' 12 to 500 psi for 13 gdown n/d be 14 at us. Rdwor	ach wellbore diagram of proposed completion oing, rih w/ gauge ring to top of r 30 min op, n/u well head, run chart e and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih we test to 500 psi, For and test to 500 psi, For	lhead n/u bop, poh w/9 uge ring np 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes / 2 7/8" tbing poh layin 30 min for OCD T/A st tify OCD Hobbs nning MIT Test & Chart bove is true and complete to the boosed according to NMOCD guidelines [ile Completions: Att 21 jts 2 7/8" th 3 sdon 1 at 9275' 1 to 500 psi for 1 g down n/d be 2 atus. Rdwor est of my knowledge 3, a general permit	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan . DATE 9-26-08 June (yst- DATE 9-26-08)
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, log 5) if test is good, rih we test to 500 psi, For and test to 500 psi, For	lhead n/u bop, poh w/9 uge ring np 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes / 2 7/8" tbing poh layin 30 min for OCD T/A st tify OCD Hobbs nning MIT Test & Chart bove is true and complete to the boosed according to NMOCD guidelines [ile Completions: Att 21 jts 2 7/8" th 3 sdon 1 at 9275' 1 to 500 psi for 1 g down n/d be 2 atus. Rdwor est of my knowledge 3, a general permit	e and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . DATE 9-26-08 Jephone No. 713-984-9700
of starting any proposed work or recompletion. 1) Miru wor, n/d well perf's @ 9350' poh w/ gau 2) Rih w/ bailer & dun 3) Rih w/ wire line tag 4) r/d wire line trk, loa 5) if test is good, rih we test to 500 psi, For and test to 500 psi, For	lhead n/u bop, poh w/9 uge ring np 25'+cmt 9300'-9275 top of cmt-if top of cm ad csg and pressure tes / 2 7/8" tbing poh layin 30 min for OCD T/A st tify OCD Hobbs nning MIT Test & Chart bove is true and complete to the boosed according to NMOCD guidelines [ile Completions: Att 21 jts 2 7/8" th 3 sdon 1 at 9275' 1 to 500 psi for 1 g down n/d be 2 atus. Rdwor est of my knowledge 3, a general permit	ach wellbore diagram of proposed completion oing, rih w/ gauge ring to top of r 30 min op, n/u well head, run chart e and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan