

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIP OCT 2 2 2008 OIL CONSERVATION DIVISION	
DISTRICT I 1625 G. Freech 188840 Santa Fe, NM 87505 DISTRICT I 1301 W. Grand Ave, Artesia, NM 88210	WELL API NO. 30-025-29521
DISTRICTAL DESCRIPTION OF THE PROPERTY OF THE	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210 DISTRICT III	STATE X FEE 6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	South Hobbs (G/SA) Unit
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 5
Type of Well: Oil Well Gas Well Other Injector Other Injector	8. Well No. 208
2 Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323	10. Pool name or Wildcat Hobbs (G/SA)
4 Well Location	I
Unit Letter N : 931 Feet From The South 2263 Fee	t From The West Line
Section 5 Township 19-S Range 38-F	NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3629' KB	, Eca county
Pit or Below-grade Tank Application or Closure Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	
	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OF ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze perfs to isolate injection X OTHER:	NS. PLUG & ABANDONMENT TJOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	NS. PLUG & ABANDONMENT TJOB nicluding estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OR ALTER CASING Multiple Completion CASING TEST AND CEMENTO OTHER: Squeeze perfs to isolate injection X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the clean out to PBTD @4280'. 13. Squeeze perfs at 4075-4101'. 14. Test squeeze to 500 PSI. 15. RIH w/dual injection packer assembly. 16. Test casing and chart for the NMOCD. 17. Return well to injection.	NS. PLUG & ABANDONMENT IT JOB including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENTOTHER: Squeeze perfs to isolate injection X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of 1. Kill well. POOH w/injection equipment. 2. Clean out to PBTD @4280'. 3. Squeeze perfs at 4075-4101'. 4. Test squeeze to 500 PSI. 5. RIH w/dual injection packer assembly. 6. Test casing and chart for the NMOCD. 7. Return well to injection.	NS. PLUG & ABANDONMENT IT JOB including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OR ALTER CASING Multiple Completion CASING TEST AND CEMENTO OTHER: Squeeze perfs to isolate injection X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the clean out to PBTD @4280'. 13. Squeeze perfs at 4075-4101'. 14. Test squeeze to 500 PSI. 15. RIH w/dual injection packer assembly. 16. Test casing and chart for the NMOCD. 17. Return well to injection.	NS. PLUG & ABANDONMENT IT JOB including estimated date of starting any completion or recompletion.

TYPE OR PRINT NAME E-mail address: mendy_johnson@oxy.com TELEPHONE NO 806-592-6280 For State Use Only

APPROVED BY CONDITIONS OF APPROVAL IF ANY