0070-000		OF THE INTERIOR		FORM APPROVED OMB No 1004-0137 Expires July 31, 2010
0 CT 2 1 2008		AND MANAGEMENT		5 Lease Serial No
SUND	RY NOTICES A	ND REPORTS ON W	VELLS	NMNM70988X 6 If Indian, Allottee or Tribe Name
abandone	ed well. Use Form	oposals to drill or to re 3160-3 (APD) for such j	enter an proposals.	NM09015
		Other instructions on	A CARLE IN CONTRACTOR	7 If Unit or CA/Agreement, Name and/or No
1 Type of Well			r page z	
Oil Well Gas Well	Other			Maljamar Grayburg 8 Weil Name and No
2 Name of Operator				Maljamar Grayburg Unit 89
Forest Oil Corporation				9 API Well No
3a Address		3b Phone No (include area c	code)	30-025-33048
707 17 th St. Ste 3600, Den 4 Location of Well (Footage, Sec. 7	iver, CO 80202	303-812-1554		10 Field and Pool, or Exploratory Area
Sec. 4, T-17-S, R-32-E,	, K, M, OF Survey Descrip	pilon)	/	Maljamar Grayburg San And
1275 FSL, 2525 FEL				
· · · · · · · · · · · · · · · · · · ·	APPROPRIATE BO	X(ES) TO INDICATE N	ATURE OF NOTICE	Lea Co. NM · EPORT, OR OTHER DATA
TYPE OF SUBMISSION			TYPE OF ACTION	LEI OKT, OK OTHER DATA
	Acidize	Deepen	Production (Start/Res	
Notice of Intent	Alter Casing	Fracture Treat	Reclamantion	ume) 🛄 Water Shut-Off
Subsequent Report		New Construction	Recomplete	Other
A	Change Plans	Plug and Abandon	Temporarily Abandor	
Final Abandonment Notice	Convert to Injecti		Water Disposal	
determined that the site is ready f 9/15/08 MIRU pulling un 9/16/08 RIH w/ 122 jts. 2 9/17/08 MI cementing equ cement plug @ 2210-1963	the work will be perforn volved operations If the imal Abandonment Notice for final inspection.) it. ND wellhead, N 3/8. Tagged CIBP uip. Circulate hold 3. POH w/ 60 jts. V	very shall be filed only after all very as a shall be filed only after all very as a shall be filed. Layed dow e w/ mud laiden fluid. WOC overnight.	e completion or recompletion 1 requirements, including rec rkstring. Tallied tbg. on one jt. CWISD. Spot 25 sx cement @	In a new interval, a Form 3160-4 shall be filed lamantion, have been completed, and the operator PU 8 jts. CWISD. () 3728-3481. POH to 2210'. Spot 25
Attach the Bond under which following completion of the in- testing has been completed Fi determined that the site is ready f 9/15/08 MIRU pulling un 9/16/08 RIH w/ 122 jts. 2 9/17/08 MI cementing equ cement plug @ 2210-1963 9/18/08 Tagged plug @ 20 800'. Spot 45 sx. WOC ov 9/19/08 Tagged plug @ 35	the work will be perforr volved operations If the inal Abandonment Notice for final inspection.) it. ND wellhead, N 3/8. Tagged CIBF uip. Circulate hold 3. POH w/ 60 jts. V 047'. POH to 1167 /ernight. 50'. POH to 60'. C	operation results in a multiple es shall be filed only after al NU BOP. Move in wor @ 3800'. Layed dow e w/ mud laiden fluid. WOC overnight. 7'. Spot 25 sx cement p Circulate 10 sx cement	e completion or recompletion 1 requirements, including rec rkstring. Tallied tbg. (n one jt. CWISD. 2 Spot 25 sx cement @ plug @ 1167-920. WO	in a new interval, a Form 3160-4 shall be filed lamantion, have been completed, and the operator PU 8 jts. CWISD.
Attach the Bond under which following completion of the in- testing has been completed Fi determined that the site is ready fi 9/15/08 MIRU pulling un 9/16/08 RIH w/ 122 jts. 2 9/17/08 MI cementing equ cement plug @ 2210-1963 9/18/08 Tagged plug @ 20 800'. Spot 45 sx. WOC ov	the work will be perforr volved operations If the inal Abandonment Notice for final inspection.) it. ND wellhead, N 3/8. Tagged CIBF uip. Circulate hold 3. POH w/ 60 jts. V 047'. POH to 1167 /ernight. 50'. POH to 60'. C	operation results in a multiple es shall be filed only after al NU BOP. Move in wor @ 3800'. Layed dow e w/ mud laiden fluid. WOC overnight. 7'. Spot 25 sx cement p Circulate 10 sx cement	e completion or recompletion 1 requirements, including rec rkstring. Tallied tbg. rn one jt. CWISD. Spot 25 sx cement (a plug @ 1167-920. W(t to surface. ND BOP	in a new interval, a Form 3160-4 shall be filed lamantion, have been completed, and the operator PU 8 jts. CWISD. () 3728-3481. POH to 2210'. Spot 25 DC 4 hrs. Tagged plug @ 933'. POH
Attach the Bond under which following completion of the in- testing has been completed Fi determined that the site is ready f 9/15/08 MIRU pulling un 9/16/08 RIH w/ 122 jts. 2 9/17/08 MI cementing equ cement plug @ 2210-1963 9/18/08 Tagged plug @ 20 800'. Spot 45 sx. WOC ov 9/19/08 Tagged plug @ 35 Hole Marker. Clean loc. 1 14 Thereby certify that the foregoing Name (Printed Typed)	the work will be perform volved operations If the inal Abandonment Notice for final inspection.) it. ND wellhead, N 3/8. Tagged CIBP uip. Circulate hold 3. POH w/ 60 jts. V 047'. POH to 1167 /ernight. 50'. POH to 60'. C Rig down. Move o	operation results in a multiple es shall be filed only after al NU BOP. Move in wor P @ 3800'. Layed dow e w/ mud laiden fluid. WOC overnight. 7'. Spot 25 sx cement p Circulate 10 sx cement off.	le <u>Fareman</u>	In a new interval, a Form 3160-4 shall be filed lamantion, have been completed, and the operator PU 8 jts. CWISD. (a) 3728-3481. POH to 2210'. Spot 25 DC 4 hrs. Tagged plug @ 933'. POH . Cut off well head and weld on Dry ACCEPTED FOR RECOR
Attach the Bond under which following completion of the in- testing has been completed Fi determined that the site is ready f 9/15/08 MIRU pulling un 9/16/08 RIH w/ 122 jts. 2 9/17/08 MI cementing equ cement plug @ 2210-1963 9/18/08 Tagged plug @ 20 800'. Spot 45 sx. WOC ov 9/19/08 Tagged plug @ 35 Hole Marker. Clean loc. 1 14 Thereby certify that the foregoing Name (Printed Typed)	the work will be perform volved operations If the inal Abandonment Notice for final inspection.) it. ND wellhead, N 3/8. Tagged CIBP uip. Circulate hold 3. POH w/ 60 jts. V 047'. POH to 1167 /ernight. 50'. POH to 60'. C Rig down. Move o	operation results in a multiple ss shall be filed only after all NU BOP. Move in wor P @ 3800'. Layed dow e w/ mud laiden fluid. WOC overnight. I'. Spot 25 sx cement p Circulate 10 sx cement off.	te $jo - l - o$ 8	In a new interval, a Form 3160-4 shall be filed lamantion, have been completed, and the operator PU 8 jts. CWISD. (a) 3728-3481. POH to 2210'. Spot 25 DC 4 hrs. Tagged plug @ 933'. POH . Cut off well head and weld on Dry ACCEPTED FOR RECOF OCT 1 1 2008 BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE
Attach the Bond under which following completion of the im- testing has been completed Fi determined that the site is ready f 9/15/08 MIRU pulling un 9/16/08 RIH w/ 122 jts. 2 9/17/08 MI cementing equ cement plug @ 2210-1963 9/18/08 Tagged plug @ 20 800'. Spot 45 sx. WOC ov 9/19/08 Tagged plug @ 35 Hole Marker. Clean loc. 1	the work will be perform volved operations If the inal Abandonment Notice for final inspection.) it. ND wellhead, N 3/8. Tagged CIBP uip. Circulate hold 3. POH w/ 60 jts. V 047'. POH to 1167 /ernight. 50'. POH to 60'. C Rig down. Move o	operation results in a multiple es shall be filed only after al NU BOP. Move in wor P @ 3800'. Layed dow e w/ mud laiden fluid. WOC overnight. 7'. Spot 25 sx cement p Circulate 10 sx cement off.	te $jo - l - o$ 8	In a new interval, a Form 3160-4 shall be filed lamantion, have been completed, and the operator PU 8 jts. CWISD. (a) 3728-3481. POH to 2210'. Spot 25 DC 4 hrs. Tagged plug @ 933'. POH . Cut off well head and weld on Dry ACCEPTED FOR RECOF OCT 1 1 2008 BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE
Attach the Bond under which following completion of the in- testing has been completed Fi determined that the site is ready f 9/15/08 MIRU pulling un 9/16/08 RIH w/ 122 jts. 2 9/17/08 MI cementing equ cement plug @ 2210-1963 9/18/08 Tagged plug @ 20 800'. Spot 45 sx. WOC ov 9/19/08 Tagged plug @ 35 Hole Marker. Clean loc. 1	the work will be perform volved operations If the inal Abandonment Notice for final inspection.) it. ND wellhead, N 3/8. Tagged CIBF uip. Circulate hold 3. POH w/ 60 jts. V 047'. POH to 1167 /ernight. 50'. POH to 60'. C Rig down. Move o Curculate hold 50'. POH to 60'. C Rig down. Move o THIS SPA	operation results in a multiple ss shall be filed only after all NU BOP. Move in wor @ 3800'. Layed dow e w/ mud laiden fluid. WOC overnight. ". Spot 25 sx cement p Circulate 10 sx cement off. CE FOR FEDERAL ce does not warrant or certify the	te $jo - l - o g$	In a new interval, a Form 3160-4 shall be filed lamantion, have been completed, and the operator PU 8 jts. CWISD. (a) 3728-3481. POH to 2210'. Spot 25 DC 4 hrs. Tagged plug @ 933'. POH . Cut off well head and weld on Dry ACCEPTED FOR RECOF OCT 1 1 2008 BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

•