State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

OIL CONSERVATION DIVISION	
DISTRICT 1 NOV 1 7 2008 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO 30-025-07594
DISTRICT IN LAND ARESTA, NM 882 FO	5 Indicate Type of Lease STATE FEE FEE
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)	South Hobbs (G/SA) Unit Section 3
1. Type of Well Onl Well Gas Well Other Temporarily Abandoned	8. Well No. 58
2. Name of Operator	9 OGRID No. 157984
Occidental Permian Ltd. 3 Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
4008 N. Grimes PMB-269, Hobbs, NM 88240 4. Well Location	
	From The West Line
Section 3 Township 19-S Range 38-E	NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3607' RDB	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Mat	erial
12 Check Appropriate Box to Indicate Nature of Notice, Report, or C NOTICE OF INTENTION TO: SUBS	ther Data EQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPN	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	
OTHER Return well to injection X OTHER	
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well, MIRU PU. NU BOP RIH w/ 4-3/4", drill out cmt and CIBP @ 3880", continue to CO to PBTD @ 4218" Obtain a static bottomhole pressure reading RIH w/ 5-1/2" packer & RPB on workstring, set RBP @ 4130", packer @ 3880" Pressure test Grayburg & Zone 1 perfs, if tst holds circulate clean & POOH RIH w/ 5-1/2" treating packer on 2-7/8" workstring, set @ 4130", acid treat: 20Bbls 15% NEFE HO 500# block, 20 Bbls acid, flush w/ 50 bbls fresh water POOH w/ work string & treating packer RIH w/ duoline injection equipment RDPU Return well to injection 	ompletion or recompletion. CI acid, 500# gelled rock salt block, 20 Bbls acid,
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify the constructed or	
closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	OCD-approved
SIGNATURE HOURS Administrative A	Associate DATE //-/2-08
TYPE OR PRINT NAME Rebecca L. Larmon E-mail address: rebecca larmon@oxy.com For State Use Only	TELEPHONE NO 575-397-8247
// // POLICE SUPERVISOR/O	11 11 4 G U ZUL
() // W SASTRET SUPERVISORO	DATE NOV 2 0 200