Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources District I	May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 87240 District II 1301 W. Grand Ave., Artesia, NM 88210	30-025-29333
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rdf. Azffec INM 87410 Santa Fe, NM 87505 District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505	STATE FEE X
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Central Corbin Queen Unit
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 602
2. Name of Operator  OXY USA Inc.	9. OGRID Number 16696
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710-0250 4. Well Location	Corbin Queen, Central
Unit Letter L: 1650 feet from the south line and	330 feet from the west line
Section 3 Township 18S Range 33E	
11. Elevation (Show whether DR, RKB, RT, GR, et	
Pit or Below-grade Tank Application or Closure	
Pit type <u>Steel</u> Depth to Groundwater <u>100</u> Distance from nearest fresh water well Dis	stance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction	on Material
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK	SEQUENT REPORT OF:
TEMPORARILY ABANDON	
TEMPORARILY ABANDON	ING OPNS.  PLUG AND ABANDONMENT
PULL OR ALTER CASING	ING OPNS.  PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER: OTHER:  OTHER:  OTHER:  OTHER:  Add give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach	PLUG AND ABANDONMENT  e pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.  TD-5200' PBTD-4350' PERFS-4224-4234' 4898-5128  8-5/8" 24# csg @ 1554' w/ 710sx, 12-1/4" hole, on CIBP@ 4350'1. RIH & Set CIBP@ 4175' M&P 25sx cmt to 4025'  2. Perf @ 3200', sqz 70sx cmt to 3000' WOC-Tag  3. Perf @ 1604' sqz 60sx cmt to 1454' WOC-Tag	PLUG AND ABANDONMENT  e pertinent dates, including estimated date wellbore diagram of proposed completion  8' CIBP-4350'-8/85
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.  TD-5200' PBTD-4350' PERFS-4224-4234' 4898-5128 8-5/8" 24# csg @ 1554' w/ 710sx, 12-1/4" hold sold starting any proposed work).  ON CIBP@ #350'1. RIH & Set CIBP @ 4175' M&P 25sx cmt to 4025' 2. Perf @ 3200', sqz 70sx cmt to 3000' WOC-Tag  ALF 10# MLF between plugs  BE  BE	PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  Proposed completion  8' CIBP-4350'-8/85  1e, T0C-Surface-Circ  T0C-3179'-Calc  PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  PROPOSED COMPLETE COM
PULL OR ALTER CASING	PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  PROPERTY ABANDONMENT  PLUG AND ABANDONMENT  PROPERTY ABANDONMENT  PLUG AND ABANDONMENT  PROPERTY ABANDONMENT
DTHER:  OTHER:  Is Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.  TD-5200' PBTD-4350' PERFS-4224-4234' 4898-5128	PLUG AND ABANDONMENT  e pertinent dates, including estimated date wellbore diagram of proposed completion  8' CIBP-4350'-8/85  1e, TOC-Surface-Circ  TOC-3179'-Calc  BE OIL CONSERVATION DIVISION MUST  NOTIFIED 24 HOURS PRIOR TO THE GINNING OF PLUGGING OPERATIONS  and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  tory Analyst  DATE  LUGGOS
PULL OR ALTER CASING	PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  Provided Proposed Completion  B' CIBP-4350'-8/85  Ple, TOC-Surface-Circ Ple OIL CONSERVATION DIVISION MUST  NOTIFIED 24 HOURS PRIOR TO THE  EGINNING OF PLUGGING OPERATIONS  Pland belief. I further certify that any pit or below-  or an (attached) alternative OCD-approved plan  tory Analyst  DATE  LUCE  david_stewart@oxy.com  Telephone No. 432-685-5717
PULL OR ALTER CASING	PLUG AND ABANDONMENT  e pertinent dates, including estimated date wellbore diagram of proposed completion  8' CIBP-4350'-8/85  1e, TOC-Surface-Circ  TOC-3179'-Calc  BE OIL CONSERVATION DIVISION MUST  NOTIFIED 24 HOURS PRIOR TO THE GINNING OF PLUGGING OPERATIONS  and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  tory Analyst  DATE  U(18/08)

**OXY USA Inc.** Central Corbin Queen Unit #602 API No. 30-025-29333


60sx @ 150'-Surface

60sx @ 1604-1454' WOC-Tag

70sx @ 3200-3000' WOC-Tag

CIBP @ 4175' w/ 25sx

8/85-CIBP @ 4350'



12-1/4" hole @ 1554' 8-5/8" csg @ 1554' w/710sx-TOC-Surf-Circ

Perfs @ 4224-4234'

7-7/8" hole @ 5200' 5-1/2" csg @ 5200' w/ 350sx-TOC-3179'-Calc

Perfs @ 4898-5128'

OXY USA Inc. Central Corbin Queen Unit #602 API No. 30-025-29333

8/85-CIBP @ 4350'

